# Waste Tank Summary Report for Month Ending November 30, 1998



Prepared for the U.S. Department of Energy Office of Environmental Restoration and Waste Management



Hanford Management and Integration Contractor for the U.S. Department of Energy under Contract DE-AC06-96RL13200

#### **LEGAL DISCLAIMER**

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, nor any of their contractors, subcontractors or their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or any third party's use or the results of such use of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof or its contractors or subcontractors. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

This report has been reproduced from the best available copy.

Printed in the United States of America

DISCLM-2.CHP (1-91)

### Waste Tank Summary Report for Month Ending November 30, 1998

B. M. Hanlon Lockheed Martin Hanford Corp.

Date Published

January 1999

Prepared for the U.S. Department of Energy Office of Environmental Restoration and Waste Management

P.O. Box 1000
Richland, Washington

Hanford Management and Integration Contractor for the U.S. Department of Energy under Contract DE-AC06-96RL13200

Approved for Public Release; Further Dissemination Unlimited

#### RELEASE AUTHORIZATION

**Document Number:** 

HNF-EP-0182-128

**Document Title:** 

WASTE TANK SUMMARY REPORT FOR MONTH ENDING

**NOVEMBER 30, 1998** 

This document, reviewed in accordance with DOE Order 241.1, "Scientific and Technical Information Management," and 241.1-1, "Guide to the Management of Scientific and Technical Information," does not contain classified or sensitive unclassified information and is:

#### APPROVED FOR PUBLIC RELEASE

Mark A. Williams

Lockheed Martin Services, Inc.
Document Control/Information Clearance

Reviewed for Applied Technology, Business Sensitive, Classified, Copyrighted, Export Controlled, Patent, Personal/Private, Proprietary, Protected CRADA, Trademark, Unclassified Controlled Nuclear Information.

LEGAL DISCLAIMER. This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, not any of their employees, nor any of their contractors, subcontractors or their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or any third party's use or the results of such use of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof or its contractors or subcontractors. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof. This report has been reproduced from the best available copy. Printed in the United States of America.

**APPROVALS** 

Prepared by:

Responsible Manager:

C. DeFigh-Price, Manager Date

**Process Engineering** 

This page intentionally left blank.

#### WASTE TANK SUMMARY REPORT

#### B. M. Hanlon

#### **ABSTRACT**

This report is the official inventory for radioactive waste stored in underground tanks in the 200 Areas at the Hanford Site. Data that depict the status of stored radioactive waste and tank vessel integrity are contained within the report. This report provides data on each of the existing 177 large underground waste storage tanks and 63 smaller miscellaneous underground storage tanks and special surveillance facilities, and supplemental information regarding tank surveillance anomalies and ongoing investigations. This report is intended to meet the requirement of U. S. Department of Energy-Richland Operations Office Order 5820.2A, Chapter I, Section 3.e. (3) (DOE\_RL, 1990, Radioactive Waste Management, U. S. Department of Energy-Richland Operations Office, Richland, Washington) requiring the reporting of waste inventories and space utilization for Hanford Tank Farm tanks.

This page intentionally left blank.

### **CONTENTS**

	Page
	MMARY
I.	WASTE TANK STATUS
II.	WASTE TANK INVESTIGATIONS
Ш	SURVEILLANCE AND WASTE TANK STATUS HIGHLIGHTS
Δn	pendixes:
Αр	pendixes.
A.	WASTE TANK SURVEILLANCE MONITORING TABLES
	Tables:
	1 Watch List Tanks A-2
	2 Additions/Deletions to Watch List Tanks by Year A-3
	3 Temperature Monitoring in Watch List Tanks
	4 Temperature Monitoring in Non-Watch List Tanks
	5 Single-Shell Tanks Monitoring Compliance Status
	6 Double-Shell Tanks Monitoring Compliance Status
	8 Tank Monitor and Control System (TMACS) Monitoring Status
	5 Table Frontier and Condot System (Travecs) Frontiering Status
В.	DOUBLE-SHELL TANK WASTE TYPE AND SPACE ALLOCATION B-1
	Tables:
	1 Double-Shell Tank Waste Type and Space Allocation B-2
	2 Double-Shell Tank Waste Inventory
	Figures:
	1 Total Double-Shell Tank Total Inventory B-5
C.	TANK AND EQUIPMENT CODE AND STATUS DEFINITIONS C-1
	1 Tank and Equipment Code/Status Definitions
D.	TANK FARM CONFIGURATION, STATUS AND FACILITY CHARTS D-1
	Figures:
	1 High-Level Waste Tank Configuration
	2 Double-Shell Tank Instrumentation Configuration D-3
	3 Single-Shell Tank Instrumentation Configuration D-4
F	MONTHLY SUMMARY E-1
<b>-</b>	1 Monthly Summary
	2 Tank Use Summary
	3 Pumping Record, and Liquid Status and Pumpable Liquid Remaining
	In Tanks
	4 Inventory Summary by Tank Farm E-5
	5 Inventory and Status by Tank - Double-Shell Tanks F-6
	6 Inventory and Status by Tank - Single-Shell Tanks E-8
FI	PERFORMANCE SUMMARY F-1
1.1	Table:
	1 Performance Summary F-2
	2 Summary of Waste Transactions in the Double-Shell Tanks F-4
	3 Comparison of Projected Versus Actual Waste Volumes for
	Hanford Facilities

G.	MISCELLANEOUS UNDERGROUND STORAGE TANKS AND SPECIAL SURVEILLANCE
	FACILITIES G-1
	Tables:
	1 Misc. Underground Storage Tanks and Special Surveillance Facilities (Active). G-2
	2 East Area Inactive Underground Storage Tanks and Special Surveillance
	Facilities (Inactive)
	3 West Area Inactive Underground Storage Tanks and Special Surveillance
	Facilities (Inactive)
H.	LEAK VOLUME ESTIMATES H-1
	Table:
	1 Single-Shell Tank Leak Volume Estimates
I.	SINGLE-SHELL TANKS INTERIM STABILIZATION, AND CONTROLLED, CLEAN
	AND STABLE STATUS I-1
	Tables:
	1 Single-Shell Tanks Interim Stabilization Status I-2
	2 Tri-Party Agreement Single-Shell Tank Interim Stabilization
	Schedule I-5
J	CHARACTERIZATION PROGRESS STATUS
•	Figure:
	1 Characterization Progress Status
	•

	ETRIC CONV	ERSION CHART						
1 inch = 2.54 centimeters								
1 foot = 30.48 centimeters								
1 gallon = 3.80 liters								
1 ton	=	0.90 metric tons						
	$^{\circ}\mathbf{F} = \left(\frac{9}{5}\right)$	°C)+32						
1 Btu/h = 2.930711 E-01 watts (International Table)								

### WASTE TANK SUMMARY REPORT FOR MONTH ENDING NOVEMBER 30, 1998

Note: Changes from the previous month are in bold print.

#### I. WASTE TANK STATUS

Category	Quantity	Date of Last Change
Double-Shell Tanks <sup>c</sup>	28 double-shell	10/86
Single-Shell Tanks	149 single-shell	07/88
Assumed Leaker Tanks	67 single-shell	7/93
Sound Tanks	28 double-shell 82 single-shell	19 <b>8</b> 6 7/93
Interim Stabilized Tanks <sup>b,d</sup>	119 single-shell	11/97
Not Interim Stabilized f	30 single-shell	11/97
Intrusion Prevention Completed	108 single-shell	09/96
Controlled, Clean, and Stable	36 single-shell	09/96
Watch List Tanks 8  Total	32 single-shell 6 double-shell 38 tanks	9/96 <sup>h</sup> 6/93

<sup>&</sup>lt;sup>4</sup> All 149 single-shell tanks were removed from service (i.e., no longer authorized to receive waste) as of November 21, 1980.

<sup>&</sup>lt;sup>b</sup> Of the 119 tanks classified as Interim Stabilized, 64 are listed as Assumed Leakers. The total of 119 Interim Stabilized tanks includes one tank that does not meet current established supernatant and interstitial liquid stabilization criteria. (See Table I-1 footnotes, item #2)

<sup>&</sup>lt;sup>c</sup> Six double-shell tanks are currently included on the Hydrogen Watch List and are thus prohibited from receiving waste in accordance with "Safety Measures for Waste Tanks at Hanford Nuclear Reservation," Section 3137 of the National Defense Authorization Act for Fiscal Year 1991, November 5, 1990, Public Law 101-510.

<sup>&</sup>lt;sup>d</sup> Of the 32 single-shell tanks on Watch Lists, 11 have been Interim Stabilized.

<sup>&</sup>lt;sup>6</sup> Of the 32 single-shell tanks on Watch Lists, 11 have completed Intrusion Prevention (this category replaced Interim Isolation). (See Appendix C for "Intrusion Prevention" definition).

Three of these tanks are Assumed Leakers (BY-105, BY-106, SX-104). (See Table H-1)

<sup>&</sup>lt;sup>8</sup> See Section A tables for more information on Watch List Tanks. Eight tanks (A-101, S-102, S-111, SX-103, SX-106, U-103, U-105, and U-107) are currently on more than one Watch List.

<sup>&</sup>lt;sup>h</sup> Dates for the Watch List tanks are "officially added to or removed from the Watch List" dates. (See Table A-1, Watch List Tanks, for further information.)

The TY tank farm was officially declared Controlled, Clean, and Stable in March 1996. The TX tank farm and BX tank farms were declared CCS in September 1996. (BX-103 has been declared to have met current interim stabilization criteria, and is included in CCS - see also Appendix I).

#### II. WASTE TANK INVESTIGATIONS

This section includes all single-shell tanks or catch tanks which are showing surface level or interstitial liquid level (ILL) decreases, or drywell radiation level increases in excess of established criteria.

There are currently no tanks under investigation for ILL decreases or drywell radiation level increases which exceed the criteria. Drywell monitoring is done on an "as needed basis" with the exception of tanks C-105 and C-106 which are monitored monthly.

#### A. Assumed Leakers or Assumed Re-leakers: (See Appendix C for definition of "Re-leaker")

This section includes all single- or double-shell tanks or catch tanks for which an off-normal or unusual occurrence report has been issued, or for which a waste tank investigation is in progress, for assumed leaks or re-leaks. Tanks/catch tanks will remain on this list until either a) completion of Interim Stabilization, b) the updated occurrence report indicates that the tank/catch tank is not an assumed leaker, or c) the investigation is completed.

There are currently no tanks for which an off-normal or unusual occurrence report has been issued for assumed leaks or re-leaks.

#### B. Tanks with increases indicating possible intrusions:

This section includes all single-shell tanks and related receiver tanks for which the surveillance data show that the surface level or ILL has met or exceeded the increase criteria, or are still being investigated.

<u>Candidate Intrusion List:</u> Increase criteria in the following tanks indicate possible intrusions; however, no funds were allocated for performing intrusion investigations in FY 1999 due to higher priority work in the area of safe storage.

Tank 241-U-111 has been added to the list. This tank has been experiencing a gradual level increase (about 5 inches) since 1985. The increase appears to be seasonal. There may be an intrusion due to snowmelt as has been observed in other single-shell tanks. Since the intrusion is so small, this tank will be rebaselined, and placed on a list of tanks requiring intrusion investigation.

Tank 241-B-202 Tank 241-BX-101 Tank 241-BX-103 Tank 241-BY-103 Tank 241-C-101 Tank 241-U-111

244-AR Tanks and Sumps: Currently, all ventilation systems at 244-AR are shut down. Based on the weight factor gauges for the sumps and tanks, Tank 001 contains 1,300 gallons, Tank 002 contains 12,250 gallons, Tank 003 contains 2,000 gallons, and Tank 004 contains 250 gallons. Sump 001 contains 15.5 gallons, Sump 002 contains 0-2 gallons, and Sump 003 contains 3,300 gallons. There was no change in tank/sump contents as of September 30, 1998. Status of jet pumping: first attempts at jetting were unsuccessful. The next attempt to jet pump may be in FY99, depending on funding.

Catch Tank 241-AX-152: The liquid level in this catch tank was steady around 66.75 inches from the startup of Project W-030, Tank Farm Ventilation System," in March 1998 until late August 1998. The level then began to decrease. The October reading of 65 inches is 1.75 inches below the summer average. This is an active catch tank, routinely pumped, and deviations from baseline are not applicable per OSD-31. The decrease represents a significant change in trend and it is apparent that tank conditions changed around the end of August 1998.

Resolution Status: Discrepancy Report #98-853 was issued on November 4, 1998. One possible cause under investigation is a change in flow path, causing an increase in evaporation. The tank was pumped down to 2.25

inches on November 13. Since that time the level has decreased to 1.00 inch. The Discrepancy Report will remain open and the tank will remain on the alert list until an engineering investigation is complete.

Catch Tank 241-TX-302-C: The ENRAF readings have been gradually decreasing since pumping on April 27, 1998. After the catch tank was pumped, a new baseline of 7.0 inches was established. There has been a gradual decrease from 7.0 to 5.84 inches since that time.

Resolution Status: This tank was rebaselined again with a sloping baseline of 6.14 inches to account for the evaporation.

#### III. SURVEILLANCE AND WASTE TANK STATUS HIGHLIGHTS

Single-Shell Tanks Saltwell Jet Pumping (See Table E-6 footnotes for further information)

Tank 241-C-106 – Waste removal operations were initiated on November 18, 1998. Commencement of sluicing (sludge removal) begins the process of waste removal in the highest heat-generating single-shell storage tank. Wastes from C-106 are being pumped underground through a new specially constructed pipeline to AY-102. The ventilation system for AY-102 is designed for the anticipated heat load of the waste from C-106.

Tank 241-S-109 - The saltwell screen installation is in progress.

Tank 241-SX-104 - Pumping resumed October 7, 1998, and was shut down for several periods during October and November for transfer of waste from the DCRT to SY-102, and to perform an integrity assessment of the DCRT. 14.1 Kgallons were pumped in November; 26,326 gallons of dilution water and 2,435 gallons of water for transfer line flushes were used during November pumping operations. A total of 158.5 Kgallons has been pumped from this tank.

Tank 241-SX-106 – Pumping started on October 7, 1998, and was shut down for several periods during October and November for transfer of waste from the DCRT to SY-102, and to perform an integrity assessment of the DCRT. 1.9 Kgallons were pumped in November; 1,372 gallons of dilution water and 976 gallons of water for transfer line flushes were used during November pumping operations. A total of 11.7 Kgallons has been pumped from this tank.

Tank 241-T-104 - Pumping resumed on June 7, 1998; 3.2 Kgallons were pumped in November. Actual volume of liquid remaining to be pumped is still a rough estimate. Volumes will be adjusted as porosity data becomes available with continued pumping; 362 gallons of raw water were used during November for pumping operations. A total of 142.6 Kgallons has been pumped from this tank.

Tank 241-T-110 - Pumping resumed in July after the pump was replaced; 3.6 Kgallons were pumped in November. Actual volume of liquid remaining to be pumped is still a rough estimate. Volumes will be adjusted as porosity data becomes available with continued pumping; 932 gallons of raw water were used during November for pumping operations. A total of 37.1 Kgallons has been pumped from this tank.

#### Single-Shell Tank TPA Interim Stabilization Milestones

All M-41-xx Milestones are being renegotiated. See also Table I-2, Tri-Party Agreement Single-Shell Tank Interim Stabilization Schedule.

#### 3 Tank Waste Remediation System Safety Initiatives

The U. S. Secretary of Energy has directed that six safety initiatives be implemented in the Tank Waste Remediation System Program to accelerate the mitigation/resolution of the high priority waste tank safety issues at the Hanford Site. Forty-two milestones were established for accomplishing the initiatives.

#### No Safety Initiatives were scheduled to be completed in November.

The following Safety Initiatives remain to be completed:

SI 4a - Upgrade Alarm Panels in Seven Tank Farms

SI 4c - Complete Accelerated Walk-Downs and Field Verify Essential Drawings

SI 6d - Initiative C-106 Accelerated Retrieval

Completion dates for Safety Initiatives 4c and 6d have been missed.

SI 4a - An assessment of the Completion Record is being evaluated for this Safety Initiative.

#### 4. Double-Shell Tank 241-SY-101 Waste Level Increase

Although the waste level in tank SY-101 has risen slowing and steadily since last February, the surface level and hydrogen venting are within safety and operating limits. A mixer pump was installed in the tank in July 1993, which circulates liquid wastes from the tank's upper layer down to the bottom where jet nozzles discharge the fluid about two feet from the bottom. This prevents gas bubbles from building up at the bottom, and results in venting of small steady gas releases, rather than in large infrequent gas releases. Investigations continue on why the surface level is rising.

Several void fraction instrument (VFI) readings have been completed which gives the void fraction at depth in the riser through which it is deployed. The VFI readings indicate that the level increase is due to gas trapped in the crust, which comprises the upper approximately 60 inches of waste. Additionally, core sampling of both retained gas sampling (RGS), and regular cores, is presently in progress.

Resolution Status: On February 11, 1998, the PRC recommended that the DOE-RL declare an Unreviewed Safety Question (USQ) over the continued level growth observed in this tank. The PRC implemented a standing order (SO) that placed operational restrictions on mixer pump operations. The SO released Operations from required actions at waste levels of 402 inches as measured by the Riser IC ENRAF. Riser 1A was rebaselined from 403.65 to 417.5 inches in August, USQ approval #TF-98-0852. Riser 1C has readings of 405.24 inches. DOE has modified the 406-inch and 422-inch mixer pump operational controls to allow additional mixer pump and characterization operations. Tank Farms has implemented TWO Standing Order 99-01 to reflect the relaxation of mixer pump operating controls at 406 and 422 inches. The contractor has established a multi-disciplinary team to solve the level growth issues in SY-101.

#### 5. Characterization Progress Status (See Appendix J)

Characterization is the understanding of the Hanford tank waste chemical, physical, and radiological properties to the extent necessary to ensure safe storage and interim operation, and ultimate disposition of the waste.

#### **Characterization Progress for November:**

Characterization sampling efforts were directed towards obtaining solid samples from 241-SY-101 this month. Weather, holidays, and equipment needs delayed this activity throughout the month. Vapor grab samples were obtained from the SHMS cabinets, and a grab sample was taken from S-106 to support characterization.

#### 6. Standard Hydrogen Monitoring System (SHMS)

Gas monitoring systems have been installed on 41 of the underground waste storage tanks including the 25 tanks on the Hydrogen Watch List. The monitors provide essential data to aid in safely managing wastes in the tanks by sampling gases in the air space above the tanks contents, and analyzing the amount of hydrogen. Some newer monitors also analyze the amount of nitrous oxide, ammonia, methane and other flammable gases.

7. PMHC-TANKFARM-1998-0131, Off-Normal Occurrence Report, "Tank SX-104 Dome Deflection Not Performed as Required by Operating Specification Document," Initial Update October 22, 1998.

On October 20, 1998, it was discovered that the tank dome deflection for SX-104 had not been performed as required by Operating Specification Document (OSD), OSD-T-151-00013. The requirement for performing the dome deflection is that a dome deflection survey be performed every  $20,000 \pm 5,000$  gallons net jet pump production. Approximately 28,000 gallons had been jet pumped out of SX-104 when this was discovered.

Dome deflection of >0.02 feet may indicate excessive dome loading or possible structural failure. This phenomenon is expected primarily after the pumping, since salt cake encrustations on in-tank equipment could load the domes severely when not buoyed by the interstitial liquid removed during jet pumping. Deflection is defined as a decrease in elevation measurements from the original survey elevation.

On October 21, a critique of this event was held. As a result of this critique, it was decided that this be reported as an Off-Normal Occurrence.

Saltwell pumping of SX-104 has been suspended until the dome settlement survey is completed. (Pumping resumed in November - see also Highlights, page 3, for more current information since this Occurrence Report was issued).

Methods are currently being developed by Interim Stabilization management to ensure this situation does not occur again.

8. PHMC-TANKFARM-1998-0124, Off-Normal Report, "Liquid Observation Well (LOW) Readings in SST 241-B-111 Indicate a Potential Drop in Interstitial Liquid Level," Initial Update October 22, 1998.

Liquid Observation Well (LOW) readings taken on September 29, 1998, of the interstitial Liquid level in SST B-111 were in excess of -3 standard deviations from the baseline established for this tank. Two additional LOW readings were performed on September 30, 1998, to validate the weekly data. The readings taken on September 30 also exceeded the -3 standard deviation criteria required for this tank per OSD-T-151-00031.

Tank B-111 was declared an "Assumed Leaker" in 1978. Interim Stabilization of the tank was completed in 1985.

On October 1, 1998, daily LOW and surface level gauge readings were initiated on the anomalous data.

On October 1, 1998, an operational and engineering review of the anomalous data was initiated.

On October 7, 1998, operations and engineering completed a review of the LOW monitoring equipment, barometric pressure change information and recent tank B-111 activities. This review determined that these factors did not appear to contribute to the anomalous data.

On October 7, 1998, a formal engineering evaluation team was initiated to investigate a potential drop in the ILL for this tank.

On October 20, 1998, the Plant Review Committee (PRC) reviewed the information presented and the consensus recommendations include: 1) Place the tank on the alert list and continue normal monitoring with increased emphasis on surveillance; 2) Re-evaluate if growth 2-sigma deviations from the data of the last 21 days is experienced; 3) Re-evaluate if the level trend is downward 2-sigma deviations.

Pumping activities were evaluated and determined not appropriate at this time.

Tank B-111 appears to be returning to the pre-event trend. Any significant deviations or anomalies noted during surveillance activities of this tank will be submitted in future reports.

This page intentionally left blank.

### APPENDIX A

### WASTE TANK SURVEILLANCE MONITORING TABLES

#### TABLE A-1. WATCH LIST TANKS

November 30, 1998

These tanks have been identified as Watch List Tanks in accordance with Public Law 101-510, Section 3137, "Safety Measures for Waste Tanks at Hanford Nuclear Reservation," (1990). These tanks have been identified because they "... may have a serious potential for release of high-level waste due to uncontrolled increases in temperature or pressure."

		Officially			Officially
Single-Shell Tank	<u>s</u>	Added to	Double-Shell Tanks		Added to
Tank No.	Watch List	Watch List	Tank No.	Watch List	Watch List
A-101 (*)	Hydrogen	1/91	AN-103	Hydrogen	1/91
	Organics	5/94	AN-104	Hydrogen	1/91
AX-101	Hydrogen	1/91	AN-105	Hydrogen	1/91
AX-102	Organics	5/94	AW-101	Hydrogen	6/93
AX-103	Hydrogen	1/91	SY-101	Hydrogen	1/91
B-103	Organics	1/91	SY-103	Hydrogen	1/91
C-102	Organics	5/94	e ranka		
C-103	Organics	1/91	The state of the s		
C-106	High Heat Load	1/91	TANKS BY WATCH	LIST	
S-102 (*)	Hydrogen,	1/91		<del></del>	
	Organics	1/91	<u>Hydrogen</u>	Organics	
S-111 (*)	Hydrogen	1/91	A-101	A-101	
	Organics	5/94	AX-101	AX-102	
S-112	Hydrogen	1/91	AX-103	B-103	
SX-101	Hydrogen	1/91	S-102	C-102	
SX-102	Hydrogen	1/91	S-111	C-103	
SX-103 (*)	Hydrogen	1/91	S-112	S-102	
	Organics	5/94	SX-101	S-111	
SX-104	Hydrogen	1/91	SX-102	SX-103	
SX-105	Hydrogen	1/91	SX-103	SX-106	
SX-106 (*)	Hydrogen,	1/91	SX-104	T-111	
	Organics	1/91	SX-105	TX-105	
SX-109	Hydrogen because		SX-106	TX-118	
	other tanks vent		SX-109	TY-104	
	thru it	1/91	T-110	U-103	
T-110	Hydrogen	1/91	U-103	U-105	
T-111	Organics	2/94	U-105	U-106	
TX-105	Organics	1/91	U-107	U-107	
TX-118	Organics	1/91	U-108	U-111	
TY-104	Organics	5/94	U-109	U-203	
U-103 (*)	Hydrogen	1/91	AN-103	U-204	
	Organics	5/94	AN-104	20 Tanke	1
U-105 (*)	Hydrogen	1/91	AN-105	· · · · · · · · · · · · · · · · · · ·	,
	Organics	5/94	AW-101		
U-1 <b>06</b>	Organics	1/91	SY-101	High Heat	
U-107 (*)	Organics	1/91	SY-103	C-106	
	Hydrogen	12/93	25 Tanke	1 Tank	
U-108	Hydrogen	1/91		er var zo er zamietakin adala initia	
U-109	Hydrogen	1/91			
U-1 <b>11</b>	Organics	8/93	32 Single-	Shell tanks	
<b>⊍-203</b>	Organics	5/94	<del>_</del> _	-Shell tanks	
J-204	Organics	5/94		on Watch Lists	
32 Tenke (*)				VII. 17 MANIE LAGIS	

<sup>(\*)</sup> Eight tanks are on more than one Watch List

All tanks were removed from the Ferrocyanide Watch List; see Table A-2 for list and dates.

## TABLE A-2. ADDITIONS/DELETIONS TO WATCH LISTS BY YEAR November 30, 1998

Added/Deleted dates may differ from dates that tanks were officially added to the Watch Lists. (See Table A-1).

		·				Total Tanks (1)			
	Ferrocyanide	Hydrogen	Organics	High Heat			Total		
1/91 Original List -Response to Public Law 101-510	23	23	8	e me <b>t</b> mai	47	5	. 5		
Added 2/91 (revision to Original List)	1 T-107				1				
		25	8	1	48	5	5		
Added 8/92	Africhidadoesaredanaaaaaaaaaaaaaaaaaaa	1 AW-101				1	<u>'</u>		
Total - December 31, 1992	24	24	8		48	- 6	5		
Added 3/93 Deleted 7/93	-4		1 0-111		1				
Deleted 1753	(BX-110)			<u> </u>	4		i		
	(BX-111)					Ī			
	(BY-101)			ļ		ļ			
	(T-101)		]				1		
Added 12/93		1 (U-107)			0				
Total - December 31, 1993	20	25	9	1	45	8	5		
Added 2/94 Added 5/94			1 1-111		1				
Added 5/94			10 A-101		4				
			AX-102 C-102						
			S-111						
			SX-103						
			TY-104						
			U-103						
			U-105						
·			U-203						
Deleted 11/94	-2 (BX-102)		U-204		-2				
	(BX-106)			i	-2	i			
Total - December 31, 1994, & December 31, 1985	18	. 25	20	1.0	48	6	54		
Deleted 6/96	-4 (C-108)				-4		111111111111111111111111111111111111111		
ľ	(C-109)				·	ļ			
	(C-111)					ļ			
Deleted 9/96	(C-112) -14 (BY-103)	i							
1	(BY-104)				-12	Į			
	(BY-105)			l		Ī			
	(BY-106)		İ	ļ	- 1				
	(BY-107)					1			
	(BY-108)								
	(BY-110)			i	- 1				
	(BY-111) (BY-112)		Į						
	(T-107)		1	- 1	Į				
	(TX-118)		į		Ī	ļ			
İ	(TY-101)			J					
	(TY-103)	İ				- 1			
TEAN SEE A COLOR OF THE SECOND	(TY-104)			]					
otal - November 30, 1998		25	20		32	8	38		

<sup>(1)</sup> Eight tanks are on more than one list: A-101, S-102, S-111, SX-103, SX-106, U-103, U-105, and U-107; therefore the total of tanks added or deleted will depend upon whether a tank is also on another list.

### TABLE A-3. TEMPERATURE MONITORING IN WATCH LIST TANKS (Sheet 1 of 2) November 30, 1998

All Watch List tanks are reviewed for increasing temperature trends. Temperatures in these tanks are monitored by the Tank Monitor And Control System (TMACS), unless indicated otherwise.

Temperatures are taken in the waste unless in-waste thermocouples are out of service. See footnote (3). Temperatures below are the highest temperatures recorded in these tanks during this month, and do not exceed the maximum criteria limit for this month.

## Temperatures in Degrees F. Total Waste in Inches

(Total waste in inches is calculated from Inventory tables and size of tank, not surface level readings)

Hydro/Flammable Gas				nic Salts	0.20 0. 10		h Heat	iriga,
Total					Total			Total
Tank No.	Temp.	Waste	Tank No.	Temp.	<u>Waste</u>	Tank No.	Temp.	Waste
A-101	148	347	A-101	148	347	C-106 (2)	195	72
AX-101 (*)(3)	130	272	AX-102 (*)	78	14	i fark		
AX-103 (*)	111	40	B-103 (*)(3)	68	17			
S-102	104	207	C-102	82	149	Note: Sluicing	began	
S-111	90	224	C-103	117	66	November 18, 1	1998	
S-112	84	239	\$-102	104	207			
SX-101	133	171	S-111	90	224			
SX-102	142	203	SX-103	161	242	j		
SX-103	161	243	SX-106	105	201			
SX-104	148	229	T-111	67	158			
SX-105	167	254	TX-105	97	228			
SX-106	105	201	TX-118	75	134			
SX-109 (1)	141	96	TY-104	67	24			
T-110	65	133	U-103	86	166			
U-103	86	166	U-105	89	147			
U-105	89	147	U-106	82	78			
U-107	79	143	U-107	79	166			
U-108	87	166	U-111	81	115			
U-109	83	164	U-203	64	12	1		
AN-103	109	348	U-204	64	12			
AN-104	109	384	20 Tarks					
AN-105	106	410						
AW-101 (*)	101	410				ļ		
SY-101	122	405						
SY-103	95	270						
25 Tenks		[						

<sup>(\*)</sup> Temperatures in these tanks are taken manually on a weekly basis.

<sup>38</sup> Tanks are on the Watch List (8 tanks are on more than one list: A-101, S-102, S-111, SX-103, SX-106, U-103, U-105, U-107)

All tanks have been removed from the Ferrocyanide Watch List. See Table A-2 for list and dates.

## TABLE A-3. TEMPERATURE MONITORING IN WATCH LIST TANKS (sheet 2 of 2)

#### Notes:

#### Unreviewed Safety Question(USQ):

There is a USQ currently associated with all single-shell tanks, resulting in special controls required, and limiting the work in the tanks. Pumping is on hold until the DOE-RL approval is received for each tank.

#### Hydrogen/Flammable Gas:

Tanks which are suspected to have a significant potential for hydrogen/flammable gas generation, entrapment, and episodic release. The USQ associated with these tanks is due of the potential consequences of a radiological release resulting from a flammable gas burn, an event not analyzed in the SST Safety Analysis Report (SAR).

#### Organic Salts:

Single-shell tanks containing concentrations of organic salts ≥3 weight% of total organic carbon (TOC)(equivalent to 10 wt% sodium acetate). The USQ associated with these tanks is because it has been concluded there is a small potential for an organic nitrate accident. Double-shell tanks have >3 weight% TOC but are not on the Watch List because they contain mostly liquid, and there is no credible organic safety concern for tanks which contain mostly liquid.

#### High Heat:

Tanks which contain heat generating strontium-rich sludge and require drainable liquid to be maintained in the tank to promote cooling. Only tank C-106 is on the High Heat Watch List because in the event of a leak, without water additions the tank could exceed temperature limits resulting in unacceptable structural damage. The tank is cooled through evaporation in conjunction with active ventilation. Water is periodically added as evaporation takes place.

#### Active ventilation:

There are 15 single-shell tanks on active ventilation (eight are on the Watch List as indicated by an asterisk):

C-105	SX-107
C-106 *	SX-108
SX-101 *	SX-109 *
SX-102 *	SX-110
SX-103 *	SX-111
SX-104 *	SX-112
SX-105 *	SX-114
SX-106 *	

Note: A-104, 105 and 106 exhauster has been out of service since 1991 and is no longer considered actively ventilated. Although C-104 has a cascade line with C-105, it is not considered to be actively ventilated.

#### Footnotes:

- (1) Tank SX-109 has the potential for flammable gas accumulation only because other SX tanks vent through it.
- (2) Tank C-106 is on the Watch List because in the event of a leak without water additions the tank could exceed temperature limits resulting in unacceptable structural damage.
- (3) There are no in-waste temperatures for tanks AX-102 and B-103. The waste level in these tanks is lower than the lowest thermocouple in these trees. Temperatures in this table show the maximum in the tanks taken in the vapor space.

## TABLE A-4. TEMPERATURE MONITORING IN NON-WATCH LIST TANKS November 30, 1998

### SINGLE-SHELL TANKS WITH HIGH HEAT LOADS (>40,000 Btu/hr)

Ten tanks have high heat loads for which temperature surveillance requirements are established by OSD-T-151-00013. Only one of these tanks (241-C-106) is on the High Heat Watch List. In an analysis, WHC-SD-WM-ER-333, "Evaluation of Heat Sources in High Heat Single Shell Tanks," Bander, 1994, it was determined that six of the ten tank have heat sources greater than 40,000 Btu/h. Additionally, although four tanks have heat loads less than 40,000 Btu/h, it is recommended that these tanks remain on the High Heat Load Listbecause of uncertainties in the parameters used in these analyses. It is estimated that the current analysis predicts the heat loads within +/- 20%.

Temperatures in these tanks did not exceed OSD requirements for this month. All high heat load tanks, with the exception of 241-A-104 and 241-A-105, are on active ventilation. All high heat load tanks are monitored by the Tank Monitor and Control System (TMACS), with the exception of A-104 and A-105, which are taken manually on a weekly basis.

Tank No.	Temperature (F.)	Total Waste In Inches	(Total Waste In Inches is calculated from inventory table
A-104	——————————————————————————————————————		****
	171	10	and tank size, not surface level
A-105	141	07	readings)
C-106 (*)	195	72	
SX-107	166	43	
SX-108	187	37	
SX-109	141	96	
SX-110	164	28	
SX-111	187	51	
SX-112	149	39	
SX-114	179	71	

(\*) C-106 on High Heat Load Watch List. Sluicing began November 18, 1998. Highest temperature in 34 lateral thermocouples beneath A-105: 237

#### SINGLE SHELL TANKS WITH LOW HEAT LOADS (<=40,000 Btu/hr)

There are 108 low heat load non-watch list tanks. Temperatures in tanks connected to TMACS are monitored by TMACS; temperatures in those tanks not yet connected to TMACS are manually taken semiannually in January and July. Temperatures obtained were within historical ranges for the applicable tank.

No temperatures have been obtained for several years in the tanks listed below. Most of these tanks have no thermocouple tree.

Tank No.	Tank No.
BX-104	TX-101
BY-102	TX-110
BY-109	TX-114
C-204	TX-116
SX-115	TX-117
T-102	U-104
T-105	

#### TABLE A-5. SINGLE-SHELL TANKS MONITORING COMPLIANCE STATUS

149 TANKS (Sheet 1 of 6) November 30, 1998

The following table indicates whether Single-Shell tank monitoring was in compliance with the requirements as specified in the applicable documents as of the last day of the applicable month:

#### NOTE:

All Watch List and High Heat tank temperature monitoring is in compliance. (4)
All Dome Elevation Survey monitoring is in compliance. (See also footnote 13)
All Psychrometrics monitoring is in compliance (2).
Drywell monitoring is done "as needed" (9).
In-tenk photos/videos are taken "as needed" (3)

LEGEND:	
CECEND:	= in compliance with all applicable documentation = noncompliance with applicable documentation
0/S	= Out of Service
Neutron	= LOW readings taken by Neutron probe
POP	≈ Plant Operating Procedure, TO-040-650
MT/FIC/ ENRAF	= Surface level measurement devices
OSD	= Operating Specifications Doc., OSD-T-151-00013, -00031
N/A	= Not applicable (not monitored, or no monitoring schedule)
None	= Applicable equipment not installed

	Tank Category		Primary Temperature Leak	Surface Level Readings (1)			Low	
Tank	Watch	High	Readings	Detection	(OSR,OSD)			Readings (OSD)(5,7)
Number	List	Heat	(4)	Source (5)	MT	FIC	I ENRAF	Neutron
A-101			i ka i	LOW	None	Herie		
A-102				None	None		None	None
A-103				LOW	None	Han		
A-104	LIPA N			None	None			A Plane
A-105	a ser sammer d			None				All - None
A-106				None				i i i i i i i i i i i i i i i i i i i
AX-101				LOW	The Parts	PTPONE III		H4 110
AX-102				None		Talaa III		
AX-103				None	None			No.
AX-104				None	i ion			None
B-101				None				
B-102				ENRAF				Main <b>Res</b> al
B-103				None				GB .
B-104				LOW				
B-106				LOW		The second second		
B-106				FIC	None			None
B-107				None				No.
B-108				None	None		The state of the s	
B-109				None				
B-110				LOW	0/8		Times	
B-111				LOW	Hore			
B-112				ENRAF				
B-201				MT		Bellis de debendades de deservición de la companya de la companya de la companya de la companya de la companya		Kon
B-202				MT		an ann an t-airean a t-airean a t-airean a t-airean a t-airean a t-airean a t-airean a t-airean a t-airean a t		The second
B-203				MT			Taristan III III II	Note
B-204		kiimini		MT			Property of Property of the Party	
BX-101				ENRAF	ANCHORRORAGINA CONTRACTOR DE LA CONTRACTOR DEL CONTRACTOR DE LA CONTRACTOR DE LA CONTRACTOR DE LA CONTRACTOR			None
BX-102				None				
BX-103				ENRAF				T Reid
BX-104				ENRAF	None .			None
BX-105				None				Turis .
BX-106				ENRAF	None			Control of the Contro
BX-107				ENRAF	None	None		None

TABLE A-5. SINGLE-SHELL TANKS MONITORING COMPLIANCE STATUS
149 TANKS (Sheet 2 of 6)

	Tank C	ategory	Temperature	Primary Leak	Surfac	e Level Readin	as (1)	LOW Readings
Tank	Watch					(OSD)(5,7)		
Number	List	Heat	(4)	Source (5)	MI	(OSD)	ENRAF	Neutron
BX-108				None	None	None		Nore
BX-109				None	None	None		None
BX-110				None	Nors			Hora
BX-111				FOM	None			
BX-112				ENRAF	None :			
BY-101				LOW	in a securitar and	) jere		
BY-102				LOW				
BY-103				LOW				
BY-104				LOW				
BY-105				LOW				
BY-106				LOW				
BY-107				LOW		Secretary Company	A the second of	
BY-108				None			THE LEGISLAND	
BY-109				LOW				
BY-110				LOW	Neg III			
BY-111				LOW		Pen-		
BY-112				LOW				
C-101 C-102				None		والمراجعة المراجعة المراجعة		
C-102 C-103				None	None			None
C-103				ENRAF	None			None
C-105				None				None
C-106 (3)				None ENRAF	A THE PARTY OF THE			i Nos
C-100 (3)				ENRAF	ercestesiasussimusimusetasi t			
C-108				None				i i Acce
C-109				None				licie
C-110				MT				
C-111				None		Colorado parado de la Colorado	1000	
C-112				None			SHOPP OF BUILDING	1980 1 18 18 18 19 19 19 19 19 19 19 19 19 19 19 19 19
C-201				None				None .
C-202				None			Milifeldende Steel	
C-203				None			Berthi and name of the state	
C-204				None		Ali danish dada da		
S-101				ENRAF				
S-102				ENRAF				
S-103				ENRAF				
S-104				LOW				
S-105				LOW				
S-106				ENRAF				
S-107				ENRAF				No.
S-108				LOW				
S-109				FOM		Marie Marie		
S-110				LOW				
S-111				ENRAF	Car		COLUMN CO	
S-112		TATAL PARKET BANK BANK BANK BANK BANK BANK BANK BANK		LOW				
6X-101	DELECTION OF THE PROPERTY OF T	a wow our count our and this base this sea to see				PRINCIPLE DESCRIPTION OF THE PRINCIPLE O		
5X-102	DE LESSUES RESERVA DE PROPERTA DE SE	madrodendoddobbbbbdhannaam 🕻		LOW				
SX-103	SERVINISTRANDINOSIONOPORO IO			LOW		Kore		
SX-104	Editodoutleare reassements re	NAME AND PARTY OF THE PARTY OF		LOW	Military was proposed to defend			
SX-105	PHOENIS OF DOMESTICS AND THE THE			LOW				
SX-106				ENRAF				
SX-107				None		Y Paris		No.
SX-108		X		None		Reside 1		Alone

TABLE A-5. SINGLE-SHELL TANKS MONITORING COMPLIANCE STATUS 149 TANKS (Sheet 3 of 6)

	Tenk Ca	tegory	Temperature	Primary Leak	Surfe	ice Level Readi	inge (1)	LOW Readings
Tank	Watch	High	Readings	Detection		(OSD)(5,7)		
Number	List	Heat	(4)	Source (5)	MT MT	(OSD)	I ENRAF	Neutron
SX-109 (3)	2			None	None			None
SX-110				None		i ika		RES.
SX-111		MALIAN		None				A de la
SX-112				None				The state of the s
SX-113				None				
SX-114				None				
SX-115		lilithi	A section of the contract of t	None				THE Note of
T-101				None		Letter 1		Rolls
T-102				ENRAF	l lée	Noise		
T-103				None	l lens			Pone /
T-104				LOW	None	None	i de como de participa de	
T-105			liere;	None	None	المراداة الأراز	ii ja ja ja ja ja ja ja ja ja ja ja ja ja	Alone :
T-106				None	None T	None		None
T-107				ENRAF	None	tions		Hore
T-108				ENRAF	Name	None T		None
T-109				None	Hate	None		North
T-110				LOW	lione	No.		
T-111				LOW				
T-112				ENRAF	in Personal			
T-201				MT				
T-202				MT			Principal Particular Control	
T-203				None			F SHEETHER AND SHEETHER SHEETH	
T-204				MT				Port
TX-101				ENRAF	Rest.	No.		Ker
TX-102				LOW	i i i	. We		
TX-103				None				
TX-104				None				
TX-105				None				
TX-106				LOW				
TX-107				None		None		
TX-108				None	Here	None		None :
TX-109				LOW	None	None		
TX-110				LOW	None	None	1	
TX-111				LOW	None	None		
TX-112				LOW	None	None		
TX-113				LOW	None	None		
TX-114			THE RESIDENCE OF THE PERSON OF	LOW	None	None		
TX-115				LOW	None	None		
TX-116			None	None	None	None		
TX-117			None	LOW	None	None		None
TX-118	and the second second		Maria da Sala Sala Sala Sala Sala Sala Sala	LOW	None	None		
TY-101	Carried Paradigues and		ratual rational and a second	None	None	None		
TY-102	00000000000000000000000000000000000000			ENRAF	CONTROL OF CONTROL OF	straight the second second	MANAGEMENT SERVICE SER	None
TY-103	MANAGEMENT OF THE PROPERTY OF THE PARTY OF T			LOW	New			Nane
TY-104	Helianganananananan sono			ENRAF	Ners	None		
TY-105				None	None	None		Nore
TY-106				None	Nere	None		More
J-101				MT	Hill Make Andrews	None		Nors
J-102	## ###################################	The state of the s		LOW	MODEL CONTROL CONTROL OF THE PROPERTY OF THE P	Nore		Noise
J-103	MESSESSESSESSESSESSESSESSESSESSESSESSESS			ENRAF	00000000000000000000000000000000000000	Nove		
J-104	CHOCCOSTORICATION OF THE PROPERTY OF THE PROPE			None	Minanassanosomus su su su su su su su su su su su su s			
J-105	IPCR050569be969000000000000000000000000000000000			ENRAF	ADDITION OF THE PROPERTY OF TH	No.		
J-106	P. C. C. C. C. C. C. C. C. C. C. C. C. C.					None		
				ENRAF	None	None		

TABLE A-5. SINGLE-SHELL TANKS MONITORING COMPLIANCE STATUS 149 TANKS (Sheet 4 of 6)

	Tank Ca	itegory	Temperature	Primary Leak	Surfa	ice Level Readir	ngs (1)	LOW Readings
Tank Number	Watch List	High Heat	Readings (4)	Detection Source (5)	MT	(OSD)	I ENRAF	(OSD)(5,7)
U-107				ENRAF	None			
U-108				LOW				
U-109				ENRAF	Note			
U-110				None	Nema			i i i i i i i i i i i i i i i i i i i
U-111				LÓW				
U-112				None				None :
U-201				MT		None	Note	, None
U-202				MT		Pierre	ا فرمان	Nove Fig.
U-203				None	Norm	None		None
U-204				ENRAF	None	None		Norw
Catch Tanks a	ind Special Su	rveillance Fa	cilities	<del></del>				
A-302-A			N/A	[6]	Rote			None
A-302-B			na -					
ER-311		MECZIE						Nere
AX-152							The state of the s	
AZ-151					7 (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)			
AZ-154								
BX-TK/SMP		FFIJIE 5				The Company of the		
A-244 TK/SMP								
AR-204								
A-417		BULLAR						
A-350								L. Pere
CR-003								Pana 1
Vent Sta.								Pers
S-302								
S-302-A								
S-304					Todaya III			
TX-302-B		HERCLINE						
TX-302-C			NA:					None
U-301-B								Hore
UX-302-A								Plone
S-141							Noe	Mone
S-142						Nore	Nee	None
Totals:	32	10	N/C: 0		N/C: 0	N/C: O	N/C: Ö	N/C: 0
149 tanks	Watch	High						
	List	Heat						1
	Tanke	Tanks						
	(4)	(4)				<u> </u>		

## TABLE A-5. SINGLE-SHELL TANKS MONITORING COMPLIANCE STATUS -149 TANKS (Sheet 5 of 6)

#### Footnotes:

- All SSTs have either manual tape, FIC, or ENRAF surface level measuring devices. Some also have zip cords.
  - ENRAF gauges are being installed to replace FICs (or sometimes manual tapes). The ENRAF gauges are being connected to TMACS, but many are currently being read manually from the field. See Table A-7 for list of ENRAF installations.
- 2. High heat tanks have active exhausters; psychrometrics can be taken in the high heat tanks. Psychrometric readings are taken on an "as needed" basis with the exception of tanks C-105 and C-106. Hanford Federal Facility Agreement and Consent Order," Washington State Department of Ecology, U. S. Environmental Protection Agency, and U. S. Department of Energy," Fourth Amendment 1994 (Tri-Party Agreement) requires psychrometric readings to be taken in C-105 and C-106 on a monthly frequency. Tank C-105 exhauster has been shut down for preparation of C-106 sluicing. There were no psychrometrics performed on C-105 and C-106 during November. Also, SX-farm now has psychrometrics taken monthly.
- 3. C-106 and SX-109 these tanks are on both category lists (Watch List and high heat list) C-106 is the only tank on the high heat list included on the High Heat Watch List; SX-109 is on the Organics Watch List, and also on the high heat list (but not on the High Heat Watch List).
- 4. Temperature readings may be regulated by OSD or POP. Temperatures cannot be obtained in 13 low heat load tanks (see Table A-4). The OSD does not require readings or repair of out-of service thermocouples for the low heat load (<40,000 Btu/h) tanks. However, the POP requires that attempts are to be made semiannually in January and July to obtain readings for these tanks.
  - Temperatures for many tanks are monitored continuously by TMACS; see Table A-8, TMACS Monitoring Status.
- Document WHC-OSD-T-151-00031, "Operating Specifications for Tank Farm Leak Detection," requires that single-shell tanks with the surface level measurement device contacting liquid, partial liquid, or floating crust surface, will be monitored for leak detection on a daily basis. Tanks with a solid surface will be monitored for leak detection on a weekly basis by taking neutron scan data from a Liquid Observation Well (LOW), if an LOW is present. Tanks with a solid surface but without LOWs will not be monitored for leak detection if the tank has been interim stabilized, until an LOW is installed. Non-interim-stabilized tanks will have drywell surveys taken as a backup on a monthly basis if surface or interstitial level measurement equipment is unavailable. The OSD specifies what leak detection methods are to be used for each tank, and the requirements if the readings are not taken on the required frequency or if equipment is out of service.
- 6. Leak detection for the catch tanks is performed by monitoring for the buildup of liquid in the secondary containment (for most tanks with secondary containment) or for decrease in the liquid level for those tanks without secondary containment or secondary containment monitoring.
  - Catch tanks 240-S-302 and 241-S-302-A are monitored for intrusions only, and are not subject to leak detection monitoring requirements until liquid is present above the intrusion level.
  - Weight Time Factor is the surface level measuring device currently used in A-417, A-350 and 244-A-Tank/Sump. DCRT CR-003 is inactive and measured in gallons.
- 7. Document WHC-SD-WM-TI-605, REV. 0, dated January 1994, describes the rationale for Liquid Observation Well (LOW) installation priority. This priority is based on tank leak status, tank surface condition, and tank stabilization status. Also included is a listing of tanks with the waste level being below two feet which have no

### TABLE A-5. SINGLE-SHELL TANKS MONITORING COMPLIANCE STATUS - 149 TANKS (Sheet 6 of 6)

priority assigned because no effort will be made to install LOWs in the near future. LOW probes are unable to accurately monitor interstitial liquid levels less than two feet high.

Tanks which will not receive LOWs:

A-102	BX-101	C-201	T-106
A-104	BX-103	C-202	T-108
A-105	BX-105	C-203	T-109
AX-102	BX-106	C-204	TX-107
AX-104	BX-108	SX-110	TY-102
B-102	C-108	SX-113	TY-104
B-103	C-109	SX-115	TY-106
B-112	C-111	T-102	U-101
		T-103	U-112

Total - 34 Tanks

- 8. TX-105 the riser has been removed; the LOW has not been monitored since January 1987. Liquid levels are being taken.
- 9. All drywell scans are done by request only, when required in addition to, or as a BACKUP for, a PRIMARY leak detection method, per OSD-T-151-00031. Currently, there are only two tanks which require drywell scans (C-105 and C-106); these are taken monthly.

Only two tank farms, A and SX, have laterals. There are currently no functioning laterals and no plans to prepare these for use.

- 10. AX-101 LOW readings are taken by gamma sensors.
- 11. SX-101 ENRAF data suspect: core sampling done displacer sticks on top of crust or goes into hole. LOW is primary device. ENRAF was flushed and recalibrated September 1, 1998, and the reading was back to near normal. Data marked suspect since September 10, when readings began fluctuating daily from 163 inches to 169 inches (new baseline established November 19, 1998, at 16.6 inches). Still suspect as of November 30, with 168.71 inch reading.
- 12. Catch Tanks S-141 and S-142 have no M.T. readings.
- 13. SX-104 Dome Deflection tank dome deflection for this tank has not been performed during pumping as required by OSD-T-151-00013. The OSD required a dome deflection survey by performed every 20,000 ± 5,000 gallons net jet pump production. Approximately 28,000 gallons had been jet pumped out of SX-104 when this was discovered. See UOR PMHC-TANKFARM-1998-0131 on page 5 of the Monthly Summary Tank Investigations. Dome deflection surveys are now being done according to this requirement.

### TABLE A-6. DOUBLE-SHELL TANKS MONITORING COMPLIANCE STATUS

28 TANKS (Sheet 1 of 2) November 30, 1998

The following table indicates whether Double-Shell tank monitoring was in compliance with the requirements as specified in the applicable documents as of the last day of the applicable month.

NOTE:

Dome Elevation Surveys are not required for DSTs.

Psychrometrics and in-tank photos/videos are taken "as needed" (2)

LEGEND: (Shaded) = In compliance with all applicable documentation N/C = Noncompliance with applicable documentation FIC/ENRAF = Surface level measurement devices M.T. OSD = OSD-T-151-0007, OSD-T-151-0031 None = no M.T., FIC or ENRAF installed 0/\$ = Out of Service W.F. = Weight Factor Rad. = Radiation

		İ	Ī			R	adiation Reading	s	
l Tank		Temperature Readings (3)	Sur	Surface Level Readings (1) (OSD)			Leak Detection Pits (4) (OSD) An		
Number	Watch List	(OSD)	M.T.	FIC	ENRAF	W.F.	Rad. (8)	(OSD)	
AN-101				Nene			10		
AN-102									
AN-103									
AN-104								C CONTROL OF THE CONT	
AN-105	X		6,6				THE TRANSPORT OF THE PROPERTY		
AN-106									
AN-107									
AP-101			DE .		The state of the s		(8)		
AP-102					Test.	0/8 (9)	(8)		
AP-103					None	0/5 (9)	(8)		
AP-104			O/S			0/8 (0)	(6)		
AP-105						0/8 (B)			
AP-106							180		
AP-107							100		
AP-108							A SHEUSSELLER OF THE THE SECRETARIES		
AW-101							(a)		
AW-102				i Maria II.			(6) (6)		
AW-103					· · · · · · · · · · · · · · · · · · ·	en anneadouspagnionalingusgipusg La sanskalakahangspenneadous oom	er ennitrom oppositioners and property and		
AW-104							(8)		
AW-105							(8)		
AW-106							(8)		
AY-101						O/B	P		
AY-102				ien			<b>B</b>	(5)	
AZ-101							(8)		
AZ-102					Norm		(8)	(5)	
SY-101			(O) (F	Nene	TO HOROCO DISCONSIDENTAL PROPERTY AND AND AND AND AND AND AND AND AND AND		<b>(8)</b>	<b>(6)</b>	
SY-102				No.			. 8		
SY-103						171	(A)		
Fotals:	6	N/C: 0	N/C: 0		N/C: O	N/C: O			
28 tanks	Watch List Tanks			.,,.,	14,0. <del>0</del>	III/C. U	N/C: U	N/C: 0	

## TABLE A-6. DOUBLE-SHELL TANKS MONITORING COMPLIANCE STATUS - 28 TANKS (Sheet 2 of 2)

#### Footnotes:

- Some double-shell tanks have both FIC and manual tape which is used when the FIC is out of service.
   Noncompliance (N/C) will be shown when no readings are obtained. ENRAF gauges are being installed to replace FICs. The ENRAF gauges are being connected to TMACS, but some are currently being read manually.
- Psychrometric readings are taken on an "as needed" basis. No psychrometric readings are currently being taken in the double-shell tanks.
- 3. OSD specifies double-shell tank temperature limits, gradients, etc.
- 4. Applicable OSD and HNF-IP-0842, latest revisions, are used as guidelines for monitoring Leak Detection Pits. See also (8) below.
- 5. AY-101 and AZ-101/102 are monitored only by the annulus Leak Detection Probe Measurement device.
- 6. AW-102 has ENRAF, FIC and M.T. At some point the FIC will be removed.
- 7. SY-103 CWF reading is above normal range of 24 inches.
- 8. USQ TF-97-0038, dated April 28, 1997, specifies discontinuing the use of leak detection pit radiation monitoring equipment in all double-shell tank farms where the leak detection pits are used as tertiary leak detection. This applies to all double-shell tank farms

Also, two radiation monitors used for leak detection for transfer lines will not be discontinued (CRM-101B in AY farm and CRM-101/102-1 in AZ farm) - these were not included in the USQ. May 1998 - RAD monitoring is no longer required in these monitors per TSR-006 (Rev 0-6)

9. Weekly readings being obtained by Instrument Technicians in these tanks:

AP-103C (for tanks AP-101 - 104)

AP-105C (for tanks AP-105 - 108)

## TABLE A-7. ENRAF SURFACE LEVEL GAUGE INSTALLATION AND DATA INPUT METHODS

November 30, 1998

LEGEND	0466			end Committee	- Custom							
LEGEND	-	•		ited Surveillar	_							
	SACS = Surveillance Analysis Computer System											
i	TMACS = Tank Monitor and Control System  Auto = Automatically entered into TMACS and electronically transmitted to SACS											
İ	Auto = Automatically entered into TMACS and electronically transmitted to SACS  Manual = EITHER manually entered into CASS by field operators and electronically transmitted to SACS											
1	Mainai		•	d directly into		•		-				
<b></b>	<del></del>	011111011	July Olitore	a allocay with		<b>***</b>	poisonii.o.,					
EAST .	A DE A					WEST	AREA					
	1		***	T	T .	***	T		***		T	T .
Tank	Installed	Input	Tank	installed	Input	Tank	Installed	Input	28	Tank	installed	Input
No.	Date	Method	No.	Date	Method	No.	Date	Method		No.	Date	Method
A-10	09/95	Auto	B-201			S-101	02/95	Menuel	****	TX-101	11/95	Auto
A-102			B-202	<del> </del>		S-102	06/95	Auto	40.00	TX-102	05/96	Auto
A-103	07/96	Auto	B-203			S-103	05/94	Auto	-	TX-103	12/95	Auto
A-104	05/96	Manual	B-204 BX-101	04/96	Auto	S-104 S-105	07/95	Manual	-	TX-104	03/96	Auto
A-105 A-106	01/96	Auto	BX-101	06/96	Auto	S-106	06/94	Manual Auto	-	TX-105 TX-106	04/96	Auto
AN-101	08/96	Auto	BX-103	04/96	Auto	S-107	06/94	Auto	-	TX-107	04/96	Auto
AN-102			BX-104	05/96	Auto	S-108	07/95	Manual		TX-108	04/96	Auto
AN-103	08/95	Auto	BX-105	03/96	Auto	S-109	06/95	Manual	10000	TX-109	11/95	Auto
AN-104	08/95	Auto	BX-106	07/94	Auto	S-110	08/95	Manual		TX-110	06/96	Auto
AN-105	08/95	Auto	BX-107	06/96	Auto	S-111	08/94	Auto		TX-111	05/96	Auto
AN-106			BX-108	05/96	Auto	S-112	05/95	Auto	-	TX-112	05/96	Auto
AN-107			BX-109	08/95	Auto	SX-101	04/95	Auto	-	TX-113	05/96	Auto
AP-101 AP-102			BX-110 BX-111	06/96 06/96	Auto	SX-102 SX-103	04/95 04/95	Auto	error.	TX-114	05/96	Auto
AP-103			BX-112	03/96	Auto	SX-103	05/95	Auto		TX-115 TX-116	06/96 06/96	Auto
AP-104		****	BY-101		744	SX-105	06/95	Auto	****	TX-117	06/96	Auto Auto
AP-105			BY-102			SX-106	08/94	Auto	-	TX-118	03/96	Auto
AP-106			BY-103	12/96	Manual	SX-107				TY-101	07/95	Auto
AP-107			BY-104			SX-108			*****	TY-102	09/95	Auto
AP-108			BY-105			SX-109	09/98	Auto	<b>W</b>	TY-103	09/95	Auto
AW-101	08/95	Auto	BY-106			SX-110				TY-104	06/95	Auto
AW-102	05/96	Auto	BY-107			SX-111			<del>- 1000</del>	TY-105	12/95	Auto
AW-103 AW-104	05/96 01/96	Auto Auto	BY-108 BY-109			SX-112			200	TY-106	12/95	Auto
AW-105	06/96	Auto	BY-110	2/97	Manual	SX-113		-	****	U-101 U-102	01/96	
AW-106	06/96	Auto	BY-111	2/97	Manual	SX-115			277.1	U-102	07/94	Manual Auto
AX-101	09/95	Auto	BY-112			SY-101	07/94	Auto		U-104	07/34	AUIO
AX-102	09/98	Manual	C-101			SY-102	06/94	Manual	-	J-106	07/94	Auto
AX-103	09/95	Auto	C-102			SY-103	07/94	Auto	2000	J-106	08/94	Auto
AX-104	10/96	Auto	C-103	08/94	Auto	T-101	05/95	Manuel		U-107	08/94	Auto
AY-101	03/96	Manual	C-104			T-102	06/94	Auto		J-108	05/95	Auto
AY-102	01/98	Auto	C-105	05/96	Manual	T-103	07/95	Manual		J-109	07/94	Auto
AZ-101	08/96	Manuai	C-106	02/96	Auto	T-104	12/95	Manual		J-110	01/96	Manual
AZ-102 B-101			C-107 C-108	04/95	Auto	T-105 T-106	07/95 07/95	Manual		J-111	01/96	Manual
B-102	02/95	Manual	C-109			T-107	06/94	Manual Auto		J-112 J-201		
B-103			C-110			T-108	10/95	Manual		J-202		
B-104			C-111			T-109	09/94	Manuel	-	J-203	Q9/9B	Manual
B-105			C-112	03/96	Manual	T-110	05/95	Auto		J-204	6/98	Manual
B-106			C-201			T-111	07/95	Menual				
B-107			C-202			T-112	09/95	Manual				
B-108			C-203			T-201						
B-109 B-110			C-204	<del></del>		T-202			▓			
B-110 B-111						T-203 T-204						
B-112	03/95	Manual							<b>***</b>	}		
	t Area: 43	171-111-101	330			W Tab-1 Mr			***			
	L Area. 43			and inc. The	100 20	I Otal We	st Area: 69	·	_	<u> </u>		

<sup>112</sup> ENRAFs installed: 80 automatically entered into TMACS, 32 manually entered into CASS

## TABLE A-8. TANK MONITOR AND CONTROL SYSTEM (TMACS) November 30, 1998

Note: Indicated below are the number of tanks having at least one operating sensor (some tanks have more than one sensor: multiple sensors of the same type in a tank are not shown in the table) for example: 10 tanks in BY-Farm have at least one operating TC sensor and 3 tanks in BY-Farm have at least one operating RTD sensor.

Acceptance Testing Completed: Sensors Automatically Monitored by TMACS

	Temper	atures				
		Resistance				
EAST AREA	Thermocouple	Thermal	ENRAF			Gas
	Tree	Device	Level	Pressure	Hydrogen	Sample
Tank Farm	(TC)	(RTD)	Gauge	(b)	(c)	Flow
A-Farm (6 Tanks)	1		3	127	1 1	1
AN-Farm (7 Tanks)	7		4	7	3	3
AP-Farm (8 Tanks)				· · · · · · · · · · · · · · · · · · ·		
AW-Farm (6 Tanks)	6		6		1	1
AX-Farm (4 Tanks)	3		3		(d)	
AY-Farm (2 Tanks)			1	<u> </u>		
AZ-Farm (2 Tanks)		, , , , , , , , , , , , , , , , , , , ,	· · · · · · · · · · · · · · · · · · ·		1	
B-Farm (16 Tanks)	1		71. 1.11		<del></del>	
BX-Farm (12 Tanks)	11		12			
BY-Farm (12 Tanks)	10	3				
C-Farm (16 Tanks)	15	7	3	1		
TOTAL EAST AREA						
(91 Tanks)	54	4	32	8	5	5
WEST AREA						
S-Farm (12 Tanks)	12		6	1	3	3
SX-Farm (15 Tanks)	14		7	1	7	7
SY-Farm (3 Tanks) (a)	3		2	1	2	2
T-Farm (16 Tanks)	14	1	3		1	1
TX-Farm (18 Tanks)	13		18		1	
TY-Farm (6 Tanks)	6	3	6			
U-Farm (16 Tanks)	15		6	4	6	6
TOTAL WEST AREA						<del></del>
(86 Tanks)	81	4	48	7	18	18
TOTALS (177 Tanks)	131	8	80	15	23	23

- (a) Tank SY-101 has 2 gas sample flow sensors plus 2 vent flow sensors, and 2 ENRAFs.
- (b) Each tank has low and high range sensors (9x2=18 sensors)
- (c) Each tank has low and high range sensors (17x2=34 sensors)
- (d) AX-101 Hydrogen was ATP'd in TMACS on September 21, 1998, but not transmitting yet lines plugged.

### APPENDIX B

# DOUBLE SHELL TANK WASTE TYPE AND SPACE ALLOCATION

TABLE B-1. DOUBLE-SHELL TANK WASTE TYPE AND SPACE ALLOCATION NOVEMBER 1998

DOUBLE-SHELL TANK INVENTORY BY WASTE TYPE SPACE DESIGNATED FOR SPECIFIC USE Spare Tanks (3) 2.28 Mgal Complexed Waste 3.97 Mgal (AN-102, AN-106, AN-107, SY-101, (1 Aging & 1 Non-Aging Waste Tank) SY-103, (AY-101, AP-108 (DC)) 0.67 Mgal Watch List Tank Space 1.09 Mgal (AN-103, AN-104, AN-105, AW-101, SY-101, SY-103) Concentrated Phosphate Waste (AP-102) Double-Shell Slurry and Slurry Feed 4.4 Mgal Segregated Tank Space 3.23 Moal (AN-102, AN-106, AN-107, AP-102, AP-108, AY-101 (AN-103, AN-104, AN-105, AP-101, AZ-101, AZ-102) AW-101, AW-106) Aging Waste (NCAW) at 5M Na 1.23 Mgail Receiver/Operational Tank Space (2) 3.06 Mgai Dilute in Aging Tanks 0,37 Mgai (AN-101, AP-106, AW-102, AW-106, SY-102) (AZ-101, AZ-102) 3.64 Mgat Dilute Waste (1) (AN-101, AP-103, AP-105, AP-104, AP-106, AP-107, 9.23 Hoal Total Specific Use Space (11/30/98) AW-102, AW-103, AW-104, AW-105, AY-102, SY-102) TOTAL DOUBLE-SHELL TANK SPACE 4.04 Mgal NCRW, PFP and DST Settled Solids 24 Tanks at 1140 Kgai 27.36 Mgal (All DSTs) 4 Tanks at 980 Kgal 3.92 Mgal 31.28 Maa! Total Inventory= 18.74 Mgal Total Available Space 31.28 Mgal Double-Stiell Tank Inventory 18.74 Mgal Space Designated for Specific Use 9.23 Mgal

Remaining Unallocated Space

Note: Net change in total DST inventory since last month: +0.069 Mgal

**WVPTOT** 

3.31 Mgal

<sup>(1)</sup> Was reduced in volume by -0.00 Mgal this month (Evaporator WVR)

<sup>(2)</sup> Tank Space Reduced by Facility Generations and Saltwell Liquid pumping

<sup>(3) 241-</sup>AY-101: A minumum liquid level is set to provide extra protection against any bottom uplifting of the tank's steel liner. Because of space availability, waste is stored in AY-102, the aging waste spare tank. In case of a leak the contents of AY-102 will be distributed to any other DST(s) having available space.

Table B-2. Double Shell Tank Waste Inventory for November 30, 1998

AN-103=

TANKS	INVENTORY	SOLIDS	TYPE	LEFT
AN-101=	158	33	DN	982
AN-102=	1065	89	CC	75
AN-103=	958	410	DSS	182
AN-104=	1054	449	DSSF	86
AN-105=	1128	489	DSSF	12
AN-106=	39	17	CC	1101
AN-107=	1047	247	CC	93
AP-101=	1115	0	DSSF	25
AP-102=	1093	0	CP	47
AP-103=	24	1	DN	1116
AP-104=	24	0	DN	1116
AP-105=	767	89	DSSF	373
AP-106=	389	0	DN	751
AP-107=	23	0	DN	1117
AP-108=	254	0	DC	886
AW-101=	1125	306	DSSF	15
AW-102=	590	40	DN	550
AW-103=	512	347	NCRW	628
AW-104=	1119	231	DN	21
AW-105=	433	280	NCRW	707
AW-106=	580	228	CC	560
AY-101=	168	108	DC	812
AY-102#	467	30	DN	513
AZ-101=	849	47	NCAW	131
AZ-102=	900	104	NCAW	80
SY-101=	1165	41	CC	-25
SY-102*	953	88	DN/PT	187
SY-103=	745	362	CC	395
TOTAL=	18744	4036		12536

NOTE: Solids Adjusted to Most Current.	vailable Data
NOTE: All Volumes In Kilo-Gallons (Kga	s)

TOTAL DST SPACE	AVAILABLE	DST INVENTOR	CHANGE
NON-AGING =	27360	10/98 TOTAL	1867
AGING =	3920	11/98 TOTAL	1874
TOTAL	31280	RNCREASE	

182

AN-104=	86
AN-105=	12
AW-101=	15
SY-101=	-25
SY-103=	395
TOTALE	- 668
SEGREGATED SPACE	E (DC,CC,CP,AW)
AN-102=	75
	4404
AN-106=	1101
AN-106= AN-107=	1101 <b>93</b>
AN-107=	93
AN-107= AP-102=	93 47
AN-107= AP-102= AP-108=	93 47 886
AN-107= AP-102= AP-108= AY-101=	93 47 886 812

WATCH LIST SPACE

WASTE RECEIVER SPACE				
AN-101 (200E/DC)=	982			
AP-106 (200E/DN)=	751			
SY-102 (200W/DN)=	187			
TOTALE CONTRACTOR	1920			

USABLE SPACE	
AP-101=	25
AP-103=	1116
AP-104=	1116
AP-105=	373
AP-107 <del>=</del>	1117
AW-102=	550
AW-103=	628
AW-104=	21
AW-105=	707
AW-106=	560
AY-102=	513
TOTALE	6728
EVAP. OPERATIONS	-1140

-2280

USABLE SPACE CHANGE	Ē
10/98 TOTAL SPACE	3314
11/98 TOTAL SPACE	3306

SPARE SPACE

USABLE LEFTS

WASTE RECEIVER SPACE	CHANGE
10/98 TOTAL SPACE	1961
11/98 TOTAL SPACE	1920
CHANGE	41

### **Inventory Calculation by Waste Type:**

COMP	PLEXED WASTE
AN-102=	976 (CC)
AN-106=	22 (CC)
AN-107≖	800 (CC)
AP-108=	254 (DC)
AW-106=	352 (CC)
AY-101=	60 (DC)
SY-101=	1124 (CC)
SY-103=	383 (CC)
TOTAL DC/CC=	2974
TOTAL SOLIDS#	1092

NCRW SOLIDS (PD)		
AW-103=	347	
AW-105=	280	
TOTAL=		

	PFP SOLIDS (PT)
SY-102=	88
TOTAL=	

C	ONCENTRATED PHOSPHATE (CP)
102-AP=	1093
TOTAL	

DILUTE WAS	TE (DN)
AN-101=	125
AP-103=	23
AP-104=	24
AP-106=	389
AP-107=	23
AW-102=	550
AW-103=	165
AW-104=	888
AW-105=	153
AY-102=	437
SY-102=	865
TOTAL ONE	3642
TOTAL SOLIDS=	336

ASTE)			
(@ 5M Na)			
791			
434			
122			
273			
48			

DSS/I	SSF
AN-103=	548
AN-104=	605
AN-105=	639
AP-101=	1115
AP-105=	678
AW-101=	819
TOTAL DSS/DSSF=	4484
TOTAL SOLIDS=	1743

GRAND TOTA	LS
NCRW SOLIDS=	627
DST SOLIDS=	3170
PFP SOLIDS=	88
AGING SOLIDS=	151
cc <del>-</del>	3657
DC=	314
CP*	1093
NCAW=	1598
DSS/DSSF=	4404
DILUTE=	3642
TOTAL	18744

NOTE: Tank AW-106 (evaporator receiver) has Concentrated Complexed (CC) waste in it and will be transferred to Tank 106-AN. inv1198

Table B-2. Double Shell Tank Waste Inventory for November 30, 1998

TOTAL AVAILABLE SPA	CE AS OF	NOVEMBER 30, 1998:	# 12882	KGAL
VATCH LIST TANK SPACE:	TANK	WASTE TYPE	AVAILABLE	SPAC
nusable DST Headspace - Due to Special Restrictions	AN-103	DSS	182	KGAL
laced on the Tanks, as Stated in the "Wyden Bill"	AN-104	DSSF	86	KGAL
	AN-105	DSSF	12	KGAL
	AW-101	DSSF	15	KGAL
	SY-101	CC	-25	KGAL
	SY-103	CC	Pharmonic recommendation	KGAL KGAL
		AVAILABLE TANK SPACE=		KGAL
	gerterateriana, a 2006, Mari	NUS WATCH LIST SPACE:	and the contraction of a left against	KGAL
TOTAL AVAILABLE SPACE AFT	ER WATCH L	IST SPACE DEDUCTIONS	12017	KGAL
EGREGATED TANK SPACE:	TANK	WASTE TYPE	AVAILABLE	SPAC
T Headspace Available to Store Only Specific Waste Type	AN-102	CC	75	KGAL
	AN-106	CC	1101	KGAL
	AN-107	CC	93	KGAL
	AP-102	CP	47	KGAL
	AP-108	DC	886	KGAL
	AY-101	DC	812	KGAL
	AZ-101	AW	131	KGAL
	AZ-102	AW	e data da militara mengana pada da di di meran	KGAL
			<u> </u>	KGAL
AVAILABLE SPA	CE AFTER	WATCH LIST DEDUCTIONS	S= 12017	KGAL
	MINI	US SEGREGATED SPACE=	-3225	KGAL
TOTAL AVAILABLE SPACE AFTE	R SEGREGA	TED SPACE DEDUCTIONS	e 8792	KGAL
SABLEWASTE RECEIVER TANK SPACE:	TANK	WASTE TYPE	AVAILABLE	SPACI
T Headepace Available to Store Facility Generated	AN-101	DN	982	KGAL:
d Evaporator Product Waste	AP-101	DSSF	25	KGAL
	AP-103	DN	1116	KGAL
	AP-104	DN	1116	KGAL:
	AP-105	DSSF	373	KGAL
FACILITY WASTE RECEIVER TANK	AP-106	DN	751	KGAL:
	AP-107	DN	1117	KGAL:
EVAPORATOR FEED TANK	AW-102	DN	550	KGAL:
	AW-103	NCRW	628	KGAL
	AW-104	DN		KGAL
	AW-105	NCRW	707	KGAL
EVAPORATOR RECEIVER TANK	AW-106	CC		KGAL
	AY-102	DN		KGAL
FACILITY WASTE RECEIVER TANK	SY-102 ULAVAILABI	DN LE USABLE TANK SPACE	BARGES BULL COTO COLLECTO PA	KGAL:
APORATOR OPERATIONAL TANK SPACE	<u> </u>	-	-1140	KGALS
PARE TANK SPACE: (DOE Order 5820,2A)			-2280	




FIGURE B-1. TOTAL DOUBLE-SHELL TANK INVENTORY

This page intentionally left blank

## APPENDIX C

# TANK AND EQUIPMENT CODE AND STATUS DEFINITIONS

#### C. TANK AND EQUIPMENT CODE/STATUS DEFINITIONS

November 30, 1998

#### 1. TANK STATUS CODES

#### WASTE TYPE (also see definitions, section 3)

AGING Aging Waste (Neutralized Current Acid Waste [NCAW]) CC Complexant Concentrate Waste CP Concentrated Phosphate Waste DC Dilute Complexed Waste DN Dilute Non-Complexed Waste Double-Shell Slurry DSS DSSF Double-Shell Slurry Feed NCPLX Non-Complexed Waste Plutonium-Uranium Extraction (PUREX) Neutralized Cladding PD/PN

Removal Waste (NCRW), transuranic waste (TRU)

PT Plutonium Finishing Plant (PFP) TRU Solids

#### TANK USE (DOUBLE-SHELL TANKS ONLY)

**CWHT** Concentrated Waste Holding Tank DRCVR Dilute Receiver Tank

Evaporate Feed Tank **EVFD** SRCVR Slurry Receiver Tank

#### 2 SOLID AND LIQUID VOLUME DETERMINATION METHODS

F Food Instrument Company (FIC) Automatic Surface Level Gauge

ENRAF Surface Level Gauge (being installed to replace FICs) E

Manual Tape Surface Level Gauge M

Photo Evaluation

Sludge Level Measurement Device S

#### 3. **DEFINITIONS**

#### **WASTE TANKS - GENERAL**

#### Waste Tank Safety Issue

A potentially unsafe condition in the handling of waste material in underground storage tanks that requires corrective action to reduce or eliminate the unsafe condition.

#### Watch List Tank

An underground storage tank containing waste that requires special safety precautions because it may have a serious potential for release of high level radioactive waste because of uncontrolled increases in temperature or pressure. Special restrictions have been placed on these tanks by "Safety Measures for Waste Tanks at Hanford Nuclear Reservation," Section 3137 of the National Defense Authorization Act for Fiscal Year 1991. November 5, 1990, Public Law 101-510, (also known as the Wyden Amendment).

#### Characterization

Characterization is understanding the Hanford tank waste chemical, physical, and radiological properties to the extent necessary to insure safe storage and interim operation, and ultimate disposition of the waste.

#### WASTE TYPES

#### Aging Waste (AGING)

High level, first cycle solvent extraction waste from the PUREX plant (NCAW)

#### Concentrated Complexant (CC)

Concentrated product from the evaporation of dilute complexed waste.

#### Concentrated Phosphate Waste (CP)

Waste originating from the decontamination of the N Reactor in the 100 N Area. Concentration of this waste produces concentrated phosphate waste.

#### Dilute Complexed Waste (DC)

Characterized by a high content of organic carbon including organic complexants: ethylenediaminetetra-acetic acid (EDTA), citric acid, and hydroxyethyl-ethylenediaminetriacetic acid (HEDTA), being the major complexants used. Main sources of DC waste in the DST system are saltwell liquid inventory (from SSTs).

#### Dilute Non-Complexed Waste (DN)

Low activity liquid waste originating from T and S Plants, the 300 and 400 Areas, PUREX facility (decladding supernatant and miscellaneous wastes), 100 N Area (sulfate waste), B Plant, saltwells, and PFP (supernate).

#### Double-Shell Slurry (DSS)

Waste that exceeds the sodium aluminate saturation boundary in the evaporator without exceeding receiver tank composition limits. For reporting purposes, DSS is considered a solid.

#### Double-Shell Slurry Feed (DSSF)

Waste concentrated just before reaching the sodium aluminate saturation boundary in the evaporator without exceeding receiver tank composition limits. This form is not as concentrated as DSS.

#### Non-complexed (NCPLX)

General waste term applied to all Hanford Site (NCPLX) liquors not identified as complexed.

#### PUREX Decladding (PD)

PUREX Neutralized Cladding Removal Waste (NCRW) is the solids portion of the PUREX plant neutralized cladding removal waste stream; received in Tank Farms as a slurry. NCRW solids are classified as transuranic (TRU) waste.

#### PFP TRU Solids (PT)

TRU solids fraction from PFP Plant operations.

#### Drainable Interstitial Liquid (DIL)

Interstitial liquid that is not held in place by capillary forces, and will therefore migrate or move by gravity. (See also Section 4)

#### Supernate

The liquid above the solids in waste storage tanks. (See also Section 4)

#### Ferrocyanide

A compound of iron and cyanide commonly expressed as FeCN. The actual formula for the ferrocyanide anion is [Fe(CN)<sub>6</sub>]<sup>-4</sup>.

#### INTERIM STABILIZATION (Single-Shell Tanks only)

#### Interim Stabilized (IS)

A tank which contains less than 50 Kgallons of drainable interstitial liquid and less than 5 Kgallons of supernatant liquid. If the tank was jet pumped to achieve interim stabilization, then the jet pump flow must also have been at or below 0.05 gpm before interim stabilization criteria is met.

#### Jet Pump

The jet pump system includes 1) a jet assembly with foot valve mounted to the base of two pipes that extend from the top of the well to near the bottom of the well casing inside the saltwell screen, 2) a centrifugal pump to supply power fluid to the down-hole jet assembly, 3) flexible or rigid transfer jumpers, 4) a flush line, and 5) a flowmeter. The jumpers contain piping, valves, and pressure and limit switches.

The centrifugal pump and jet assembly are needed to pump the interstitial liquid from the saltwell screen into the pump pit, nominally a 40-foot elevation rise. The power fluid passes through a nozzle in the jet assembly and acts to convert fluid pressure head to velocity head, thereby reducing the pressure in the jet assembly chamber. The reduction in pressure allows the interstitial liquid to enter the jet assembly chamber and mix with the power fluid. Velocity head is converted to pressure head above the nozzle, lifting power fluid, and interstitial liquid to the pump pit. Pumping rates vary from 0.05 gallons to about 4 gpm.

#### Saltwell Screen

The saltwell system is a 10-inch diameter saltwell casing consisting of a stainless steel saltwell screen welded to a Schedule 40 carbon steel pipe. The casing and screen are to be inserted into the 12-inch tank riser located in the pump pit. The stainless steel screen portion of the system will extend through the tank waste to near the bottom of the tank. The saltwell screen portion of the casing is an approximately 10-foot length of 300 Series, 10-inch diameter, stainless steel pipe with screen openings (slots) of 0.05 inches.

#### **Emergency Pumping Trailer**

A 45-foot tractor-type trailer is equipped to provide storage space and service facilities for emergency pumping equipment: this consists of two dedicated jet pump jumpers and two jet pumps, piping and dip tubes for each, two submersible pumps and attached piping, and a skid-mounted Weight Factor Instrument Enclosure (WFIE) with an air compressor and electronic recording instruments. The skid also contains a power control station for the pumps, pump pit leak detection, and instrumentation. A rack for over 100 feet of overground double-contained piping is also in the trailer.

#### INTRUSION PREVENTION (ISOLATION) Single-Shell Tanks only

#### Partially Interim Isolated (PI)

The administrative designation reflecting the completion of the physical effort required for Interim Isolation except for isolation of risers and piping that is required for jet pumping or for other methods of stabilization.

#### Interim Isolated (II)

The administrative designation reflecting the completion of the physical effort required to minimize the addition of liquids into an inactive storage tank, process vault, sump, catch tank, or diversion box. In June 1993, Interim Isolation was replaced by Intrusion Prevention.

#### Intrusion Prevention (IP)

Intrusion Prevention is the administrative designation reflecting the completion of the physical effort required to minimize the addition of liquids into an inactive storage tank, process vault, sump, catch tank, or diversion box. Under no circumstances are electrical or instrumentation devices disconnected or disabled during the intrusion prevention process (with the exception of the electrical pump).

#### Controlled, Clean, and Stable (CCS)

Controlled, Clean, and Stable reflects the completion of several objectives: "Controlled" - provide remote monitoring for required instrumentation and implement controls required in the TWRS Authorization Basis; "Clean" - remove surface soil contamination and downpost the Tank Farms to RBA/URMA/RA radiological control status, remove abandoned equipment, and place reusuable equipment in compliant storage; and "Stable" - remove pumpable liquids from the SSTs and IMUSTs and isolate the tanks.

#### TANK INTEGRITY

#### Sound

The integrity classification of a waste storage tank for which surveillance data indicate no loss of liquid attributed to a breach of integrity.

#### Assumed Leaker

The integrity classification of a waste storage tank for which surveillance data indicate a loss of liquid attributed to a breach of integrity.

#### Assumed Re-Leaker

A condition that exists after a tank has been declared as an "assumed leaker" and then the surveillance data indicates a <u>new</u> loss of liquid attributed to a breach of integrity.

#### TANK INVESTIGATION

#### Intrusion

A term used to describe the infiltration of liquid into a waste tank.

#### SURVEILLANCE INSTRUMENTATION

#### Drywells

Drywells are vertical boreholes with 6-inch (internal diameter) carbon steel casings positioned radially around SSTs. These wells range between 50 and 250 feet in depth, and are monitored between the range of 50 to 150 feet. The wells are sealed when not in use. They are called drywells because they do not penetrate to the water table and are therefore usually "dry." There are 759 drywells.

Monitoring is done by gamma radiation or neutron-moisture sensors to obtain scan profiles of radiation or moisture in the soil as a function of well depth, which could be indicative of tank leakage.

Two single-shell tanks (C-105 and C-106) are currently monitored monthly by gamma radiation sensors. The remaining drywells are monitored on request by gamma radiation sensors. Monitoring by neutron-moisture sensors is done only on request.

#### Laterals

Laterals are horizontal drywells positioned under single-shell waste storage tanks to detect radionuclides in the soil which could be indicative of tank leakage. These drywells can be monitored by radiation detection probes. Laterals are 4-inch inside diameter steel pipes located 8 to 10 feet below the tank's concrete base. There are three laterals per tank. Laterals are located only in A and SX farms. There are currently no functioning laterals and no plan to prepare them for use.

#### Surface Levels

The surface level measurements in all waste storage tanks are monitored by manual or automatic conductivity probes, and recorded and transmitted or entered into the Computer Automated Surveillance System (CASS).

#### **Automatic FIC**

An automatic waste surface level measurement device is manufactured by the Food Instrument Company (FIC). The instrument consists of a conductivity electrode (plummet) connected to a calibrated steel tape, a steel tape

reel housing and a controller that automatically raises and lowers the plummet to obtain a waste surface level reading. The controller can provide a digital display of the data and also transmit the reading to the CASS. Some tanks have gauges connected to CASS and others are read manually. FICs are being replaced by ENRAF detectors (see below).

#### **ENRAF 854 ATG Level Detector**

FICs and some manual tapes are in the process of being replaced by the ENRAF ATG 854 level detector. The ENRAF gauge, fabricated by ENRAF Incorporated, determines waste level by detecting variations in the weight of a displacer suspended in the tank waste. The displacer is connected to a wire wound onto a precision measuring drum. A level causes a change in the weight of the displacer which will be detected by the force transducer. Electronics within the gauge causes the servo motor to adjust the position of the displacer and compute the tank level based on the new position of the displacer drum. The gauge displays the level in decimal inches. The first few ENRAFs that received remote reading capability transmit liquid level data via analog output to the Tank Monitor and Control System (TMACS). The remaining ENRAFs and future installations will transmit digital level data to TMACS via an ENRAF Computer Interface Unit (CIU). The CIU allows fully remote communication with the gauge, minimizing tank farm entry.

#### **Annulus**

The annulus is the space between the inner and outer shells on DSTs only. Drain channels in the insulating and/or supporting concrete carry any leakage to the annulus space where conductivity probes are installed. Alarms from the annunciators are received by CASS. Continuous Air Monitoring (CAM) alarms are also located in the annulus. The annulus conductivity probes and radiation detectors are the primary means of leak detection for all DSTs.

#### Liquid Observation Well (LOW)

In-tank liquid observation wells are used for monitoring the interstitial liquid level (ILL) in single-shell waste storage tanks. The wells are usually constructed of fiberglass or TEFZEL-reinforced epoxy-polyester resin (TEFZEL, a trademark of E. I. du Pont de Nemours & Company). There are a few LOWs constructed of steel. LOWs are sized to extend to within 1 inch of the bottom of the waste tank, are sealed at their bottom ends and have a nominal outside diameter of 3.5 inches. Two probes are used to monitor changes in the ILL; gamma and neutron, which can indicate intrusions or leakage by increases or decreases in the ILL. There are 65 LOWs (64 are in operation) installed in SSTs that contain or are capable of containing greater than 50 Kgallons of drainable interstitial liquid, and in two DSTs only. The LOWs installed in two DSTs, (SY-102 and AW-103 tanks), are used for special, rather than routine, surveillance purposes only.

#### Thermocouple (TC)

A thermocouple is a thermocouple on a device (probe) is called a thermocouple tree. In DSTs there may be one or more thermocouple trees in risers in the primary tank. In addition, in DSTs only, there are thermocouple elements installed in the insulating concrete, the lower primary tank knuckle, the secondary tank concrete foundation, and in the outer structural concrete.

These monitor temperature gradients within the concrete walls, bottom of the tank, and the domes. In SSTs, one or more thermocouples may be installed directly in a tank, although some SSTs do not have any trees installed. A single thermocouple (probe) may be installed in a riser, or lowered down an existing riser or LOW. There are also four thermocouple laterals beneath Tank 105-A in which temperature readings are taken in 34 thermocouples.

#### In-tank Photographs and Videos

In-tank photographs and videos may be taken to aid in resolving in-tank measurement anomalies and determine tank integrity. Photographs and videos help determine sludge and liquid levels by visual examination.

#### TERMS/ACRONYMS

<u>CASS</u> Computer Automated Surveillance System

CCS Controlled, Clean and Stable (tank farms)

II Interim Isolated

IP Intrusion Prevention Completed

IS Interim Stabilized

MT/FIC/ENRAF Manual Tape, Food Instrument Corporation, ENRAF Corporation (surface level measurement devices)

OSD Operating Specifications Document

PI Partial Interim Isolated

SAR Safety Analysis Reports

SHMS Standard Hydrogen Monitoring System

<u>TMACS</u> Tank Monitor and Control System

TPA Hanford Federal Facility Consent and Compliance Order, "Washington State Department of Ecology,

U. S. Environmental Protection Agency, and U. S. Department of Energy," Fourth Amendment, 1994

(Tri-Party Agreement)

USQ Unreviewed Safety Question

Wyden Amendment "Safety Measures for Waste Tanks at Hanford Nuclear Reservation," Section 3137 of the National Defense Authorization Act for Fiscal Year 1991, November 5, 1990, Public Law 101-510.

## 4. <u>INVENTORY AND STATUS BY TANK - VOLUME CALCULATIONS AND DEFINITIONS FOR TABLE E-6 (SINGLE-SHELL TANKS)</u>


COLUMN HEADING	VOLUME CALCULATIONS/DEFINITIONS
Total Waste	Solids volume plus Supernatant liquid. Solids include sludge and saltcake (see definitions below)
Supernate Liquid	Drainable Liquid Remaining minus Drainable Interstitial. Supernate is the clear liquid floating on the surface of the waste. Supernate is usually derived by subtracting the solids level measurement from the liquid level measurement. In some cases, the supernatant volume includes floating solid crusts because their volume cannot be measured. In-tank photographs or videos are useful in estimating the liquid volumes; the area of solids covered and the average depth can be estimated.
Drainable Interstitial Liquid	Drainable Liquid Remaining minus Supernate. Drainable interstitial liquid is calculated based on the saltcake and sludge volumes, using average porosity values or actual data for each tank, when available. Interstitial liquid is liquid that fills the interstitial spaces of the solids waste. Drainable interstitial liquid is calculated based on the saltcake and sludge volumes in the tank. The sum of the interstitial liquid contained in saltcake and sludge is the initial volume of drainable interstitial liquid. The volume reported as Drainable Interstitial

#### HNF-EP-0182-128

COLUMN HEADING	VOLUME CALCULATIONS/DEFINITIONS
	Liquid is the initial volume of drainable interstitial liquid minus interstitial liquid removed by pumping.
Pumped This Month	Net total gallons of liquid pumped from the tank during the month. If supernate is present, pump production is first subtracted from the supernatant volume. The remainder is then subtracted from the drainable interstitial liquid volume. The total pumped volume is subtracted from drainable liquid remaining and pumpable liquid remaining. Pump production takes into account the amount of water added to the tank during the month (if any).
Total Pumped	Cumulative net total gallons of liquid pump from 1979 to date.
Drainable Liquid Remaining	Supernate plus Drainable Interstitial. (See Supernatant Liquid and Drainable Interstitial Liquid above for definitions). The total Drainable Liquid Remaining is the sum of drainable interstitial liquid and supernate minus total gallons pumped.
Pumpable Liquid Remaining	Drainable Liquid Remaining minus undrainable heel volume. (Dish bottom tanks have a "heel" where liquids can collect: flat bottom tanks do not). (See Drainable Liquid Remaining and Pumped this Month for definitions). Not all drainable interstitial liquid is pumpable. It is assumed that drainable interstitial liquid on top of the undrainable heel in sludge or saltcake, is not jet pumpable. Therefore, pumpable interstitial liquid is the initial volume of drainable interstitial liquid minus the amount of interstitial liquid on top of the heel. The volume shown as Pumpable Liquid Remaining is the sum of pumpable interstitial liquid and supernate minus total gallons pumped.
Sludge	Solids formed during sodium hydroxide additions to waste. Sludge usually was in the form of suspended solids when the waste was originally received in the tank from the waste generator. In-tank photographs or videos may be used to estimate the volume.
Saltcake	Results from crystallization and precipitation after concentration of liquid waste, usually in an evaporator. If saltcake is layered over sludge, it is only possible to measure total solids volume. In-tank photographs or videos may be used to estimate the saltcake volume.
Solids Volume Update	Indicates the latest update of any change in the solids volume.
Solids Update Source - See Footnote	Indicates the source or basis of the latest solids volume update.
Last In-tank Photo	Date of last in-tank photographs taken.
Last In-tank Video	Date of last in-tank video taken.
See Footnotes for These Changes	Indicates any change made the previous month. A footnote explanation for the change follows the Inventory and Status by Tank section (Table E-6).

## APPENDIX D

# TANK FARM CONFIGURATION, STATUS, AND FACILITY CHARTS



HNF-EP-0182

FIGURE D-1. HIGH-LEVEL WASTE TANK CONFIGURATION




FIGURE D-2. DOUBLE-SHELL TANK INSTRUMENTATION CONFIGURATION




FIGURE D-3. SINGLE-SHELL TANK INSTRUMENTATION CONFIGURATION

# THE HANFORD TANK FARM FACILITY CHARTS (colored foldouts) ARE ONLY BEING INCLUDED IN THIS REPORT ON A QUARTERLY BASIS (i. e., months ending March 31, June 30, September 30, December 31)

NOTE: COPIES OF THE FACILITY CHARTS CAN BE OBTAINED FROM
DENNIS BRUNSON, MULTI-MEDIA SERVICES,

375-6820, K1-03

ALMOST ANY SIZE IS AVAILABLE, AND CAN BE LAMINATED.

CACN/COA required

This page intentionally left blank

### APPENDIX E

MONTHLY SUMMARY
TANK USE SUMMARY
PUMPING RECORD, LIQUID STATUS AND PUMPABLE
LIQUID REMAINING IN TANK FARMS
INVENTORY SUMMARY BY TANK FARM
INVENTORY AND STATUS BY TANK

## Ŧ

# TABLE E-1. MONTHLY SUMMARY TANK STATUS

	200	200	
	EAST AREA	WEST AREA	TOTAL
IN SERVICE	25	03	28 (1)
OUT OF SERVICE	66	83	149
SOUND	59	51	110
ASSUMED LEAKER	32	35	67
INTERIM STABILIZED	60	59	119 (2)
ISOLATED			
PARTIAL INTERIM	11	30	41
INTRUSION PREVENTION COMPLETE	<b>5</b> 5	53	108
CONTROLLED, CLEAN, AND STABLE	12	24	36_

		WASTE VOI	_UMES (Kgallo	ns)			
		200	200		SST	DST	
		EAST AREA	<b>WEST AREA</b>	TOTAL	TANKS	TANKS	TOTAL
SUPERNA	<u>ATANT</u>						
AGING	Aging waste	1598	0	1598	0	1598	1598
CC	Complexent concentrate waste	2153	1503	3656	3	3653	3656
CP	Concentrated phosphate waste	1093	0	1093	0	1093	1093
DC	Dilute complexed waste	865	1	866	2	864	866
DN	Dilute non-complexed waste	1917	0	1917	0	1917	1917
DN/PD	Dilute non-complex/PUREX TRU solid	343	0	343	0	343	343
DN/PT	Dilute non-complex/PFP TRU solids	0	865	865	0	865	865
NCPLX	Non-complexed waste	207	277	484	484	0	484
DSSF	Double-shell slurry feed	4413	48	4461	57	4404	4461
TOTAL	. SUPERNATANT	12589	2694	15283	546	14737	15283
SOLIDS		a contra a marco de aban o montrar a bosto de Calendario de Calendario de Calendario de Calendario de Calendario		entropped and a property of the state of the	est regis our handwise tour control Herodal Color Color	Manager A. Committee of the committee of	
Double	e-shell slurry	410	0	410	0	410	410
Sludge	, '	9147	6212	15359	11841	3518	15359
Saitcai	ke	6265	16740	23005	22926	79	23005
TOTA	L SOLIDS	15822	22952	38774	34767	4007	38774
TO:	TAL WASTE	28411	25646	54057	35313	18744	54057 i
AVAILAE	BLE SPACE IN TANKS	11979	582	12561	0	12561	12561
DRAINAE	BLE INTERSTITIAL	2229	4615	6844	6565	27 <del>9</del>	6844
DRAINAE	BLE LIQUID REMAINING	14819	7296	22115	7099	15016	22115

<sup>(1)</sup> Includes six double-shell tanks on Hydrogen Watch List not currently allowed to receive waste, AN-103, AN-104, AN-105, AW-101, SY-101, and SY-103.

<sup>(2)</sup> Includes one tank (B-202) which does not meet current established supernatent and interstitial liquid stabilization criteria.

#### TABLE E-2. TANK USE SUMMARY

					ISOLATED TAI		_	
TANK F <u>ARMS</u>	TANKS RECEIVING WASTE TRANSERS	SOUND	ASSUMED LEAKER	PARTIAL INTERIM	INTRUSION PREVENTION COMPLETED	CONTROLLED CLEAN, AND <u>STABLE</u>	INTERIM TABILIZED TANKS	
EAST								
A	0	3	3	2	4	0	5	
AN	7 (1)	7	0	0	0		0	
AP	8	8	0	0	0		0	
AW	6 (1)	6	0	0	0		0	
AX	0	2	2	1	3		3	
AY	2	2	0	0	0		0	
ΑZ	2	2	0	0	0		0	
В	0	6	10	0	16		16	(2)
BX	0	7	5	0	12	12	12	
BY	0	7	5	5	7		10	
C	0	9	7	3	13		14	
Total	****	59	32		<b></b>		60	
Access to the distribution of		1.1		10	2			
5	0	11	1	10	2		4	
S SX	0	5	10	6	9		9	
S SX SY	0 3 (1)	5 3	10 0	6 0	9 0		9	
S SX SY T	0 3 (1) 0	5 3 9	10 0 7	6 0 5	9 0 11	19	9 0 14	
S SX SY T	0 3 (1) 0 0	5 3	10 0 7 8	6 0 5 0	9 0 11 18	18	9 0 14 18	
WEST S S S Y T T T X T U U	0 3 (1) 0	5 3 9	10 0 7	6 0 5	9 0 11	18 6	9 0 14	

<sup>(1)</sup> Six Double-Shell Tanks on the Hydrogen Tank Watch List are not currently receiving waste transfers (AN-103, 104, 105, AW-101, SY-101 and 103).

<sup>(2)</sup> Includes tank B-202 which no longer meets established supernatant interstitial liquid stabilization criteria.

# TABLE E-3. PUMPING RECORD, LIQUID STATUS AND PUMPABLE LIQUID REMAINING IN TANK FARMS

			Waste Ve	olumes (Kgallons)			
TANK FARMS E <b>AST</b>	PUMPED I	PUMPED FY TO DATE	CUMULATIVE TOTAL PUMPED 1979 TO DATE	SUPERNATANT LIQUID	DRAINABLE INTERSTITIAL REMAINING	DRAINABLE LIQUID REMAINING	PUMPABLE LIQUID REMAINING
A	0.0	0.0	150.5	9	492	501	441
AN	N/A	N/A	N/A	3715	127	3842	N/A
AP	N/A	N/A	N/A	3599	3	3602	N/A
AW	N/A	N/A	N/A	2952	139	3091	N/A
AX	0.0	0.0	13.0	3	409	412	344
ΑY	N/A	N/A	N/A	505	5	510	N/A
ΑZ	N/A	N/A	N/A	1598	5	1603	N/A
В	0.0	0.0	0.0	15	164	179	80
ВХ	N/A	0.0	200.2	21	107	129	N/A
BY	0.0	0.0	1567.8	0	588	588	431
С	0.0	0.0	103.0	172	190	362	272
Total 🦭	0.0	0.0	2034.5	17589	2229	14819	1568
WEST							
S	0.0	0.0	853.6	71	1303	1361	1138
SX	16.1	32.0	170.2	51	1462	1513	1388
SY	N/A	N/A	N/A	2368	0	2368	N/A
T	6.8	16.1	225.6	28	212	240	176
TX	N/A	0.0	1205.7	5	250	255	N/A
TY	N/A	0.0	29.9	3	31	34	N/A
U	0.0	0.0	0.0	168	1357	1525	1377
	22.9	484	<b>1</b> 2485.0	والمراجع والم	4615	7298	4079

<sup>(1)</sup> Volume based on 21% (sludge waste) and 50% (saltcake waste) liquid in solid (porosity) value, per WHC-SD-W236A-ES-012, Rev .1, dated May 21, 1996, a re-evaluation of the non-stabilized tanks.

N/A = Not applicable for Double-Shell Tank Farms, and Single-Shell Tank Farms which have been declared Controlled, Clean and Stable (BX, TX, TY).

# TABLE E-4. INVENTORY SUMMARY BY TANK FARM November 30, 1998

					SUPERIV.	AIANI	LIUUIL	, VUL	UMES	(Kgallo	ns)			SOLID	S VOLUM	1E
TANK	TOTAL	AVAIL						, <u></u>			<del></del>				SALT	
FARM	WASTE	SPACE	AGING	CC	CP	DC	DN	DN/PD	DN/PT	DSSE	NCPLX	TOTAL	DSS	SLUDGE	_CAKE	TOTAL
ENST																
A	1537	0	0	0	0	0	0	0	0	9	0	9	0	556	972	1528
AN	5449	2531	0	1798	0	0	125	0	0	1792	0	3715	410	1324	0	1734
AP	3689	5431	0	0	1093	254	459	0	0	1793	0	3599	0	90	0	90
AW	4359	2481	0	352	0	550	888	343	0	819	0	2952	0	1332	75	1407
AX	906	0	0	3	0	0	0	0	0	0	0	3	0	19	884	903
AY	835	1325	0	0	0	60	445	0	0	0	0	505	0	130	0	130
AZ	1749	211	1598	0	0	0	0	0	0	0	0	1598	0	151	0	151
В	2057	0	0	0	0	0	0	0	0	0	15	15	0	1697	345	2042
вх	1493	0	0	0	0	0	0	0	0	o	21	21	o	1351	121	1472
BY	4561	0	0	0	0	0	0	0	0	0	0	0	0	693	3868	4561
С	1976	0	0	0	0	1	0	0	0	0	171	172	0	1804	0	1804
Total	28411	11979	1598	2153	1093	865	1917	343		4413	207	12589	410	9147	8285	15822
The Control of the Co																
WEST																
S	5300	0	0	0	0	0	0	0	0	17	54	71	o	1166	4063	5229
SX	4407	0	0	0	0	1	0	0	0	0	50	51	0	1254	3102	4356
SY	2863	582	0	1503	0	0	0	0	865	0	0	2368	0	491	4	495
T	1879	0	0	0	0	0	0	0	0	0	28	28	0	1851	0	1851
TX	7009	0	0	0	0	0	0	0	0	0	5	5	o	241	6763	7004
ΓY	638	0	0	0	0	0	0	0	0	0	3	3	o	571	64	635
J	3550	o	0	0	0	0	0	0	0	31	137	168	o	638	2744	3382
		lenska mili <b>4 k</b> e			a la <b>u</b> nida		465							: Shidsourna		
otal	25646	582	0	1503	0	1	. 0	O.	865	48	277	2694	0	6212	16740	22952
TOTAL	54057	12561	1598	3656	1093	866	1917	249	865	4481	484	15283	410	15359	23005	38774

HNF-EP-0182-128

TABLE E-5. INVENTORY AND STATUS BY TANK - DOUBLE SHELL TANKS

		TANK S	STATUS					LIQU	JID VOLUN	AE	S	OLIDS VOL	UME	VOLU	ME DETERN	INATION	PHOTOS/	VIDEOS	
				EQUIVA-	TOTAL	ANAH	SUPER-	DRAIN- ABLE INTER-	DRAIN- ABLE LIQUID	PUMP- ABLE LIQUID				LIQUID	SOLIDS	SOLIDS	LAST	LAST	SEE FOOTNOT FOR
	WAST	TANK	TANK	WASTE	WASTE		LIQUID	STIT.	REMAIN	REMAIN	DSS	SLUDGE	CALT		VOLUME	VOLUME	IN-TANK	IN-TANK	THESE
TANK		INTEGRITY		INCHES	(Kgal)	(Kgai)	(Kgai)	(Kgal)	(Kgal)	(Kgal)	(Kgal)	SLODGE		-	METHOD	UPDATE	PHOTO	VIDEO	CHANGE
		-		_															
									<u>an Tani</u>		TATUS	i		1		1	Ī		ī
AN-101		SOUND	DRCVR	57.6	158	982	125	0	1 25	1 25	)	33	0	FM	S	04/30/96	1		Ì
AN-102		SOUND	CWHT	387.3	1065	75	976	3	979	976	0	89	0	FM	S	08/22/89	0/0/0		
AN-103		SOUND	CWHT	348.4	958	182	548	0	548	548	410	0	0	FM	S	03/31/97	10/29/87		l
AN-104		SOUND	CWHT	383.3	1054	86	605	48	653	631	0	449	0	FM	S	03/31/97	08/19/88		
AN-105		SOUND	CWHT	410.2	1128	12	639	53	692	670	i °	489	0	FM	S	03/31/97	01/26/88		į.
AN-106		SOUND	CWHT	14.2	39	1101	22	0	22	22	º	17	0	FM	S	08/22/89	0/ 0/ 0		
AN-107	CC	SOUND	CWHT	380.7	1047	93	800	23	823	801	l °	247	0	FM	S	08/22/89	09/01/88		
7 DOUB	LE-SHEL	L TANKS		TOTALS	5449	2531	3715	127	3842	3773	410	1324	0						
																	···		
									AP TANI	K FARM	STATUS	<u> </u>					•		1
AP-101		SOUND	DRCVR	405.5	1115	25	1115	0	1115	1115	0	0	0	FM	S	05/01/89	0/0/0		
AP-102		SOUND	GRTFD	397.5	1093	47	1093	0	1093	1093	0	0	0	FM	S	07/11/89	0/0/0		
AP-103		SOUND	DRCVR	8.7	24	1116	23	0	23	23	0	1	0	FM	S	05/31/96	0/ 0/ 0		
AP-104		SOUND	GRTFD	8.7	24	1116	24	0	24	24	0	0	0	FM	S	10/13/88	0/0/0		1
AP-105		SOUND	CWHT	278.9	767	373	678	3	681	678	0	69	0	FM	S	03/31/98	1	09/27/99	5 (a)
AP-106		SOUND	DRCVR	141.5	389	751	389	0	389	389	0	0	0	FM	S	10/13/88	0/0/0		
AP-107		SOUND	DRCVR	8.4	23	1117	23	0	23	23	0	0	0	FM	S	10/13/88	0/ 0/ 0		
AP-108	DC	SOUND	DRCVR	92.4	254	886	254	0	254	254		0	0	FM	S	10/13/88	0/ 0/ 0		
8 DOUB	LE-SHEL	L TANKS		TOTALS	3689	5431	3599	3	3602	3599	0	90	0		<del></del>				
				<u>_</u>			<u>.                                  </u>					_							<u> </u>
AW-101	Deel	SOUND	CWHT	409.1	1125	15	819	30	<u>AW_TAN</u> 849	K FARM 827	1	-	_	1	s	03/31/97	03/17/88		ı
AW-101		SOUND	EVFD	214.5	590	550	550	30 0	550		٥		0	FM	S	08/31/97			l
AW-102 AW-103			DRCVR	186.2	512	628			200	550	°	40	0	FM	s S		02/02/83		<b> </b> (
AW-103 AW-104		SOUND	DRCVR	406.9	1119		165 888	35 30	918	178	°	347	76	FM	s S	03/31/98	-		(a)
AW-105		· · · · · · · · · · · · · · · · · · ·	DRCVR	157.5	433	21 707				896	° ا		76	FM		03/31/98			(a)
AW-106		SOUND	SRCVR	210.9	433 580	560	178 352	24 20	202 372	160 362	0	255 228	0	FM FM	S S	03/31/98 08/31/97	0/ 0/ 0		(a)
																			1
6 DOUBL	LE-SHEL	L TANKS		TOTALS	4359	2481	2952	139	3091	2983	0	1332	75						<u> </u>

## 7

### TABLE E-5. INVENTORY AND STATUS BY TANK - DOUBLE SHELL TANKS

November 30, 1998

		TANK S	STATUS					LIQU	ID VOLU	AE .		SOLIDS V	OLUME	VOL	UME DETE	RMINATION	PHOTO	S/VIDEOS	
								DRAIN-	DRAIN-	PUMP-							7,1,5		SEE
				EQUIVA-			SUPER-	ABLE	ABLE	ABLE									FOOTNO'
				LENT	TOTAL		NATANT	INTER-	LIQUID	LIQUID				rianid	SOLIDS	SOLIDS	LAST	LAST	FOR
<b>TANK</b>	WAST		TANK	WASTE	WASTE	SPACE	LIQUID	STIT.	REMAIN	REMAIN	DSS	SLUDGE			VOLUME	VOLUME	IN-TANK	IN-TANK	THESE
ANK	MAIL	INTEGRITY	USE	INCHES	(Kgal)	(Kgal)	(Kgal)	(Kgal)	(Kgal)	(Kgal)	(Kgal)		CAKE	METHOD	METHOD	UPDATE	PHOTO	VIDEO	CHANGE
								A	Y TANK	FARM ST	TATUS								
Y-101	DC	SOUND	DRCVR	61.1	168	812	60	5	<b>6</b> 5	60	0	108	0	l FM	s	10/31/97	12/28/82		I .
Y-102	DN	SOUND	DRCVR	169.8	467	513	445	0	445	445	0	22	0	FM	S		04/28/81		ŀ
										- 1, -			•	''''	·	10,01,07	04/20/01		
DOUBL	LE-SHELL	TANKS		TOTALS	635	1325	505	5	510	505	0	130	0						<del>†                                      </del>
											-	<del></del>			•				<u> </u>
								A	<u>Z TANK</u>	FARM ST	ATUS								
	AGING	<del>-</del>	CWHT	308.7	849	131	802	0	802	802	0	47	0	FM	s	10/31/97	08/18/83		
Z-102	AGING	SOUND	DRCVR	327.3	900	80	796	5	801	796	0	104	0	FM	s	10/31/97	10/24/84		
DOUBL	E-SHELL	TANKS		TOTALS	1749	211	1598	5	1603	1598	0	151	0						
		······································					1000		1000	1330		191	-						<u> </u>
								<u>S</u>	Y TANK	FARM ST	ATUS								
Y-101	CC	SOUND	CWHT	423.6	1165	0	1124	0	1124	1124	0	41	0	FM	s	05/31/98	04/12/89		<b>I</b> (ь)
Y-102	DN/PT	SOUND	DRCVR	346.5	953	187	865	0	865	865	o	88	o	FM	s		04/29/81		(a)
Y-103	CC	SOUND	CWHT	270.9	745	<b>39</b> 5	379	0	379	379	0	362	4	FM	S	06/30/96			'"'
DOLLDI	F 011544	74147															<u>.                                    </u>		
DOOBL	E-SHELL	IANKS		TOTALS	2863	582	2368	0	2368	2368	0	491	4						
RAND 1	TOTAL				18744	12561	14737	279	15016	14826	410	2510			<del>_</del> .				<u> </u>
					10/44	12301	14/3/	2/9	12010	14826	410	3518	79						1

Note: +/- 1 Kgal differences are the result of computer rounding

Available Space Calculations

Used in This Document

IOSR WHC-SD-WM-OSR-16 (AN, AP, AW, SY)

AN, AP, AW, SY

(Most Conservative)

WHC-T-151-00009 (Aging Waste)

AY, AZ (Aging Waste)

1,140,000 gal (414,5 in.) 980,000 gal (356,4 in.) 1,144,000 gal (416 in.)(AN, AP, SY) 1,127,500 (410 in.)(AW-Farm)

1,000,000 gai (363.6 in.)(AY, AZ)

NOTE: Tanks AN-102, AN-107, AY-101, AY-102, AP-103, AP-104, AP-107 - These tanks currently contain waste that is outside of the current corrosion control specification. An alternate strategy of corrosion control (monitor using corrosion probes; adjust chemistry as required for control) is being proposed but has not been fully evaluated. Note that the supernate in AY-102 is within the corrosion specifications, however, the sludge layer is outside the specifications.

(a) Solids levels in tanks AP-105, AW-104, AW-105, and SY-102 were adjusted based on document HNF-SD-WM-TI-806, "Safety Control Optimization by Performance Evaluation-Analysis Tool (SCOPE-AT) Pedigree Database for Hanford Tanks," which will soon be released.

(b) Tank SY-101 - Total Waste exceeds the "most conservative" Available Space calculations used for these tanks, but does not exceed the OSR requirements

## TABLE E-6. INVENTORY AND STATUS BY TANK - SINGLE-SHELL TANKS

November 30, 1998

	TANK	STATUS					LIC	UID VOLU	ME		SOLIDS	VOLUME	VOLUM	DETERMIN	IATION	PHOTOS/	VIDEOS	[
			STABIL/	TOTAL	SUPER- NATE	DRAIN- ABLE INTER-	PUMPED THIS	TOTAL	DRAIN- ABLE LIQUID	PUMP- ABLE LIQUID		SALT	LIQUIDS	SOLIDS	SOLIDS	LAST	LAST	SEE FOOTNOTE FOR
TANK	WASTE MAT'L	TANK INTEGRITY	ISOLATION STATUS		LIQUID (Kgal)	STIT. (Kgal)	MONTH (Kgai)	PUMPED (Kgal)	REMAIN (Kgal)	REMAIN (Kgal)	SLUDGE (Kgal)	CAKE (Kgal)	VOLUME METHOD	VOLUME METHOD	VOLUME UPDATE	IN-TANK PHOTO	IN-TANK VIDEO	THESE CHANGES
								A TAI	NK FARM	<u>STATUS</u>								
A-101		SOUND	/PI	953	0	464	0.0	0.0	464	441	3	950	P	F	11/21/80	08/21/85		1
A-102		SOUND	IS/PI	41	4	2	0.0	39.5	6	0	15	22	P	FP	07/27/89	07/20/89		
A-103		ASMD LKR	IS/IP	371	5	15	0.0	111.0	20	0	366	0		FP	06/03/88	12/28/88		ļ
A-104		ASMD LKR	IS/IP	28	0	0	0.0	0.0	0	0	28	0	М	PS	01/27/78	06/25/86		]
A-105		ASMD LKR	IS/IP	19	0	4	0.0	0.0	4	0	19	0	P	MP	08/23/79	08/20/86		
A-106	CP	SOUND	IS/IP	1 25	0	7	0.0	0.0	7	0	125	0	Р	М	09/07/82	08/19/86		
6 SIN	GLE-SHELL	TANKS	TOTALS	1537	9	492	0.0	150.5	501	441	556	972						
								AX TA	NK FARM	STATUS								
	11 DSSF	SOUND	/PI	748	0	359	0.0	0.0	359	338	] з	745	l p	F	07/16/97	08/18/87		1
AX-10	2 CC	ASMD LKR	IS/IP	39	3	14	0.0	13.0	17	3	7	29	F	S	09/06/88	06/05/89		ļ
AX-10	3 CC	SOUND	tS/IP	112	0	36	0.0	0.0	36	3	2	110	F	S	08/19/87	08/13/87		
AX-10	M NCPLX	ASMD LKR	IS/IP	7	0	0	0.0	0.0	0	0	7	0	Р	М	04/28/82	08/18/87		
4 SINC	3LE-SHELL	TANKS	TOTALS:	906	3	409	0.0	13.0	412	344	19	884						
								B TAN	K FARM	STATUS								
B-101	NCPLX	ASMD LKR	IS/IP	113	0	6	0.0	0.0	6	0	113	0	l p	F	04/28/82	06/19/83		1
B-102	NCPLX	SOUND	IS/IP	32	4	0	0.0	0.0	4	0	18	10	P	F	08/22/85	08/22/85		ŀ
B-103	NCPLX	ASMD LKR	IS/IP	59	0	0	0.0	0.0	0	0	59	0	F	F	02/28/86	10/13/88		]
B-104	NCPLX	SOUND	IS/IP	371	1	46	0.0	0.0	47	40	301	69	М	M	06/30/85	10/13/88		
B-105	NCPLX	ASMD LKR	IS/IP	306	0	23	0.0	0.0	23	0	40	266	P	MP	12/27/84	05/19/88		
B-106	NCPLX	SOUND	IS/IP	117	1	6	0.0	0.0	7	0	116	0	F	F	03/31/85	02/28/85		
B-107	NCPLX	ASMD LKR	IS/IP	165	1	12	0.0	0.0	13	7	164	ō	м	м	03/31/85	02/28/86		
B-108	NCPLX	SOUND	IS/IP	94	0	4	0.0	0.0	4	o	94	0	F	F	05/31/85	05/10/85		ļ
B-109	NCPLX	SOUND	IS/IP	127	o	8	0.0	0.0	8	o	127	ō	м	, M	04/06/85	04/02/85		
B-110	NCPLX	ASMD LKR	IS/IP	246	1	22	0.0	0.0	23	17	245	o	MP	MP	02/28/85	03/17/88		
B-111	NCPLX	ASMD LKR	IS/IP	237	1	21	0.0	0.0	22	16	236	o	F	F	06/28/86	06/26/85		
B-112	NCPLX	ASMD LKR	IS/IP	33	3	0	0.0	0.0	3	0	30	o	F.	F	05/31/85	05/29/85		!
B-201	NCPLX	ASMD LKR	IS/IP	29	1	3	0.0	0.0	4	o	28	ō	M	M	04/28/82	11/12/86	08/23/95	i
B-202	NCPLX	SOUND	IS/IP	27	0	3	0.0	0.0	3	o	27	o	P.	M	05/31/85	05/29/85		
B-203	NCPLX	ASMD LKR	IS/IP	51	1	5	0.0	0.0	6	o	50	o	PM	PM	05/31/84	11/13/86	20110190	
B-204	NCPLX	ASMD LKR	IS/IP	50	1	5	0.0	0.0	6	0	49	o	P	M	05/31/84	10/22/87		
	GLE-SHELL	TANKS	TOTALS	2057	16	164												I

## TABLE E-6. INVENTORY AND STATUS BY TANK - SINGLE-SHELL TANKS

November 30, 1998

	NCPLX NCPLX NCPLX NCPLX	TANK INTEGRITY  ASMD LKR ASMD LKR SOUND	STABIL/ ISOLATION STATUS IS/IP/CCS IS/IP/CCS	WASTE	SUPER- NATE (Kg al)	DRAIN- ABLE INTER- STIT. (Kgal)	PUMPED THIS MONTH	TOTAL PUMPED	DRAIN- ABLE LIQUID	PUMP- ABLE LIQUID								SEE FOOTNOTE
BX-101 N BX-102 N BX-103 N BX-104 N BX-106 N BX-106 N BX-107 N BX-108 N BX-109 N BX-110 N BX-111 N BX-111 N	MAT'L.  NCPLX NCPLX NCPLX NCPLX NCPLX	ASMD LKR	ISOLATION STATUS	WASTE (Kgal)	NATE	STIT.	MONTH			LIQUID	l							
BX-101 N BX-102 N BX-103 N BX-104 N BX-106 N BX-106 N BX-107 N BX-108 N BX-109 N BX-110 N BX-111 N BX-111 N	MAT'L.  NCPLX NCPLX NCPLX NCPLX NCPLX	ASMD LKR	STATUS	(Kgal)				PUMPED	DCB4A MI		<b>!</b>	SALT	LIQUIDS	SOLIDS	SOLIDS	LAST	LAST	FOR
BX-101 N BX-102 N BX-103 N BX-104 N BX-106 N BX-107 N BX-108 N BX-109 N BX-110 N BX-111 N BX-111 N	NCPLX NCPLX NCPLX NCPLX NCPLX	ASMD LKR ASMD LKR	IS/IP/CCS		(Kgal)	(Kgal)	(Kash		REMAIN	REMAIN	SLUDGE	CAKE	VOLUME	VOLUME	VOLUME	IN-TANK	IN-TANK	THESE
BX-102 N BX-103 N BX-104 N BX-106 N BX-106 N BX-107 N BX-108 N BX-109 N BX-110 N BX-111 N BX-111 N	NCPLX NCPLX NCPLX NCPLX	ASMD LKR		43			(cell an)	(Kgal)	(Kgal)	(Kgal)	(Kgal)	(Kgal)	METHOD	METHOD	UPDATE	PHOTO	VIDEO	CHANGES
BX-102 N BX-103 N BX-104 N BX-106 N BX-106 N BX-107 N BX-108 N BX-109 N BX-110 N BX-111 N BX-111 N	NCPLX NCPLX NCPLX NCPLX	ASMD LKR		4.3				RX TA	NK FARM	STATUS								
BX-103 N BX-104 N BX-106 N BX-106 N BX-107 N BX-108 N BX-109 N BX-110 N BX-111 N BX-112 N	NCPLX NCPLX NCPLX		IS/IP/CCS		1 1	0	0.0	0.0	1	0	42	0	l P	м	04/28/82	11/24/88	11/10/94	μ
BX-104 N BX-106 N BX-106 N BX-107 N BX-108 N BX-109 N BX-110 N BX-111 N BX-112 N	NCPLX NCPLX	SOUND		96	6	4	0.0	0.0	4	0	96	o	P	м		09/18/85	•	
BX-106 N BX-106 N BX-107 N BX-108 N BX-109 N BX-110 N BX-111 N BX-112 N	NCPLX		IS/IP/CCS	68	6	0	0.0	0.0	6	0	62	0	P	F	11/29/83	10/31/86	10/27/94	ı
BX-106 N BX-107 N BX-108 N BX-109 N BX-110 N BX-111 N BX-112 N	— .	SOUND	IS/IP/CCS	99	3	30	0.0	17.4	33	27	96	0	F	F	09/22/89	09/21/89		
BX-107 N BX-108 N BX-109 N BX-110 N BX-111 N BX-112 N	NON V	SOUND	IS/IP/CCS	51	5	6	0.0	15.0	11	4	43	3	F	s	09/03/86	10/23/86		
BX-108 N BX-109 N BX-110 N BX-111 N BX-112 N	NUPLA	SOUND	IS/IP/CCS	38	0	0	0.0	14.0	0	0	38	0	MP	PS	08/01/95	05/19/68	07/17/95	٠ -
BX-109 N BX-110 N BX-111 N BX-112 N	NCPLX	SOUND	IS/IP/CCS	345	1 1	29	0.0	23.1	30	23	344	0	MP	Р	09/18/90	09/11/90		
BX-110 N BX-111 N BX-112 N	NCPLX	ASMD LKR	IS/IP/CCS	26	0	1	0.0	0.0	1	0	26	0	M	PS	07/31/79	05/05/94		
BX-111 N BX-112 N	NCPLX	SOUND	IS/IP/CCS	193	0	13	0.0	8.2	13	8	193	0	FP	Р	09/17/90	09/11/90		}
BX-112 N	NCPLX	ASMD LKR	IS/IP/CCS	207	3	16	0.0	1.5	19	13	195	9	MP	M	10/31/94	07/15/94	10/13/94	ı
<u></u>	NCPLX	ASMD LKR	IS/IP/CCS	162	1	1	0.0	116.9	3	1	52	109	М	M	04/06/95	05/19/94	02/28/95	š
12 SINGLE	NCPLX	SOUND	IS/IP/CCS	165	1	7	0.0	4.1	8	2	164	0	FP	P	09/17/90	09/11/90		
	E-SHELL	TANKS	TOTALS:	1493	21	107	0.0	200.2	1 29	78	1351	121						<del> </del>
		<u>-</u>						DV TA	NK FARM	CTATIC		-						
BY-101 N	NCPI X	SOUND	IS/IP	387	1 0	5	0.0	35.8	5	O SIAIUS	109	278	i p	м	05/30/84	09/19/89		1
BY-102 N		SOUND	IS/PI	277	١	11	0.0	159.0	11	o	هٔ ا	277	MP	М		09/11/87		<u>.</u> i
BY-103 N		ASMD LKR	IS/PI	414	١ ŏ	38	0.0	95.9	38	32	5	409	MP	M		09/07/89		1
	NCPLX	SOUND	IS/IP	406	0	18	0.0	329.5	18	0	40	366	 Р	м		04/27/83		
BY-105 N	NCPLX	ASMD LKR	/PI	503	ا	228	0.0	0.0	228	216	44	459	l 'n	MP		07/01/86		
BY-106 N	NCPLX	ASMD LKR	/PI	642	هٔ	200	0.0	63.7	200	163	95	547	P	MP		11/04/82		1
BY-107 N	NCPLX	ASMD LKR	IS/IP	266	0	25	0.0	56.4	25	0	60	206	٩	MP		10/15/86		1
BY-108 N		ASMD LKR	IS/IP	228	0	9	0.0	27.5	9	ō	154	74	МР	M		10/15/86		
BY-109 N		SOUND	IS/PI	290	0	37	0.0	157.1	37	20	57	233	F	PS		06/18/97		
BY-110 N	NCPLX	SOUND	IS/IP	398	0	9	0.0	213.3	9	0	103	295	м	s		07/26/84		1
BY-111 N	NCPLX	SOUND	IS/IP	459	0	0	0.0	313.2	0	o	21	438	P	M		10/31/86		
BY-112 N	NCPLX	SOUND	IS/IP	291	0	8	0.0	116.4	8	0	5	286	Р	М		04/14/88		
12 SINGLE		TA NUCO	TOTALS:	4561	-	588	0.0	1567.8					L					<b>↓</b>

9

TABLE E-6. INVENTORY AND STATUS BY TANK - SINGLE-SHELL TANKS

	TANK :	STATUS			L		LIQ	UID VOLU	ME		SOLIDS	VOLUME	<u> </u>	VOLUM	E DETERMIN	IATION		
			. ,			DRAIN-		<u> </u>	DRAIN-	PUMP-								SEE
					1	ABLE	PUMPED		ABLE	ABLE	1		1					FOOTNOTE
			STABIL/	TOTAL	SUPER-	INTER-	THIS	TOTAL	LIQUID	LIQUID		SALT	LIQUIDS	SOLIDS	SOLIDS	LAST	LAST	FOR
	WASTE	TANK	ISOLATION	WASTE	NATE	STIT.	MONTH	PUMPED	REMAIN	REMAIN	SLUDGE	CAKE	VOLUME	VOLUME	VOLUME	IN-TANK	IN-TANK	THESE
TANK	MAT'L.	INTEGRITY	STATUS	(Kgal)	(Kgal)	(Kgal)	(Kgal)	(Kgal)	(Kgal)	(Kgal)	(Kgai)	(Kgal)	METHOD	METHOD	UPDATE	PHOTO	VIDEO	CHANGES
								C TA	NK FARM	STATUS								
C-101	NCPLX	ASMD LKR	IS/IP	88	0	3	0.0	0.0	3	_ 0	88	0	м	M	11/29/83	11/17/87		
C-102	DC	SOUND	IS/IP	316	0	30	0.0	46.7	30	17	316	0	F	FP	09/30/95	05/18/76	08/24/95	5
C-103	NCPLX	SOUND	/PI	195	133	2	0.0	0.0	135	133	62	0	] F	s	10/20/90	07/28/87		
C-104	CC	SOUND	IS/IP	295	0	11	0.0	0.0	11	5	295	0	FP	P	09/22/89	07/25/90		
C-105	NCPLX	SOUND	IS/PI	134	2	30	0.0	0.0	32	9	132	0	F	s	10/31/95	08/05/94	08/30/95	5
C-106	NCPLX	SOUND	/PI	229	32	30	0.0	0.0	62	52	197	0	F	PS	04/28/82	06/05/94	08/08/94	ıl .
C-107	DC	SOUND	IS/IP	237	0	24	0.0	40.8	24	15	237	o	F	s	09/30/95	00/00/00		
C-108	NCPLX	SOUND	IS/IP	66	0	0	0.0	0.0	0	0	66	0	М	S	02/24/84	12/05/74	11/17/94	ı
C-109	NCPLX	SOUND	IS/IP	66	4	0	0.0	0.0	4	0	62	0	М	PS	11/29/83	01/30/76		ì
C-110	DC	ASMD LKR	IS/IP	178	1	28	0.0	15.5	29	15	177	0	F	FMP	06/14/95	08/12/86	05/23/95	<sub>5</sub>
C-111	NCPLX	ASMD LKR	IS/IP	57	0	0	0.0	0.0	0	0	57	0	м	S	04/28/82	02/25/70	02/02/95	5
C-112	NCPLX	SOUND	IS/IP	104	0	32	0.0	0.0	32	26	104	0	м	PS	09/18/90	09/18/90		1
C-201	NCPLX	ASMD LKR	IS/IP	2	0	0	0.0	0.0	0	0	2	0	P	MP	03/31/82	12/02/86		
C-202	<b>EMPTY</b>	ASMD LKR	IS/IP	1	0	0	0.0	0.0	0	0	1	0	P	М	01/19/79	12/09/86		1
C-203	NCPLX	ASMD LKR	IS/IP	5	0	0	0.0	0.0	0	0	l 5	0	l p	MP	04/28/82	12/09/86		1
C-204	NCPLX	ASMD LKR	IS/IP	3	0	0	0.0	0.0	0	0	3	o	Р	MP	04/28/82	12/09/86		1
I & SIN	GLE-SHELL	TANKS	TOTALS:	1976	172	190	0.0	103.0	362	272	1804	0	<del></del>			<u></u>		<del> </del>
10 0	OLL OILEL	IARKS	TOTALS.	1970	1/2	130	0.0	7			1 1004		<u> </u>			L		
S-101	NCPLX	SOUND	/PI	427	12	126	0.0	<u>S TA</u> 0.0	<u>NK FARM</u> 1 <b>38</b>	STATUS 127	244	171	ĺF	PS	09/16/90	03/18/88		1
S-102	DSSF	SOUND	/PI	549	0	262	0.0	0.0	262		4	545	P	FP	04/28/82	1		1
S-103	DSSF	SOUND	/PI	248	17	101	0.0	0.0	118	239 97	1		I '	S	11/20/80			
S-104	NCPLX	ASMD LKR	IS/IP	294	';	28	0.0	0.0	29		10	221	М	M		12/12/84		
S-105	NCPLX	SOUND	IS/IP	456		35	0.0	114.3	29 35	23 13	293	0	M	S	12/20/84	04/12/89		
S-106	NCPLX	SOUND	/PI	479	4	186	• • • •			•	2	454	MP			1	00/4 0/0	.)
S-107	NCPLX	SOUND	/FI /PI	376	14	85	0.0	97.0 0.0	190 99	168	28	447	P	FP	12/31/93	I	09/12/94	*
-108	NCPLX	SOUND	IS/PI	450	'•	4		-		88	293	69	F	PS	09/25/80	03/12/87	3 9 /00 /04	
-109	NCPLX	SOUND	15/F1 /Pl	568		141	0.0	199.8	4	110	4	446	P	MP	12/20/96		12/03/96	ή
-110	NCPLX	SOUND	IS/PI	390	0		0.0	111.0	141	119	13	555	) F	PS PC	09/30/75	1	49/44/04	اء
-111	NCPLX	SOUND				30 195	0.0	203.1	30 20E	23	131	259	F	PS ED	05/14/92	1	12/11/90	"]
-112	NCPLX	SOUND	/P1 /P1	540 523	23	195 110	0.0 0.0	3.3 1 <i>2</i> 5.1	205 110	134 107	139	378 518	P	FP FP	06/30/97 1 2/31/93	08/10/89 03/24/87		
															, _ ,			
2 SIN	3LE-SHELL	TANKS	TOTALS:	5300	71	1303	0.0	853.6	1361	1138	1166	4063				1		]

E-10

TABLE E-6. INVENTORY AND STATUS BY TANK - SINGLE-SHELL TANKS

	TANK S	TATUS					LIQ	UID VOLU	ME		SOLIDS	VOLUME	<u> </u>	VOLUM	E DETERMIN	ATION		
		<u>.</u>				DRAIN- ABLE	PUMPED		DRAIN- ABLE	PUMP- ABLE								SEE FOOTNOTI
			STABIL/	TOTAL	SUPER-	INTER-	THIS	TOTAL	LIQUID	LIQUID		SALT	LIQUIDS	SOLIDS	SOLIDS	LAST	LAST	FOR
	WASTE	TANK	ISOLATION	WASTE	NATE	STIT.	MONTH	PUMPED	REMAIN	REMAIN	SLUDGE	CAKE	VOLUME	VOLUME	VOLUME	IN-TANK	IN-TANK	THESE
ANK	MAT'L.	INTEGRITY	STATUS	(Kgal)	(Kgal)	(Kgal)	(Kgal)	(Kgal)	(Kgal)	(Kgal)	(Kgal)	(Kgal)	METHOD	METHOD	UPDATE	PHOTO	VIDEO	CHANGES
								SX TAI	NK FARM	STATUS								
X-101	DC	SOUND	/PI	456	,	184	0.0	0.0	185	174	112	343	l P	FP	04/28/82	03/10/89		1
X-102	DSSF	SOUND	/PI	543	0	226	0.0	0.0	226	216	117	428	P	M	04/28/82	01/07/88		
X-103	NCPLX	SOUND	/Pt	652	1	281	0.0	0.0	282	272	115	536	F	s	07/15/91	12/17/87		1
X-104	DSSF	ASMD LKR	/PI	614	0	156	14.2	158.5	156	150	136	478	F	S	07/07/89	09/08/88	02/04/98	(a)
X-105	DSSF	SOUND	/PI	683	0	309	0.0	0.0	309	299	73	610	P	F	04/28/82	06/15/88		Į.
X-106	NCPLX	SOUND	/PI	526	49	224	1.9	11.7	273	252	12	465	F	PS	11/30/98	06/01/89		(b)
X-107	NCPLX	ASMD LKR	IS/IP	104	0	5	0.0	0.0	5	0	104	0	P	M	04/26/82	03/06/87		
X-108	NCPLX	ASMD LKR	IS/IP	87	0	5	0.0	0.0	5	0	87	0	P	M	12/31/93	03/06/87		
X-109	NCPLX	ASMD LKR	IS/IP	244	0	48	0.0	0.0	48	25	0	244	P	M	01/10/96	05/21/86		
X-110	NCPLX	ASMD LKR	IS/IP	62	0	0	0.0	0.0	0	0	62	0	M	PS	10/06/76	02/20/87		]
X-111	NCPLX	ASMD LKR	IS/IP	125	0	7	0.0	0.0	7	0	125	0	M	PS	06/31/74	06/09/94		
X-112	NCPLX	ASMD LKR	IS/IP	92	0	3	0.0	0.0	3	0	92	0	Р	M	04/28/82	03/10/87		
X-113	NCPLX	ASMD LKR	IS/IP	26	0	0	0.0	0.0	0	0	26	0	Р	M	04/28/82	03/18/88		
X-114	NCPLX	ASMD LKR	IS/IP	181	0	14	0.0	0.0	14	0	181	0	P	M	04/28/82	02/26/87		1
X-115	NCPLX	ASMD LKR	IS/IP	12	0	0	0.0	0.0	0	0	12	0	P	М	04/28/82	03/31/88		
5 SING	BLE-SHELL	TANKS	TOTALS:	4407	51	1462	16.1	170.2	1513	1388	1 254	3102		<del></del>				
					_			T TAN	K FARM	CTATUS								
-101	NCPLX	ASMD LKR	IS/PI	102	l 1	16	0.0	25.3	17	0	1 101	0	lε	s	04/14/93	04/07/93		1
-102	NCPLX	SOUND	IS/IP	32	13	0	0.0	0.0	13	13	19	o		FP	08/31/84			
-103	NCPLX	ASMD LKR	IS/IP	27	4	0	0.0	0.0	4	0	23	o	1 '	FP	11/29/83	1		
-104	NCPLX	SOUND	/PI	332	0	48	3.2	142.6	48	45	332	ō	1	MP	11/30/98			(c)
-105	NCPLX	SOUND	IS/IP	98	0	23	0.0	0.0	23	17	98	0	٩	F	05/29/87			
106	NCPLX	ASMD LKR	IS/IP	21	2	0	0.0	0.0	2	0	19	o	P	FP	04/28/82			
-107	NCPLX	ASMD LKR	IS/Pt	173	0	22	0.0	11.0	22	12	173	o	P	FP	05/31/96	ı	05/09/96	3
-108	NCPLX	ASMD LKR	IS/IP	44	0	0	0.0	0.0	0	0	44	0	P	M		07/17/84	20,22,00	ì

<u>-</u>

TABLE E-6. INVENTORY AND STATUS BY TANK - SINGLE-SHELL TANKS

	TANK S	TATUS					LIQ	UID VOLU	ME		SOLIDS	VOLUME	VOLUI	VE DETERM	INATION			
						DRAIN-	·		DRAIN-	PUMP-								SEE
					ł	ABLE	PUMPED		ABLE	ABLE	1		<b>\</b>					FOOTNOT
			STABIL/	TOTAL	SUPER-	INTER-	THIS	TOTAL	LIQUID	LIQUID		SALT	LIQUIDS	SOLIDS	SOLIDS	LAST	LAST	FOR
	WASTE	TANK	ISOLATION	WASTE	NATE	STIT.	MONTH	PUMPED	REMAIN	REMAIN	SLUDGE	CAKE	VOLUME	VOLUME	VOLUME	IN-TANK	IN-TANK	THESE
TANK	MAT'L.	INTEGRITY	STATUS	(Kgal)	(Kgal)	(Kgal)	(Kgal)	(Kgal)	(Kgal)	(Kgal)	(Kgal)	(Kgal)	METHOD	METHOD	UPDATE	PHOTO	VIDEO	CHANGES
r-109	NCPLX	ASMD LKR	IS/IP	58	l o	0	0.0	0,0	0	0	58	o	М	M	12/30/84	02/25/93		I
T-110	NCPLX	SOUND	/PI	356	0	56	3.6	37.1	5 <b>6</b>	53	356	0		FP	1130/98	I '		(d)
T-111	NCPLX	ASMD LKR	IS/PI	-	٥	34		_						FP	•		02/42/0E	
T-112	NCPLX		-	446	`		0.0	9.6	34	29	446	0	\		04/18/94	1	02/13/90	` <b>\</b>
T-201		SOUND	IS/IP	67	7	0	0.0	0.0	7	7	60	0	"	FP	04/28/82			
	NCPLX	SOUND	IS/IP	29	!	3	0.0	0.0	4	0	28	0	M	PS	05/31/78			
T-202	NCPLX	SOUND	IS/IP	21	0	2	0.0	0.0	2	0	21	0	FP	P	07/12/81	1		
T-203	NCPLX	SOUND	IS/IP	35	0	4	0.0	0.0	4	0	35	0	М	PS	01/31/78	•		1
T-204	NCPLX	SOUND	IS/IP	38	0	4	0.0	0.0	4	0	38	0	FP	P	07/22/81	08/03/89		
6 SIN	GLE-SHELL	TANKS	TOTALS:	1879	28	212	6.8	225.6	240	176	1851	0						
								TX TA	<u>NK FARM</u>	STATUS								
TX-101	NCPLX	SOUND	IS/IP/CCS	87	3	2	0.0	0.0	5	0	84	0	F	P	02/02/84	10/24/85		1
TX-102	NCPLX	SOUND	IS/IP/CCS	217	0	22	0.0	94.4	22	0	0	217	М	8	08/31/84	10/31/85		
TX-103	NCPLX	SOUND	IS/IP/CCS	157	0	15	0.0	68.3	15	0	157	0	F	S	08/14/80	10/31/85		1
TX-104	NCPLX	SOUND	IS/IP/CCS	65	1	14	0.0	3.6	15	0	0	64	F	FP	04/06/84	10/16/84		
TX-105	NCPLX	ASMD LKR	IS/IP/CCS	609	0	20	0.0	121.5	20	0	0	609	м	PS	08/22/77	10/24/89		
TX-106	NCPLX	SOUND	IS/IP/CCS	453	0	10	0.0	134.6	10	0	0	453	м	S	08/29/77	10/31/85		
TX-107	NCPLX	ASMD LKR	IS/IP/CCS	36	1	1	0.0	0.0	2	0	) 0	35	FP	FP	01/20/84	10/31/85		1
TX-108	NCPLX	SOUND	IS/IP/CCS	134	0	0	0.0	13.7	0	0	0	134	P	FP	05/30/B3	09/12/89		
TX-109	NCPLX	SOUND	IS/IP/CCS	384	0	10	0.0	72.3	10	0	0	384	F	PS	05/30/83	10/24/89		
TX-110	NCPLX	ASMD LKR	IS/IP/CCS	462	l o	15	0.0	115.1	15	0	ہ ا	462	М	PS	05/30/83			
	NCPLX	SOUND	IS/IP/CCS	370	0	9	0.0	98.4	9	0	ه ا	370	м	PS	07/26/77	1		1
	NCPLX	SOUND	IS/IP/CCS	649	0	24	0.0	94.0	24	0	٥	649	""	PS	05/30/83	I '		
	NCPLX	ASMD LKR	IS/IP/CCS	607	ő	16	0.0	19.2	16	0	0	607	l i	PS	05/30/83	1	09/23/94	d
	NCPLX	ASMD LKR	IS/IP/CCS	53 <b>5</b>	0	15	0.0	104.3	15	0	Ĭ	535	M	PS	05/30/83	1	03/23/3	
	NCPLX	ASMD LKR	IS/IP/CCS	640	0	19		99.1	19		0		1		03/25/83	1		Ί
	NCPLX	-			_		0.0			0	_	640	M	\$ ~~				
		ASMD LKR	IS/IP/CCS	631	0	23	0.0	23.8	23	0	0	631	M	PS	03/31/72	ł		
	NCPLX NCPLX	ASMD LKR SOUND	IS/IP/CCS IS/IP/CCS	62 <del>6</del> 347	0	8 27	0.0 0.0	54.3 89.1	8 27	0	0	626 347	M F	PS S	12/31/71 11/17/80	I		1
							5.0					J+1	_ '					<u></u>
8 SIN	GLE-SHELL	TANKS	TOTALS:	7009	5	250	0.0	1205.7	255	0	241	6763						

-12

TABLE E-6. INVENTORY AND STATUS BY TANK - SINGLE-SHELL TANKS
November 30, 1998

	TANK S	STATUS					LIQ	UID VOLU	ME		SOLIDS	VOLUM	VOLUM	E DETERMIN	NATION	PHOTOS/	VIDEOS	
			STABIL/	TOTAL	SUPER-	DRAIN- ABLE INTER-	PUMPED THIS	TOTAL	DRAIN- ABLE LIQUID	PUMP- ABLE LIQUID		SALT	LIQUIDS	SOLIDS	SOLIDS			SEE FOOTNOTE
	WASTE	TANK	ISOLATION	WASTE	1	STIT.	MONTH	PUMPED	REMAIN		SLUDGE	_	VOLUME	VOLUME	VOLUME	LAST IN-TANK	LAST IN-TANK	FOR THESE
TANK	MAT'L.	INTEGRITY	STATUS	(Kgal)	(Kgal)	(Kgal)		(Kgal)	(Kgal)	(Kgal)	(Kgal)	(Kgal)	METHOD	METHOD	UPDATE	PHOTO		CHANGES
							-											
Y-101	NCPLX	ASMD LKR	IS/IP/CCS	118	1 0	0	0.0		NK FARM		٠	_	i _			1		
Y-102	NCPLX	SOUND	IS/IP/CCS	64	١ ٥	14	0.0	8.2	0	0	118	0	₽ _	F	04/28/82			1
Y-103	NCPLX	ASMD LKR	IS/IP/CCS	162	١٥	5	0.0	6.6 11.5	14	0	0	64	Р	FP	06/28/82			
Y-104	NCPLX	ASMD LKR	IS/IP/CCS	46	3	12	0.0	0.0	5 15	0	162	0	P	FP	07/09/82			İ
Y-105	NCPLX	ASMD LKR	IS/IP/CCS	231	١٠	0	0.0	3.6	0	0	43	0	P	FP	06/27/90			
Y-106	NCPLX	ASMD LKR	IS/IP/CCS	17	ہ ا	0	0.0	0.0	0	0	231	0	P	М	04/28/82	09/07/89		
						·	0.0	0.0	U	U	17	0	P	М	04/28/82	08/22/89		
SINGL	E-SHELL T	ANKS	TOTALS:	638	3	31	0.0	29.9	34	0	571	64						
					<u>*</u>						371		<u> </u>			<u> </u>		<u> </u>
					_			<u>U TAN</u>	K FARM	STATUS								
-101	NCPLX	ASMD LKR	IS/IP	25	3	0	0.0	0.0	3	0	22	0	P	MP	04/28/82	06/19/79		1
-102	NCPLX	SOUND	/PI	374	18	154	0.0	0.0	172	160	43	313	P	MP	04/28/82	06/08/89		İ
-103	NCPLX	SOUND	/P1	468	13	207	0.0	0.0	220	205	32	423	Р	FP	04/28/82	09/13/88		
-104	NCPLX	ASMD LKR	IS/IP	122	0	7	0.0	0.0	7	0	122	0	Р	MP	04/28/82	08/10/89		
-105	NCPLX	SOUND	/PI	418	37	170	0.0	0.0	207	192	32	349	FM	PS	09/30/78	07/07/88		}
106	NCPLX	SOUND	/PI	226	15	87	0.0	0.0	102	85	26	185	F	PS	12/30/93	07/07/88		
107	DSSF	SOUND	/Pf	406	31	172	0.0	0.0	203	183	15	360	F	s	12/30/93	10/27/88		
108	NCPLX	SOUND	/PI	468	24	202	0.0	0.0	226	209	29	415	F	s	12/30/93	09/12/84		
109	NCPLX	SOUND	/PI	463	19	197	0.0	0.0	216	205	48	396	F	F	06/30/96	07/07/88		
110	NCPLX	ASMD LKR	IS/PI	186	0	15	0.0	0.0	15	9	186	0	М	М	12/30/84	12/11/84		
-111	DSSF	SOUND	/PI	329	0	146	0.0	0.0	146	129	26	303	PS	FPS	02/10/B4	06/23/88		]
-112	NCPLX	ASMD LKR	IS/IP	49	4	0	0.0	0.0	4	0	45	0	Р	MP	02/10/84	08/03/89		
201	NCPLX	SOUND	IS/IP	5	1	0	0.0	0.0	1	0	4	0	M	s	08/15/79	08/08/89		1
202	NCPLX	SOUND	IS/IP	5	1	0	0.0	0.0	1	0	4	0	М	s	08/15/79	08/08/89		
203	NCPLX	SOUND	IS/IP	3	1	0	0.0	0.0	1	0	2	o	м	S	08/15/79	06/13/89		
204	NCPLX	SOUND	IS/IP	3	1	0	0.0	0.0	1	0	2	0	М	s	08/15/79	06/13/89		
SING	LE-SHELL	TANKS	TOTALS:	3550	168	1357	0.0	0.0	1525	1377	638	2744				· · · · · · · · · · · · · · · · · · ·		
							- V. V	0.0	1325	13//	036	2744		<del>- · · · · · · · · · · · · · · · · · · ·</del>				<del> </del>
GNA	TOTAL			35313	546	6565	22.9	4519,5	7099	5725	11841	22926						ļ <u> </u>

-13

# HNF-EP-0182-128

#### TABLE E-6 INVENTORY AND STATUS BY TANK - SINGLE-SHELL TANKS

November 30, 1998

#### FOOTNOTES:

Total Waste is calculated as the sum of Sludge and Saltcake plus Supernate,

The category "Interim Isolated" (II) was changed to "intrusion Prevention" (IP) in June 1993. See section C. "Tank and Equipment Code and Status Definitions."

Stabilization information from WHC-SD-RE-TI-178 SST STABILIZATION RECORD, latest revision, or SST Stabilization or Cognizant Engineer

#### (a) SX-104 Following Information from Cognizant Engineer

Pumping resumed on October 7 and was shut down several periods during October and November for transfer of waste from DCRT to SY-102, and to perform the 244-S integrity assessment.

Pumping may be interrupted during December to install a new jumber in a valve pit, and to relocate the slarm circuitry for some of the leak detectors in the transfer line.

Total Waste: 614 Kgal Supernate: 0 Kgal

Drainable Interstitial: 155.5 Kgal Pumped this month: 14.2 Kgal Total Pumped: 158.5 Kgal

Drainable Liquid Remaining: 155.5 Kgal Pumpable Liquid Remaining: 149.5 Kgal

Sludge: 136 Kgal Saltcake: 476 Kgal

26,326 gal of dilution water and 2,435 gal of water for transfer line flushes was used during November pumping operations.

#### (b) SX-106 Following information from Cognizant Engineer

Pumping began on October 7 and was shut down several periods during October and November for transfer of waste from DCRT to SY-102, and repair of a valve.

Total Waste: 526 Kgal Supernate: 49,3 Kgal

Drainable Interstitial: 224 Kgał Pumped this month: 1.9 Kgal Total Pumped: 11.7 Kgal

Drainable Liquid Remaining: 273.3 Kgal Pumpable Liquid Remaining: 252.3 Kgal

Sludge: 12 Kgal Saltcake: 465 Kgal

1,372 gal of dilution water and 976 gal of water for transfer line flushes was used during November pumping operations.

# HNF-EP-0182-128

# E-15

# TABLE E-6. INVENTORY AND STATUS BY TANK - SINGLE-SHELL TANKS November 30, 1998

#### FOOTNOTES:

(c) T-104 Following Information from Cognizant Engineer

Pumping resumed June 7, 1998.

Total Waste: 332 Kgal Supernate: 0 Kgal

Drainable Interstitial: 47.7 Kgal Pumped this month: 3.2 Kgal Total Pumped: 142.6 Kgal

Drainable Liquid Remaining: 47.7 Kgal Pumpable Liquid Remaining: 44.7 Kgal

Sludge: 332 Kgal Saltcake: O Kgal

Actual volume of liquid remaining to be pumped is still a rough estimate. Volumes will be corrected as porosity data becomes available with continued pumping. 362 gal of rew water was used during November pumping operations.

A correction was required due to continued accumulation on the totalizer during shutdown periods; the correction for November was 805 gal.

(c) T-110 Following information from Cognizant Engineer

Pumping began May 21, 1997.

Total Waste: 356 Kgal Supernate: 0 Kgal

Drainable Interstitial: 56.4 Kgal Pumped this month: 3.6 Kgal Total Pumped: 37.1 Kgal

Drainable Liquid Remaining: 56.4 Kgal Pumpable Liquid Remaining: 53.4 Kgal

Słudge: 356 Kgal Saltcake: 0 Kgal

Actual volume of liquid remaining to be pumped is still a rough estimate. Volumes will continue to be corrected as porosity data becomes available with continued pumping.

932 gal of raw water was used during November pumping operations.

Dome elevation survey performed October 27, 1998; to correct "L" value to 41,053 on Data Sheet 2b with next procedure PCA.

This page intentionally left blank.

## APPENDIX F

## PERFORMANCE SUMMARY

# TABLE F-1. PERFORMANCE SUMMARY (Sheet 1 of 2) WASTE VOLUMES (Kgallons) November 30, 1998

INCREASES/DECREASES IN WASTE VOLUMES STORED IN DOUBLE-SHELL TANKS

CUMULATIVE EVAPORATION - 1950 TO PRESENT WASTE VOLUME REDUCTION

HNF-EP-0182-128

	THIS	FY1999	FACILITY	
SOURCE	<u>MONTH</u>	TO DATE	242-B EVAPORATOR (10)	7172
B PLANT	0	O	242-T EVAPORATOR (1950's) (10)	9181
PUREX TOTAL (1)	0	0	IN-TANK SOLIDIFICATION UNIT 1 (10)	11876
PFP (1)	0	0	IN-TANK SOLIDIFICATION UNIT 2 (10)	15295
T PLANT (1)	0	0	IN-TANK SOLID. UNIT 1 & 2 (10)	7965
S PLANT (1)	0	0	(after conversion of Unit 1 to a cooler for Unit 2)	8833
300 AREAS (1)	0	0	242-T (Modified) (10)	24471
400 AREAS (1)	0	0	242-S EVAPORATOR (10)	41983
SULFATE WASTE - 100 N (2)	0	0	242-A EVAPORATOR (11)	73689
C-106 SOLIDS (INCLUDING FLUSH)	9	9	242-A Evaporator was restarted April 15, 1994,	
TRAINING/X-SITE (9)	0	0	after having been shut down since April 1989.	
TANK FARMS (6)	1	5	Total waste reduction since restart:	9486
SALTWELL LIQUID (8)	42	111	Campaign 94-1 2417 Kgal	
			Campaign 94-2 2787 Kgal	
OTHER GAINS	24	38	Campaign 95-1 2161 Kgal	
Slurry increase (3)	7		Campaign 96-1 1117 Kgal	
Condensate	17		Campaign 97-1 351 Kgal	
Instrument change (7)	0		Campaign 97-2 653 Kgal	
Unknown (5)	0			
OTHER LOSSES	-7	-17		
Slurry decrease (3)	-2			
Evaporation (4)	-2			
Instrument change (7)	0		<b>                                     </b>	
Unknown (5)	-3			
EVAPORATED	o	0		
GROUTED	o	0		
TOTAL BUILDING STREET	69	146	]	
Note: No waste due to BIO (Basis for	Interim Operation) im	plementation	<u> </u>	

# TABLE F-1. PERFORMANCE SUMMARY (Sheet 2 of 2)

Footnotes:

#### **INCREASES/DECREASES IN WASTE VOLUMES**

- (1) Including flush
- (2) Sulfate waste is generated from ion exchange backflushing and sand filter clean out, resulting in sulfate waste.
- (3) Slurry increase/growth is caused by gas generation within the waste.
- (4) Aging waste tanks
- (5) Unknown waste gains or losses
- (6) Includes Tank Farms miscellaneous flushes
- (7) Liquid level measurement instrument changes from the automatic FIC to manual tape (and vice versa) result in unusual gains or losses because the manual tape may rest on an uneven crust surface giving a different reading from that of the automatic FIC.
- (8) Results from pumping of single-shell tanks to double-shell tanks.
- (9) Tracks waste being sent to the double-shell tanks from the "Precampaign Training Run." Evaporator procedures require a training run at least once per year. This also includes pressure testing and flushing of cross-site transfer lines.

#### WASTE VOLUME REDUCTION

- (10) Currently inoperative.
- Currently operative. The 242-A Evaporator-Crystallizer was started up March 1977, and shut down April 1989 because of regulatory issues, and remained shut down for subsequent upgrading. This evaporator operates under a vacuum, employing evaporative concentration with subsequent crystallization and precipitation of salt crystals (forming saltcake). The evaporator was restarted on April 15, 1994.

# TABLE F-2. SUMMARY OF WASTE TRANSACTIONS IN THE DOUBLE-SHELL TANKS

## SUMMARY OF WASTE TRANSACTIONS IN THE DOUBLE-SHELL TANK (DST) SYSTEM FOR NOVEMBER 1998: ALL VOLUMES IN KGALS

- The DST system received waste transfers/additions from Tank Farms, SST Stabilization and Tank 106-C solids retrieval in November.
- There was a net change of +69 Kgals in the DST system for November 1998.
- The total DST inventory as of November 30, 1998 was 18,744 Kgals.
- There was no Saltwell Liquid (SWL) pumped to the East Area DSTs in November.
- There was 42 Kgals of Saltwell Liquid (SWL) pumped to the West Area DSTs (102-SY) in November.
- There was ~ 9 Kgals of solids pumped from Tank 106-C to Tank 102-AY in November.
- The projected SWL pumping volumes were changed in November. The projected SWL pumping volumes are assumed to change again once SST stabilization engineers finish their evaluation.

FACILITY GENERAL	IONS	OTHER GAINS ASSOCIA	TED WITH	OTHER LOSSES ASSOCIA	TED WITH
SWL (West)	+42 Kgal (2\$Y)	SLURRY		SLURRY	-2 Kga
Tank Farms	+1 Kgal (2AW)	CONDENSATE		CONDENSATE	-2 Kga
Tank 106-C Solids	+9 Kgal (2AY)	INSTRUMENTATION		INSTRUMENTATION	-0 Kga
TOTAL	+52 Kgal	UNKNOWN		UNKNOWN	-3 Kga

	ACTUAL DST WASTE RECEIPTS	PROJECTED DST WASTE RECEIPTS	MISC. DST CHANGES (+/-)	WVR	NET DST CHANGE	TOTAL DST
OCT98	73	81	4	0	77	18675
NOV98	52	115	17	0	69	
DEC98		128		0	- 09	18744
JAN99		113		0		<del> </del>
FEB99		95		0		
MAR99		153		0		<del></del>
APR99		-838		0		<del>-</del>
MAY99		180	<u> </u>	0		<del></del>
UN99		231		0		<del> </del>
UL99		186		<u>0</u>		<del> </del>
<b>\UG99</b>		119	<del></del>	0		
SEP99		142		0		<del></del>

NOTE: The "PROJECTED DST WASTE RECEIPTS" numbers were updated in November 1998.




FIGURE F-1 COMPARISON OF WASTE VOLUME GENERATIONS FOR HANFORD FACILITIES
(All volumes in Kgals)

This page intentionally left blank

### APPENDIX G

## MISCELLANEOUS UNDERGROUND STORAGE TANKS AND SPECIAL SURVEILLANCE FACILITIES

## ဂု

# TABLE G-1. EAST AND WEST AREA MISCELLANEOUS UNDERGROUND STORAGE TANKS AND SPECIAL SURVEILLANCE FACILITIES

ACTIVE - still running transfers through the associated diversion boxes or pipeline encasements

November 30, 1998

	FACILITY	<u>LOCATION</u>	PURPOSE (receives waste from:)	(Gallons)	MONITORED BY	REMARKS	
	EAST AREA 241-A-302-A	A Farm	A-151 DB	965	SACS/ENRAF	Foamed over Catch Tank pump pit & div. box to prevent intrusion	
	241-ER-311	B Plant	ER-151, ER-152 DB	6723	SACS/CASS/FIC	Rain	
	241-AX-152	AX Farm	AX-152 DB	43	SACS/MT	Pumped 11/98	
	241-AZ-151	AZ Farm	AZ-702 condensate	2905	SACS/CASS/FIC	Volume changes daily - pumped to AZ-102 as needed	
	241-AZ-154	AZ Farm		25	SACS/CASS/MT		
	244-BX-TK/SMP	BX Complex	DCRT - Receives from several farms	24209	SACS/MANUALLY	Using Manual Tape for tank	
	244-A-TK/SMP	A Complex	DCRT - Receives from several farms	6821	MCS/SACS/WTF	WTF	_
	A-350	A Farm	Collects drainage	364	MCS/SACS/WTF	WTF pumped as needed	H
)	AR-204	AY Farm	RR Cars during transfer to rec. tanks	300	DIP TUBE	Alarms on CASS	٠.
)	A-417	A Farm	-	11757	SACS/DIP TUBE	WTF - pumped 4/98	Ÿ
	CR-003-TK/SUMP	C Farm	DCRT	3985	MT/ZIP CORD	Zip cord in sump O/S 3/11/96, water intrusion, 1/98	EP-0182-
	WEST AREA						128
	241-TX-302-C	TX Farm	TX-154 DB	361	SACS/CASS/ENRAF		
	241-U-301-B	U Farm	U-151, U-152, U-153, U-252 DB	8138	SACS/CASS/ENRAF	Returned to service 12/30/93	
	241-UX-302-A	U Plant	UX-154 DB	1972	SACS/CASS/ENRAF		
	241-S-304	S Farm	S-151 DB	158	SACS/CASS/ENRAF	Replaced S-302-A, 10/91; ENRAF installed 7/98	
						Sump not alarming.	
	244-S-TK/SMP	S Farm	DCRT - Receives from several farms	6683	SACS/MANUALLY	CWF	
	244-TX-TK/SMP	TX Farm	DCRT - Receives from several farms	17911	SACS/MANUALLY	MT	
	Vent Station Catch 1	<b>Tank</b>	Cross Country Transfer Line	337	SACS/MANUALLY	MT	
			Total Active Facilities 18	LECEND:	DB - Diversion Bar		

Note: Readings may be taken manually or automatically by FIC (or ENRAF).

All FICs and manual ENRAFs connected to CASS. All tanks on CASS (either suite or manual) are also on the SACS database. If sutomatic correspondings to CASS are broken, readings are taken manually.

Itemual readings include readings taken by manual tape, manual FIC, or manual readings of automatic FIC If CASS is printing \*0\*1;

Readings may also be taken by sip cord, which are acceptable but less accurate.

33/	SACS/MANUALLY M1
LEGEND:	DB - Dhemion Best
	TK-Tank Till the second of the
	SMP - Support FIC - Food Section and Corporation measurement devices
	RC: Rober (Fig. Resource) and description of the MRC - Market FC   1   1   1   1   1   1   1   1   1
	MT - Manual Tapo
	CWP - Magnit Fabrur Roph — Corrected Meight Factor 9 7  CASS - Computer Automated Statistics System 9 7
	BACS - Surveillance Automated Control Bystein MCS - Mouton and Control System
	D/8 - Out of Service

November 30, 1998

				MONITORI	ED
<u> FACILITY</u>	LOCATION	RECEIVED WASTE FROM:	(Gallons)	<u>BY</u>	<u>REMARKS</u>
216-BY-201	BY Farm	TBP Waste Line	Unknown	NM	(216-BY)
241-A-302-B	A Farm	A-152 DB	5681	CASS/MT	Isolated 1985, Project B-138
					Interim Stabilized 1990, Rain intrusio
241-AX-151	N of PUREX	PUREX	Unknown	NM	Isolated 1985
241-B-301-B	B Farm	B-151, B-152, B-153, B-252 DB	22250	NM	Isolated 1985 (1)
241-B-302-B	B Farm	B-154 DB	4930	NM	Isolated 1985 (1)
241-BX-302-A	BX Farm	BR-152, BX-153, BXR-152, BYR-152 DB	840	NM	Isolated 1985 (1)
241-BX-302-B	BX Farm	8X-154 DB	1040	NM	Isolated 1985 (1)
241-BX-302-C	BX Farm	BX-155 DB	870	NM	Isolated 1985 (1)
241-C-301-C	C Farm	C-151, C-152, C-153, C-252 DB	10470	NM	Isolated 1985 (1)
241-CX-70	Hot Semi-	Transfer lines	Unknown	NM	Isolated, Decommission Project,
241-CX-72	Works	Transfer lines	650	NM	See Dwg H-2-95-501, 2/5/87
241-ER-311A	SW B Plant	ER-151 DB	Unknown	NM	Isolated
244-AR VAULT	A Complex	Between farms & B-Plant	Unknown	NM	Not actively being used. Systems activated for final clean-out.
244-BXR-TK/SMP-001	BX Ferm	Transfer lines	7200	NM	Interim Stabilization 1985 (1)
244-BXR-TK/SMP-002	BX Farm	Transfer lines	2180	NM	Interim Stabilization 1985 (1)
244-BXR-TK/SMP-003	BX Farm	Transfer lines	1810	NM	Interim Stabilization 1985 (1)
244-BXR-TK/SMP-011	BX Farm	Transfer lines	7100	NM	Interim Stabilization 1985 (1)
361-B-TANK	B Plant	Drainage from B-Plant	Unknown	NM	Interim Stabilization 1985 (1)

CASS - Computer Automated Surveillance System
TR - Tank
Sett - Sump
R: Leursty denoted replacement
NM - Not Montread

(1) SOURCE: WASTE STORAGE TANK STATUS & LEAK DETECTION CRITERIA document

## TABLE G-3. WEST AREA INACTIVE MISC. UNDERGROUND STORAGE TANKS AND SPECIAL SURV. FACILITIES

INACTIVE - no longer receiving waste transfers November 30, 1998

#### MONITORED

				MICHALIONED	
<u> FACILITY</u>	<u>LOCATION</u>	RECEIVED WASTE FROM:	(Gallons)	BY	<u>REMARKS</u>
216-TY-201	E. of TY Farm	Supernete from T-112	Unknown	NM	Isolated
231-W-151-001	N. of Z Plant	231-Z Floor drains	Unknown	NM	Inactive, last data 1974
231-W-151-002	N. of Z Plant	231-Z Floor drains	Unknown	NM	Inactive, last data 1974
240-S-302	S Farm	240-S-151 DB	8544	CASS/ENRAF	Assumed Leeker EPDA 85-04
241-S-302-A	S Farm	241-S-151 DB	0	CASS/FIC *	Assumed Leaker TF-EFS-90-042
			* FIC in Intrus	•	Partially filled with grout 2/91, determined
					still assumed leaker after leak test
241-S-302-B	S Farm	S Encasements	Unknown	NM	Isolated 1985 (1)
241-SX-302	SX Farm	SX-151 DB, 151 TB	Unknown	NM	Isolated 1987
241-SX-304	SX Farm	SX-152 Transfer Box, SX-151 DB	Unknown	NM	Isolated 1985 (1)
241-T-301	T Farm	DB T-151, -151, -153, -252	Unknown	NM	Isolated 1985 (241-T-301B)
241-TX-302	TX Farm	TX-153 DB	Unknown	NM	Isolated 1985 (1)
241-TX-302-X-B	TX Farm	TX Encasements	Unknown	NM	Isolated 1985 (1)
241-TX-302-B	TX Farm	TX-155 DB	1600	CASS/MT	New MT installed 7/16/93
241-TX-302B(R)	E. of TX Farm	TX-155 DB	Unknown	NM	isolated
241-TY-302-A	TY Farm	TX-153 DB	Unknown	NM	Isolated 1985 (1)
241-TY-302-B	TY Farm	TY Encasements	Unknown	NM	Isolated 1985 (1)
241-Z-8	E. of Z Plant	Recupiex waste	Unknown	NM	Isolated, 1974, 1975
242-T-135	T Evaporator	T Evaporator	Unknown	NM	isolated
242-TA-R1	T Evaporator	Z Plant waste	Unknown	NM	Isolated
243-S-TK-1	N. of S Farm	Pers. Decon. Facility	Unknown	NM	Isolated
244-U-TK/SMP	U Ferm	DCRT - Receives from several farms	Unknown	NM	Not vet in use
244-TXR VAULT	TX Farm	Transfer lines	Unknown	NM	Interim Stabilized, MT removed 1984 (1)
244-TXR-TK/SMP-001	TX Farm	Transfer lines	Unknown	NM	Interim Stabilized, MT removed 1984 (1)
244-TXR-TK/SMP-002	TX Farm	Transfer lines	Unknown	NM	Interim Stabilized, MT removed 1984 (1)
244-TXR-TK/SMP-003	TX Farm	Transfer lines	Unknown	NM	Interim Stabilized, MT removed 1984 (1)
270-W	SE of U Plant	Condensate from U-221	Unknown	NM	Isolated 1970
361-T-TANK	T Plant	Drainage from T-Plant	Unknown	NM	isolated 1985 (1)
361-U-TANK	U Plant	Drainage from U-Plant	Unknown	NM	Interim Stabilzed, MT removed 1984 (1)
		<del></del>			

Total West Area tractive facilities 27

## APPENDIX H

## LEAK VOLUME ESTIMATES

TABLE H-1. SINGLE-SHELL TANK LEAK VOLUME ESTIMATES (Sheet 1 of 5) November 30, 1998

		Date Declared Confirmed or	Volume	Associated KiloCuries	Interim Stabilized	l eak i	Estimate
Tank Number		Assumed Leaker (3)	Galions (2)(4)	137 cs (10)	Date (12)	Updated	Reference
241-A-103	!	1987	5500 (9)		06/88	1987	(j)
241-A-104		1 <b>97</b> 5	500 to 2500	0.8 to 1.8 (q)	09/78	1983	(p)(a)
241-A-105	(1)	1963	10000 to 277000	85 to 760 (b)	07/79	1991	(b)(c)
241-AX-102		1988	3000 (9)		09/88	1989	(h)
241-AX-104 241-B-101	-	1977 1974	(7) (7)	· · · · · · · · · · · · · · · · · · ·	08/81 03/81	1989 1989	(g) (g)
241-B-103		1978	- (7)		02/85	1989	(g)
241-B-105 241-B-107		1978 1980	(7) 8000 (9)		12/84 03/85	1989 1986	(g) (d)(f)
241-B-110		1981	10000 (9)		03/85	1986	(d)
241-B-111 241-B-112		1978 1978	- (7) 2000		06/85 05/85	1989	(g)
241-B-201		1980	1200 (9)		08/81	1989 1984	(g) (e)(f)
241-B-203 241-B-204		1983 1984	300 (9) 400 (9)		06/84	1986	(d)
241-B-204 241-BX-101		1972	- (7)		06/84 09/78	1989 1989	(g) (g)
241-BX-102		1971	70000	50 (1)	11/78	1986	(d)
241-BX-108 241-BX-110		1974 1976	2500 (7)	0.5 (i)	07/79 08/85	1986 1989	(d) (g)
241-BX-111		1984 (14)	- (7)		03/95	1993	(g)(r)
241-BY-103 241-BY-105		1973 1984	<5000 (7)		11/97 N/A	1983 1989	(a)
241-BY-106		1984	(7)		N/A	1989	(g) (g)
241-BY-107 241-BY-108		1984 1972	15100 (9) <5000		07/79 02/85	1989 1983	(g) (a)
241-C-101		1980	20000 (9)(11)		11/83	1986	(d)
241-C-110		1984	2000		05/95	1989	(g)
241-C-111 241-C-201	(5)	1968 1988	5500 (9) 550		03/84 03/82	1989 1987	(g) (i)
241-C-202	(5)	1988	450		08/81	1987	(i)
241-C-203 241-C-204	(5)	1984 1988	400 (9) 350		03/82 09/82	1986 1987	(d) (i)
241-S-104		1968	24000 (9)		12/84	1989	(g)
241-SX-104		1988	6000 (9)		N/A	1988	(k)
241-SX-107 241-SX-108	(6)(15)	1964 1962	<5000 2400 to	17 to 140	10/79 08/79	1983 1991	(a) (m){q}(u)
241 SV.100	(8)(1E)	1085	35000	(m)(q)(u)	•		-
241-SX-109 ( 241-SX-110	(6)(15)	1965 1976	<10000 5500 (9)	<40 (n)(u)	05/81 08/79	1992 1989	(n)(u) (g)
	(15)	1974	500 to 2000	0.6 to 2.4 (I)(q)(u)	07/79	1986	(d)(q)(u)
241-SX-112 ( 241-SX-113	(15)	1969 1962	30000 15000	40 (I)(u) 8 (I)	07/79 11/78	1986 1986	(d)(u)
241-SX-114		1972	(7)		07/79	1989	(d) (g)
241-SX-115 241-T-101		1965 1992	50000	21 (o)	09/78	1992	(o)
241-T-103		1974	7500 (9) <1000 (9)		04/93 11/83	1992 1989	(p) (g)
241-T-106 241-T-107		1973 1984	115000 (9) (7)	40 (I)	08/81	1986	(d)
241-T-108		1974	<1000 (9)		05/96 11/78	1989 1980	(g) (f)
241-T-109 241-T-111		1974 1979, 1994 (13)	<1000 (9) <1000 (9)		12/84 02/95	1989	(g)
241-TX-105		1977	(7)		04/83	1994 1989	(f)(t) (g)
241-TX-107 ( 241-TX-110	(6)	1984 1977	2500		10/79	1986	(d)
241-TX-113		1974	(7) (7)		04/83 04/83	1989 1989	(g) (g)
241-TX-114 241-TX-115		1974 1977	(7) (7)		04/83	1989	(g)
241-TX-116		1977	(7) (7)		09/83 04/83	1989 1989	(g) (g)
241-TX-117		1977	- (7)		03/83	1989	(g)
241-TY-101 241-TY-103		1973 1973	<1000 (9) 3000	0.7 (I)	04/83 02/83	1980 1986	(f)
241-TY-104		1 <b>981</b>	1400 (9)		11/83	1986	(d) (d)
241-TY-105 241-TY-106		1960 1959	35000 20000	4 (I) 2 (I)	02/83 11/78	1986 1986	(d) (d)
241-U-101		1959	30000	20 (1)	09/79	1986	(d)
241-U-104 241-U-110		1961 1975	55000 5000 to 8100 (9)	0.09 (i) 0.05 (g)	10/78 12/84	1986	(d)
241-U-112	SOURS ON THE	1980	8500 (9)	0.00 (q)	09/79	1986 1 <b>986</b>	(d)(q) (d)
67 Tanke			<750,000 - 1,050,000	(8)			COMMODURATION OF LABOR OR AND ADDRESS OF THE PERSON OF THE

N/A = not applicable (not yet interim stabilized)

## TABLE H-1. SINGLE-SHELL LEAK VOLUME ESTIMATES (Sheet 2 of 5)

#### Footnotes:

- Current estimates [see reference(b)] are that 610 Kgallons of cooling water was added to Tank 241-A-105 from November 1970 to December 1978 to aid in evaporative cooling. In accordance with Dangerous Waste Regulations [Washington Administrative Code 173-303-070 (2)(a)(ii), as amended, Washington State Decartment of Ecology, 1990, Olympia, Washington], any of this cooling water that has been added and subsequently leaked from the tank must be classified as a waste and should be included in the total leak volume. In August 1991, the leak volume estimate for this tank was updated in accordance with the WAC regulations. Previous estimates excluded the cooling water leaks from the total leak volume estimates because the waste content (concentration) in the cooling water which leaked should be much less than the original liquid waste in the tank (the sludge is relatively insoluble). The total leak volume estimate in this report (10 Kgallons to 277 Kgallons) is based on the following (see References):
  - 1. Reference (b) contains an estimate of 5 Kgallons to 15 Kgallons for the initial leak prior to August 1968.
  - 2. Reference (b) contains an estimate of 5 Kgallons to 30 Kgallons for the leak while the tank was being sluiced from August 1968 to November 1970.
  - 3. Reference (b) contains an estimate of 610 Kgallons of cooling water added to the tank from November 1970 to December 1978 but it was estimated that the leakage was small during this period. This reference contains the statement "Sufficient heat was generated in the tank to evaporate most, and perhaps nearly all, of this water." This results in a low estimate of zero gallons leakage from November 1970 to December 1978.
  - 4. Reference (c) contains an estimate the 378 to 410 Kgallons evaporated out of the tank from November 1970 to December 1978. Subtracting the minimum evaporation estimate from the cooling water added estimate provides a range from 0 to 232 Kgallons of cooling water leakage from November 1970 to December 1978.

	Low Estimate	High Estimate
Prior to August 1968	5,000	15,000
August 1968 to November 1970	5,000	30,000
November 1970 to December 1978	0	232,000
Totals	10,000	277,000

- These leak volume estimates do not include (with some exceptions), such things as: (a) cooling/raw water leaks, (b) intrusions (rain infiltration) and subsequent leaks, (c) leaks inside the tank farm but not through the tank liner (surface leaks, pipeline leaks, leaks at the joint for the overflow or fill lines, etc.), and (d) leaks from catch tanks, diversion boxes, encasements, etc.
- In many cases, a leak was suspected long before it was identified or confirmed. For example, reference (d) shows that Tank 241-U-104 was suspected of leaking in 1956. The leak was "confirmed" in 1961. This report lists the "assumed leaker" date of 1961. Using present standards, Tank 241-U-104 would have been declared an assumed leaker in 1956. In 1984, the criteria designations of "suspected leaker," "questionable integrity," "confirmed leaker," "declared leaker," "borderline" and "dormant," were merged into one category now reported as "assumed leaker." See reference (f) for explanation of when, how long, and how fast some of the tanks leaked. It is highly likely that there have been undetected leaks from single-shell tanks because of the nature of their design and instrumentation.
- (4) There has been an effort in the past few years to re-evaluate these leak volume estimates; however, the activity is not currently funded.

## TABLE H-1. SINGLE-SHELL TANK LEAK VOLUME ESTIMATES (Sheet 3 of 5)

- The leak volume estimate date for these tank is before the "declared leaker" date because the tank was in a "suspected leaker" or "questionable integrity" status; however, a leak volume had been estimated prior to the tank being reclassified.
- (6) The increasing radiation levels in drywells and laterals associated with these three tanks could be indicative of a continuing leak or movement of existing radio nuclides in the soil. There is no conclusive way to confirm these observations.
- (7) Methods were used to estimate the leak volumes from these 19 tanks based on the <u>assumption</u> that their cumulative leakage is approximately the same as for 18 of the 24 tanks identified in footnote (9). For more details see reference (g). The total leak volume estimate for these tanks is 150 Kgallons (rounded to the nearest Kgallons), for an average of approximately 8 Kgallons for each of 19 tanks.
- (8) The total has been rounded to the nearest 50 Kgallons. Upper bound values were used in many cases in developing these estimates. It is likely that some of these tanks have not actually leaked.
- (9) Leak volume estimate is based solely on observed liquid level decreases in these tanks. This is considered to be the most accurate method for estimating leak volumes.
- (10) The curie content shown is as listed in the reference document and is <u>not</u> decayed to a consistent date: therefore, a cumulative total is inappropriate.
- Tank 241-C-101 experienced a liquid level decrease in the late 1960s and was taken out of service and pumped to a "minimum heel" in December 1969. In 1970, the tank was classified as a "questionable integrity" tank. Liquid level data show decreases in level throughout the 1970s and the tank was saltwell pumped during the 1970s, ending in April 1979. The tank was reclassified as a "confirmed leaker" in January 1980. See references (q) and (s); refer to reference (s) for information on the potential for there to have been leaks from other C-farm tanks (specifically, C-102, C-103, and C-109).
- These dates indicate when the tanks were declared to be interim stabilized. In some cases, the official interim stabilization documents were issued at a later date. Also, in some cases, the field work associated with interim stabilization was completed at an earlier date.
- (13) Tank T-111 was declared an assumed re-leaker on February 28, 1994, due to a decreasing trend in surface level measurement. This tank was pumped, and interim stabilization completed on February 22, 1995.
- Tank BX-111 was declared an assumed re-leaker in April 1993. Preparations for pumping were delayed, following an administrative hold place on all tank farm operations in August 1993. Pumping resumed and the tank was declared interim stabilized on March 15, 1995.
- The leak volume and curie release estimates on SX-108, SX-109, SX-111, and SX-112 have been reevaluated using a Historical Leak Model [see reference (u)]. In general, the model estimates are much higher
  than the values listed in the table, both for volume and curies released. The values listed in the table do not
  reflect this revised estimate because, "In particular, it is worth emphasizing that this report was never meant to
  be a definitive update for the leak baseline at the Hanford Site. It was rather meant to be an attempt to view the
  issue of leak inventories with a new and different methodology." (This quote is from the first page of the
  referenced report). Therefore, an uncertainty analysis to determine the applicability of this methodology is
  currently in progress.

# TABLE H-1. SINGLE-SHELL TANK LEAK VOLUME ESTIMATES (Sheet 4 of 5)

#### References:

- (a) Murthy, K.S., et al, June 1983, Assessment of Single-Shell Tank Residual Liquid Issues at Hanford Site, Washington, PNL-4688, Pacific Northwest Laboratory, Richland, Washington.
- (b) WHC, 1991a, Tank 241-A-105 Leak Assessment, WHC-MR-0264, Westinghouse Hanford Company, Richland, Washington.
- (c) WHC, 1991b, Tank 241-A-105 Evaporation Estimate 1970 Through 1978, WHC-EP-0410, Westinghouse Hanford Company, Richland, Washington.
- (d) Smith, D. A., January 1986, Single-Shell Tank Isolation Safety Analysis Report, SD-WM-SAR-006, Rev. 1, Westinghouse Hanford Company, Richland, Washington.
- (e) McCann, D. C., and T. S. Vail, September 1984, Waste Status Summary, RHO-RE-SR-14, Rockwell Hanford Operations, Richland, Washington.
- (f) Catlin, R. J., March 1980, Assessment of the Surveillance Program of the High-Level Waste Storage Tanks at Hanford, Hanford Engineering Development Laboratory, Richland, Washington.
- (g) Baumhardt, R. J., May 15, 1989, Letter to R. E. Gerton, U.S. Department of Energy-Richland Operations Office, Single-Shell Tank Leak Volumes, 8901832B R1, Westinghouse Hanford Company, Richland, Washington.
- (h) WHC, 1990a, Occurrence Report, Surface Level Measurement Decrease in Single-Shell Tank 241-AX-102, WHC-UO-89-023-TF-05, Westinghouse Hanford Company, Richland, Washington.
- (i) Groth, D. R., July 1, 1987, Internal Memorandum to R. J. Baumhardt, Liquid Level Losses in Tanks 241-C-201, -202 and -204, 65950-87-517, Westinghouse Hanford Company, Richland, Washington.
- (j) Groth, D. R. and G. C. Owens, May 15, 1987, Internal Memorandum to J. H. Roecker, *Tank 103-A Integrity Evaluation*, Westinghouse Hanford Company, Richland, Washington.
- (k) Campbell, G. D., July 8, 1988, Internal Memorandum to R. K. Welty, Engineering Investigation: Interstitial Liquid Level Decrease in Tank 241-SX-104, 13331-88-416, Westinghouse Hanford Company, Richland, Washington.
- (1) ERDA, 1975, Final Environmental Statement Waste Management Operations, Hanford Reservation, Richland, Washington, ERDA-1538, 2 vols., U.S. Energy Research and Development Administration, Washington, D.C.
- (m) WHC, 1992a, Tank 241-SX-108 Leak Assessment, WHC-MR-0300, Westinghouse Hanford Company, Richland, Washington.
- (n) WHC, 1992b, Tank 241-SX-109 Leak Assessment, WHC-MR-0301, Westinghouse Hanford Company, Richland, Washington.
- (0) WHC, 1992c, Tank 241-SX-115 Leak Assessment, WHC-MR-0302, Westinghouse Hanford Company, Richland, Washington.

## TABLE H-1. SINGLE-SHELL TANK LEAK VOLUME ESTIMATES (Sheet 5 of 5)

- (p) WHC, 1992d, Occurrence Report, Apparent Decrease in Liquid Level in Single Shell Underground Storage Tank 241-T-101, Leak Suspected; Investigation Continuing, RL-WHC-TANKFARM-1992-0073, Westinghouse Hanford Company, Richland, Washington.
- (q) WHC,1990b, A History of the 200 Area Tank Farms, WHC-MR-0132, Westinghouse Hanford Company, Richland, Washington.
- (r) WHC, 1993, Occurrence Report, Single-Shell Underground Waste Storage Tank 241-BX-111 Surface Level Decrease and Change From Steady State Condition, RL-WHC-TANKFARM-1993-0035, Westinghouse Hanford Company, Richland, Washington.
- (s) WHC, 1993a, Assessment of Unsaturated Zone Radionuclide Contamination Around Single-Shell Tanks 241-C-105 and 241-C-106, WHC-SD-EN-TI-185, REV OA, Westinghouse Hanford Company, Richland, Washington.
- (t) WHC, 1994, Occurrence Report, Apparent Liquid Level Decrease in Single Shell Underground Storage Tank 241-T-111; Declared an Assumed Re-Leaker, RL-WHC-TANKFARM-1994-0009, Westinghouse Hanford Company, Richland, Washington.
- (u) HNF, 1998, Agnew, S. F. and R. A. Corbin, August 1998, Analysis of SX Farm Leak Histories Historical Leak Model, (HLM), HNF-3233, Rev. 0, Los Alamos National Laboratory, Los Alamos, New Mexico

## APPENDIX I

INTERIM STABILIZATION STATUS CONTROLLED, CLEAN, AND STABLE STATUS

TABLE I-1. SINGLE-SHELL TANKS INTERIM STABILIZATION STATUS (Sheet 1 of 3)
November 30, 1998

	<u> </u>	Interim	Г	888	T	Interim	T	8886		1	1 ( ) .	T
Tank	Tank	Stabil.	Stabil.	Tank	Tank	Stabil.	Stabil.		Tank	<b>T</b> aul.	Interim	
i	1					I	1	. 🏻	Tank	Tank	Stabil.	Stabil.
Number A-101	Integrity SOUND	Date (1) N/A	Method	Number C-101		Date (1)	Method	1 💹	Number Table	Integrity	<u>Date (1)</u>	Method
A-102	SOUND	08/89	SN	C-102	ASMD LKR SOUND	09/95	AR	888	T-108	ASMD LKR	11/78	AR
A-102	ASMD LKR	06/88	AR	C-102	SOUND	N/A	JET	333	T-109 T-110	SOUND	12/84	AR
A-104	ASMD LKR	09/78	AR	C-104	SOUND	09/89	SN	200	T-111	ASMD LKR	N/A	<del></del>
A-105	ASMD LKR	07/79	AR	C-105	SOUND	10/95	AR (5)	-	T-112	SOUND	02/95 03/81	JET
A-106	SOUND	08/82	AR	C-106	SOUND	N/A	711 (0)		T-201	SOUND	04/81	AR(2)(3) AR (3)
AX-101	SOUND	N/A		C-107	SOUND	09/85	JET	36392	T-202	SOUND	08/81	AR
AX-102	ASMD LKR	09/88	SN	C-108	SOUND	03/84	AR		T-203	SOUND	04/81	AR
AX-103	SOUND	08/87	AR	C-109	SOUND	11/83	AR	- 889	T-204	SOUND	08/81	AR
AX-104	ASMD LKR	08/81	AR	C-110	ASMD LKR	06/95	JET	-	TX-101	SOUND	02/84	AR
B-101	ASMD IKR	03/81	SN	C-111	ASMD LKR	03/84	SN		TX-102	SOUND	04/83	JET
B-102	SOUND	08/86	SN	C-112	SOUND	09/90	AR		TX-103	SOUND	08/83	JET
B-103	ASMD IKR	02/85	SN	C-201	ASMD LKR	03/82	AR		TX-104	SOUND	09/79	SN
B-104	SOUND	06/85	SN	C-202	ASMD LKR	08/81	AR		TX-105	ASMD LKR	04/83	JET
B-105	ASMD IKR	12/84	AR	C-203	ASMD LKR	03/82	AR	***	TX-106	SOUND	06/83	JET
B-106	SOUND	03/85	SN	C-204	ASMD LKR	09/82	AR	- 10000	TX-107	ASMD LKR	10/79	AR
B-107	ASMD LKR	03/85	SN	S-101	SOUND	N/A	<u> </u>		TX-108	SOUND	03/83	JET
B-10B	SOUND	05/85	SN	S-102	SOUND	N/A			TX-109	SOUND	04/83	JET
B-109 B-110	SOUND ASMD LKR	04/86 12/84	SN	S-103	SOUND	N/A	<del></del>		TX-110	ASMD LKR	04/83	JET
B-111	ASMD LKR	06/86	AR SN	S-104	ASMD LKR	12/B4	AR		TX-111	SOUND	04/83	JET
B-112	ASMD LKR	05/86	SN	S-105 S-106	SOUND	09/88	JET		TX-112	SOUND	04/83	JET
B-201	ASMD LKR	08/81	AR (3)	S-107	SOUND	N/A			TX-113	ASMD LKR	04/83	JET
B-202	SOUND	05/85	AR	S-107	SOUND	N/A	107 (7)		TX-114	ASMD LKR	04/83	JET
B-203	ASMD LKR	06/64	AR	S-109	SOUND	12/96	JET (7)		TX-115	ASMD LKR	09/83	JET
B-204	ASMD LKR	06/84	AR	S-110	SOUND	N/A 01/97	F7 (0)	-	TX-116	ASMD LKR	04/83	JET
BX-101	ASMD LKR	09/78	AR	S-111	SOUND	N/A	JET (8)	- 1000	TX-117	ASMD LKR	03/B3	JET
BX-102	ASMD LKR	11/78	AR	S-112	SOUND	N/A			TX-118 TY-101	SOUND	04/83	JET
BX-103	SOUND	11/83	AR(2)	SX-101	SOUND	N/A			Y-102	ASMD LKR	04/83	JET
BX-104	SOUND	09/89	SN	SX-102	SOUND	N/A	<del> </del>	-00000	Y-103	SOUND ASMD LKR	09/79	AR
BX-105	SOUND	03/61	SN	SX-103	SOUND	N/A			Y-103	ASMD LKR	02/83 11/83	JET
BX-106	SOUND	07/95	SN	SX-104	ASMD LKR	N/A		-	Y-105	ASMD LKR	02/83	JET
BX-107	SOUND	09/90	JET	SX-105	SOUND	N/A	-	1000	Y-106	ASMD LKR	11/78	AR
BX-108	ASMD LKR	07/79	SN	SX-106	SOUND	N/A		-	J-101	ASMD LKR	09/79	AR
BX-109	SOUND	09/90	JET	SX-107	ASMD LKR	10/79	AR	-	J-102	SOUND	N/A	
BX-110	ASMD LKR	08/85	SN (4)	SX-108	ASMD LKR	08/79	AR	∭ί	J-103	SOUND	N/A	
BX-111	ASMD LKR	03/95	JET	SX-109	ASMD LKR	06/B1	AR	∭ (	J-104	ASMD LKR	10/7B	AR
BX-112	SOUND	09/90	JET	SX-110	ASMD LKR	08/79	AR	∭ L	J-105	SOUND	N/A	
BY-101	SOUND	05/84	JET	SX-111	ASMD LKR	07/79	SN	∭U	J-106	SOUND	N/A	
BY-102	SOUND	04/95	JET	SX-112	ASMD LKR	07/79	AR		J-107	SOUND	N/A	
BY-103	ASMD LKR	11/97		SX-113	ASMD LKR	11/78	AR	<b>∭</b> ∪	-108	SOUND	N/A	
BY-104	SOUND	01/86	JET	SX-114	ASMO LKR	07/79	AR	-	-109	SOUND	N/A	
BY-105	ASMD LKR	N/A		SX-115	ASMD LKR	09/78	AR		-110	ASMD LKR	12/84	AR
BY-106	ASMD LKR	N/A		T-101	ASMD LKR	04/93	SN	_	-111	SOUND	N/A	
BY-107 BY-108	ASMD LKR	07/79	JET	T-102	SOUND	03/.81	AR(2)(3)	_	-112	ASMD LKR	09/79	AR
BY-108	SOUND	02/85	JET (0)	T-103	ASMD LKR	11/83	AR	ALC:	-201	SOUND	08/79	ЯA
BY-110	SOUND	07/97 01/95	JET(9)	T-104	SOUND	N/A		-	-202	SOUND	08/79	SN
BY-111	SOUND	01/85	JET JET	T-106 T-108	SOUND.	06/87	AR		-203	SOUND	08/79	AR
BY-112	SOUND	06/84	JET	T-107	ASMD LKR	08/81	AR	SS U	-204	SOUND	08/79	SN
LEGEND:	COORD	VU) 04	√E I	1-10/	ASMD LKR	05/96	JET	Ĺ				
AR = A JET = S SN = S	AR = Administratively interim stabilized  JET = Saltwell jet pumped to remove drainable interstitial liquid  SN = Supernate pumped (Non-Jet pumped)									abilized Tankı terim Stabiliz		119 30
N/A = 1	N/A = Not yet interim stabilized ASMD LKR = Assumed Leaker							<del></del>	Total S	ingle-Shell T	enks	149

# TABLE I-1. SINGLE-SHELL TANKS INTERIM STABILIZATION STATUS (sheet 2 of 3)

#### Footnotes:

- These dates indicate when the tanks were actually interim stabilized. In some cases, the official interim stabilization documents were issued at a later date.
- Originally, seven tanks (B-104, B-110, B-111, BX-103, T-102, and T-112) did not meet current established supernatant and interstitial liquid interim stabilization criteria, but <u>did</u> meet the criteria in existence when they were declared interim stabilized.

B-110, B-111, U-110 were determined to have met current interim stabilization criteria, per WHC-SD-WM-ER-516-REV 0, "Interim Stabilization Status of SSTs B-104, B-110, B-111, T-102, T-112, and U-110," and WHC-SD-WM-ER-518-REV 0, "Investigation of Liquid Intrusion in 241-BX-103," both dated October 5, 1995.

B-104, BX-103, T-102, T-112 have been determined to meet current interim stabilization criteria as of September 30, 1996, per memo 9654456, J. H. Wicks to Dr. J. K. McClusky, DOE-RL.

<u>B-202</u> was determined to no longer meet the current established criteria for 200-series tanks due to a steady increase in the surface level indicating an ongoing intrusion based on a comparison of in-tank videos and subsequent evaluation in March 1996.

- (3) Original Interim Stabilization data are missing on four tanks: B-201, T-102, T-112, and T-201.
- (4) BX-110 was interim stabilized by Supernate Pumping in August 1985. Jet pumping began in December 1993 and soon stopped because of equipment failure. Due to low net volume pumped, major equipment failure, and ALARA, it was decided jet pumping would not resume. An in-tank video was taken in October 1994. Reevaluation after review of the video indicated 1.5 Kgallons of waste was pumped. (Almost 3 Kgallons of water flushes were needed to produce 1.5 Kgallons tank waste.)
- C-105 was interim stabilized administratively on October 30, 1995. No jet pumping occurred in this tank, nor does interstitial liquid level data exist for this tank. There are no diptubes or LOWs installed. Approximately 12 Kgallons of liquid waste was evaporated between May 1993 and October 1995. An in-tank video taken August 30, 1995, revealed a shallow supernatant pool surrounded by a 5-8 foot solids waste shore. The volume of supernate is estimated as 2 Kgallons. The tank currently meets the established criteria for declaring single-shell tanks Interim Stabilized.
- (6) T-107 was interim stabilized by Jet Pumping in May 1996. Pumping was completed in March, and an in-tank video taken in May showed no supernate visible on the surface. The surface has an irregular contour of mostly sludge, and the elevation differences between high and low points appear to be about four inches.
- (7) S-108 was interim stabilized by Jet Pumping in December 1996. Pumping was completed in September and an in-tank video taken in December showed no supernate visible on the surface of the waste, which appears to be saltcake. The video shows a relatively level surface with some caving and crowning. Total waste is 448.7 Kgallons, with drainable liquids 4.0 Kgallons and no pumpable liquids.
- (8) S-110 was interim stabilized by Jet Pumping in January 1997. Pumping was completed in July 1996, and an in-tank video taken in December showed no supernate visible on the surface of the waste, which appears to be saltcake. The level is not consistent and there appears to have been some caving and crowning. Total waste is 389.0 Kgallons, with drainable liquids 29.8 Kgallons and pumpable liquids 23.4 Kgallons.
- (9) BY-109 was interim stabilized by Jet Pumping in July 1997. Pumping was completed in May 1997, and an intank video taken in June indicated there is a relatively uniform, slightly concave, crusty/cracked contour over most of the surface with no visible supernate. Total waste is 290.0 Kgallons, with drainable liquids 36.7 Kgallons, and pumpable liquids 20.3 Kgallons.

# TABLE I-1. SINGLE-SHELL TANKS INTERIM STABILIZATION STATUS (sheet 3 of 3)

(10) BY-103 was interim stabilized in November 1997, after completion of jet pumping in September. An in-tank video taken in February 1997 showed no visible surface liquid and no evidence of an intrusion. The waste was dry and flaky. Dried, caked waste was suspended from many of the pipes and pieces of process equipment. The overall surface of the waste seemed to slump slightly towards the center of the tank. Total waste is 414 Kgallons, with drainable liquids 38.3 Kgallons, and pumpable liquids 31.9 Kgallons.

# TABLE I-2. TRI-PARTY AGREEMENT SINGLE-SHELL TANK INTERIM STABILIZATION SCHEDULE

November 30, 1998

As part of the Controlled, Clean, and Stable mission, the Single-Shell Tank Interim Stabilization Project goal is to mitigate the risk to the environment from a leak release from aging SSTs, by removing as much of the drainable liquid as practical, for safe storage prior to full waste retrieval.

New TPA milestones were negotiated effective September 23, 1996, to allow greater flexibility in the sequencing of tanks, in light of the latest technical information regarding tank waste safety status and watch list concerns.

Milestone	Description	Due Date	Actual Date	Comments
M-41-20	Start Interim Stabilization of 4 Single-Shell Tanks	9/30/96	3/24/96	S-108, S-110, T-104, and T-107 started.
M-41-21	Start Interim Stabilization of 2 Single-Shell Tanks	5/31/97 (1)	5/12/97	BY-109 started 9/10/96; T-110 started 5/12/97
M-41-22	Start Interim Stabilization of 6 Single-Shell Tanks	9/30/97 (2)(4)		BY-103 started 9/29/97, SX-104 started 9/26/97
M-41-23	Start Interim Stabilization of 8 Single-Shell Tanks	3/31/98 (3)(4)		
M-41-24	Start Interim Stabilization of 9 Single-Shell Tanks	9/30/98 (4)		
M-41-25	Start Interim Stabilization of 3 Single-Shell Tanks	3/31/99 (4)		
M-41-26	Start Interim Stabilization of 2 Single-Shell Tanks	9/30/99 (4)		
M-41-27	Complete Saltwell Pumping of Single-Shell Tanks	9/30/00 (4)		
M-41-00	Complete Interim Stabilization of Single-Shell Tanks including Intrusion Prevention	9/30/00 (4)		

- On March 13, 1997, Department of Ecology (Ecology) approved Change Control Form M-41-96-03, extending M-41-21 from March 31 to May 31, 1997.
- (2) Change Control Form M-41-97-01 was sent to Ecology on June 27, 1997; Dispute Resolution invoked on July 16, 1997. This Change Request was denied by the Director of Ecology on February 10, 1998.
- Change Control Form M-41-97-02 was sent to Ecology on December 29, 1997. Dispute Resolution invoked on January 13, 1998. This Change Request was denied by the Director of Ecology on March 10, 1998.
- (4) Path Forward Plan submitted to Ecology on April 15, 1998, projects completion date of September 30, 2004.

TABLE 1-3. SINGLE-SHELL TANKS STABILIZATION STATUS SUMMARY November 30, 1998

Partial Interim Isolated (PI)	Intrusion Prevent	ion Completed (IP)	Interim Stabili	zed (IS)
EAST AREA	EAST AREA	WEST AREA	EAST AREA	WEST AREA
A-101	A-103	S-104	A-102	S-104
A-102	A-104	S-105	A-103	S-105
	A-105		A-104	S-108
AX-101	A-106	SX-107	A-105	S-110
		SX-108	A-106	
BY-102	AX-102	SX-109		SX-107
BY-103	AX-103	\$X-110	AX-102	SX-108
BY-105	AX-104	SX-111	AX-103	SX-109
BY-106		SX-112	AX-104	SX-110
BY-109	B-FARM - 16 tanks	SX-113		SX-111
	BX-FARM - 12 tanks	SX-114	B-FARM - 16 tanks	SX-112
C-103	DV 404	SX-115	BX-FARM - 12 tanks	SX-113
C-105	BY-101	T 100	DV 404	SX-114
C-106	BY-104	T-102	BY-101	SX-115
East Area	BY-107	T-103	BY-102	~
MEST AREA	BY-108	T-105	BY-103	T-101
WEST AREA	BY-110	T-106	BY-104	T-102
S-101	BY-111 BY-112	T-108	BY-107	T-103
S-102 S-103	B1-112	T-109	BY-108	T-105
S-106	C-101	T-112 T-201	BY-109	T-106
S-107	C-102	T-202	BY-110	T-107
S-108	C-102		BY-111	T-108
S-109	C-107	T-203	BY-112	T-109
	C-107	T-204	C 404	T-111
S-110 S-111	C-108	TX-FARM - 18 tanks	C-101	T-112
S-111	C-110		C-102	T-201
3-112	C-111	TY-FARM - 6 tanks	C-104	T-202
SX-101	C-112	U-101	C-105	T-203
SX-101	C-201	U-104	C-107 C-108	T-204
SX-102	C-202	U-112	C-109	TV FADM 40 to los
SX-104	C-203	U-102	C-110	TX-FARM - 18 tanks
SX-105	C-204	U-202	C-111	TY-FARM - 6 tanks
SX-106	I A A C	U-203	C-112	U-101
5X 100		U-204	C-201	U-104
T-101		V/cat Area 53	C-202	U-110
T-104		ica iu	C-203	U-112
T-107		Post and a process of the second state of the	C-204	U-201
T-110			#Phuspannachtannonnachtannachtannachtannachtannachtan	U-202
T-111			hermas Probabilis (e. 14.) de dispestraci	U-203
	Controlled, Clean, and	d Stable (CCS)		U-204
U-102				West Area 59
U-103	EAST AREA	WEST AREA		Total 119
U-105	BX-FARM - 12 Tanks	TX-FARM - 18 tanks		
U-106		TY FARM - 6 tanks		
U-107		West Me and the second second		
U-108		GG 3		
U-109				
U-110	Note: CCS activities ha	ve been deferred		
U-111	until funding is availabl			
West Alies 29	_			
(COLUMN TO THE PARTY OF THE PAR				
<del>"</del>		•		

# APPENDIX J CHARACTERIZATION PROGRESS STATUS

#### **Hanford Tank** 200 West 200 East **Farm Facilities** T-Tank Farm 200 East and West Characterization (107) (01) **Progress Status BX-Tank Farm** Tank Number Hige Proory Tabs (Basis Profes) TY-Tank Farm SY-Tank Farm Need More Maleria Report Inder Review BY-Tank Farm (161) No lampie Taken (20) Analysis lucomplete Allitanks 75 ft dia. except 200 series tanks which are 20 ft dia. @ 55,000 ga TX-Tank Farm 139 Tanks Sampled (Solid Liquids) B-Tank Farm 25 Tanks Sampled (Vapor Only) 504 Samples Taken (112 (11) 42 Tanks - Alf Analyses Completed Status as of DECEMBER 2, 1998 108 **19** AP-Tank Farm U-Tank Farm AN-Tank Farm S-Tank Farm C-Tank Farm AZ-Tank Farm (26) AX-Tank Farm AY-Tank Farm SX-Tank Farm (182 (102) (108) (21) (107) (11) AW-Tank Farm A-Tank Farm Figure J-1 2G95120163.3-12/2/98 =J-2 ==

# FIGURE J-1. CHARACTERIZATION PROGRESS STATUS CHART LEGEND (Sheet 2 of 2)

#### November 30, 1998

F	
200 East/West	The chart divides the two areas.
Tank Farms	Each tank farm is represented by a rough schematic of the tank layout and a heading naming the farm.
Circles	Tanks are depicted by a circle for single-shell tanks and a double circle for double-shell tanks.
Boxes	A thin line box around a tank inside a tank farm denotes "Watch List" status, in concurrence with Table A-1 of this document.
Numbers in Circles	The top number is the tank number. The number in parentheses is a weighted priority number, described in WHC-SD-WM-TA-164, "Tank Waste Characterization Basis." The numbers can be compared to each other to gain appreciation of relative priority: the higher the number, the greater the priority to sample and analyze.
Underlined Numbers	If a number in parenthesis is underlined, it is denoted as a "Characterization Basis Tank," as described in WHC-SD-WM-TA-164, "Tank Waste Characterization Basis." These are key tanks taken from the priority list that are of principal interest to the Characterization Program.
Circle Shading	The shading in the circle indicates the degree to which sampling and analysis are complete per requirements described in applicable Data Quality Objectives (DQOs). If blank, no characterization sampling has taken place. If fully shaded, the sampling and analysis are complete for each DQO applicable to that tank. Tanks in which characterization has begun but is not complete are designated by being half shaded.
Corner Triangles	Small triangles near a tank circle give further information on half-shaded tanks. Upper left corner triangles indicate that vapor samples have been taken from the tank. Lower left-hand corner triangles indicate that the tank has been sampled, analyzed, and a formal report has been written on the condensed phase sampling. Further status of the tank will be determined after review of the report is complete. Lower right-hand corner triangles indicate that some review has been completed and it has been determined that more sampling is needed to resolve the DQO requirements. Absence of triangles from a half shaded tank indicates recent condensed phase sampling.

This page intentionally left blank

#### DISTRIBUTION

#### Number of copies

#### OFFSITE - USA

#### 2 Congress of the United States

House of Representatives 1111 Longworth Building Washington D.C. 20515-3703

Ron Wyden, Member of Congress, 3rd District

House of Representatives 1431 Longworth House Office Building Washington D. C. 20515

Richard "Doc" Hastings, Member of Congress, 4th District

#### 5 U. S. Department of Energy-Headquarters

1000 Independence Avenue, SW Washington, D. C. 20585

H. Calley EM-38 Cloverleaf Bldg.
Raymond Greenberg EM-38 Cloverleaf Bldg.
Kenneth Lang EM-36 Cloverleaf Bldg.
Ralph Lightener EM-38 Cloverleaf Bldg.
C. O'Dell EM-4 FORS/6E-034

#### 1 <u>U. S. Nuclear Regulatory Commission</u>

Division of Fuel Cycle, Safeguards & Security
Mail Stop T8-A33

Mail Stop T8-A33 Washington, DC 20555

Robert Pierson, Chief

#### 2 Washington State Department of Ecology

Nuclear & Mixed Waste Management Program

P.O. Box 47600

Olympia, WA 98504-7600

Library

Nuclear Waste Program 300 Desmond Drive Lacey, WA 98504

R. Stanley

#### l Washington State Department of Health

Radiation Protection 7171 Cleanwater Lane Box 47827

Olympia, WA 98504-7827

Ed Bricker

1 Oregon State Department of Energy 625 Marion St. NE Salem, OR 97310 Dirk Dunning 1 Oak Ridge National Laboratory P. O. Box 2008 Oak Ridge, TN 37831-6180 C. Forsberg MS-6180 Los Alamos National Laboratory I P. O. Box 1663 Los Alamos, NM 87545 Stephen Agnew Group INC-14, J-586 Sandia National Laboratories 1 1515 Eubank, NE P. O. Box 5800 Albuquerque, NM 87185 Scott Slezak, Organization 2161, MS 0716 1 Donald T. Oakley 9612 Hall Road Potomac, MD 20854 1 Fluor Daniel, Inc. 3353 Michelson Drive Irvine, CA 92698 Charles Divona, 512T 1 Foster-Miller, Inc. Power Systems Technology Group 350 Second Avenue Waltham, MA 02154-1196 Maureen Williams 3 National Research Council 2101 Constitution Ave, N.W Washington D. C. 20418 Robert S. Andrews, Senior Staff Officer, MS HA456 1 **Government Accountability Project** West Coast Office 1402 Third Avenue, Suite 1215

Seattle, WA 98101

Thomas E. Carpenter, Director

1 **Heart of America Northwest** 1305 Fourth Avenue Cobb Building Suite 208 Seattle, WA 98101 Gerald M. Pollet, Executive Director TRI-CITIES: 1 TRW Environmental Systems 507 Knight St, Ste A Richland, WA 99352 Mike Leonard 1 Foster Wheeler Environmental Corp. 3200 George Washington Way, Suite G Richland, WA 99352 R. J. Roberts 1 **ARES Corporation** 636 Jadwin Ave., Suite B Richland, WA 99352 Lewis Muhlestein 1 **Babad Technical Services** 2540 Cordoba Court Richland, WA 99352 1 Vista Research, Inc. 3000 George Washington Way, Suite 2C Richland, WA 99352 Phil Ohl 1 Wastren Inc. 1050 Gilmore Ave, Suite C Richland, WA 99352 Gary Dunford 1 R. K. Welty 409 S. 41st Ave West Richland, WA 99353 **ONSITE** 1 R. T. Winward A2-22

1

B2-05

Jacobs Engineering Group, Inc.

Ruth Schreiber

2	MACTEC - Meier Assoc		
	J. D. Bingham	R2-11	
	T. E. Jones	H6-12	
2	MACTEC - ERS		
	J. F. Bertsch	B1-42	
	J. R. Brodeur	B1-42	
_			
1	MACTEC	D2 76	
	S. M. Blacker	R3-75	
1	General Accounting Offi	<u>ce</u>	
	C. R. Abraham	A1-80	
•	W. M. 4 - 04 4- D	4 4 4 - <b>4 T</b> 7 - 1	
2	Washington State Depar Tony Valero	B5-18	
		B5-18	
	Library	D3-16	
1	U. S. Environmental Pro	tection Agency	
	D. R. Sherwood	B5-01	
22	U.S. Department of Ene	rgy-Richland Operations O	Mice
	6 B B 117		
	S. R. Brechbill	A4-52	
	D. C. Bryson	S7-41	
	J. M. Clark	S7-54	
	J. J. Davis	A0-21	
	J. A. Frey	K8-50	
	R. G. Harwood	S7-54	
	R. L. Higgins	S7-53	
	R. D. Hildebrand	H0-12	
	D. H. Irby	S7-54	
	J. E. Kinzer	S7-50	
	C. Pacheco	S7-54	
	T. E. Olds	A7-75	
	S. H. Pfaff	S7-50	
	G. M. Ramin	A2-22	
	G. W. Rosenwald	S7-54	
	M. J. Royack	S7-54	
	A. B. Sidpara	S7-53	
	R. A. Stolberg	A4-81	
	K. G. Wade	S7-53	
	D. J. Williams	S7-41	
	D. D. Wodrich	S7-50	
	Reading Room	H2-53	
9	Pacific National Northwe	st Laboratories	
	S. A. Bryan	P7-25	
	T. A. Ferryman	K5-12	
	R. E. Gephart	K9-76	
	S. A. Hartley	K5-12	
	J. L. Huckaby	K6-80	
	C. M. King	P7-25	
	A. F. Noonan	K9-91	
	B. E. Opitz	K6-75	
	~~. ~~. ~~p.~~.	110.17	

L. A. SHIVSET AU-21	L.A.	. Smyser	A0-21
---------------------	------	----------	-------

125	Fluor Daniel, Inc., and Affiliated	Companies
	D. I. Allen	R2-50
	D. G. Baide	S5-05
	R. W. Bechtol	A3-05
	D. B. Bechtold	T6-07
	L. Bedford	R2-84
	M. V. Berriochoa	B3-30
	T. M. Blaak	S5-13
	H. L. Boston	G3-21
		R2-11
	V. C. Boyles	
	C. B. Bryan	T4-07
	N. K. Butler	R3-01
	K. G. Carothers	R2-11
	R. J. Cash	S7-14
	W. L. Cowley	R1-49
	C. Defigh-Price	R2-12
	D. K. DeFord	S7-20
	M. P. Delozier	R2-58
	M. L. Dexter (10)	R1-51
	R. A. Dodd	S5-07
	J. G. Douglas	B4-51
	K. A. Elsethagen	S5-03
	A. C. Etheridge	H7-07
	S. D. Estey	R2-11
	K. D. Fowler	R2-11
	G. R. Franz	S7-40
	G. T. Frater	K9-46
•	L. A. Gaddis	H5-57
	K. A. Gasper	A3-03
	J. E. Geary	S6-71
	T. C. Geer	R1-43
	M. S. Gerber	B3-26
	B. C. Gooding	
	D. R. Groth	T4-01
		T4-15
	R. D. Gustavson	R2-54
	M. D. Guthrie	S6-72
	J. C. Guyette	S7-40
	D. B. Hagmann	R2-89
	B. K. Hampton	S7-40
	B. M. Hanlon (10)	T4-08
	G. N. Hanson	S5-07
	W.M. Harty Jr.	S5-13
	D.C. Hedengren	R2-11
	B. A. Higley	H5-49
	K. M. Hodgson	R2-11
	J. L. Homan	R3-25
	G. P. Hopkins	S5-03
	W. G. Hopkinson	R2-50
	S. E. Hulsey	S5-12
	M. N. Islam	R1-43
	O. M. Jaka	S5-12
	P. Jennings	R2-84
	R. D. Gensen	G3-21
	G. D. Johnson	S7-14
	J. Kalia	
	J. Nalia	R1-43

R. A. Kirkbride	R3-73
P. F. Kison	T4-07
N. W. Kirch	R2-11
J. S. Konyu	R2-88
J. G. Kristofzski	S7-01
M. J. Kupfer	H5-49
M. A. Lane	S2-47
M. D. LeClair	R3-75
J. A. Lechelt	R2-11
G. T. MacLean	R3-73
D. J. McCain	R2-12
M. A. McLaughlin	H8-67
W. H. Meader	H8-66
P. J. Morgan (2)	S7-40
M. A. Payne	R2-58
L. T. Pedersen, Jr.	R1-56
R. E. Pohto	R1-30
R. S. Popielarczyk	S7-01
R. L. Powers	S5-13
T. B. Powers	R3-15
C. J. Rice	R2-50
R. E. Raymond (2)	R2-38
D. S. Rewinkel	S7-40
W. E. Ross	\$7- <b>4</b> 0
K. Sathyanarayana	
D. J. Saueressig	H0-34
J. S. Schofield	S8-05
	S7-12
E. B. Schwenk, Jr.	L6-38
N. J. Scott-Proctor	S5-01
J. E. Shapley	B4-46
J. P. Shearer D. H. Shuford	H0-20
E. R. Siciliano	S7-03
J. N. Strode	B4-43
R. R. Thompson	R2-11
A. M. Urnek	R2-12
J. E. Van Beek	S7-40
J. A. Voogd	S2-48
	H6-37
A. B. Webb K. A. White	R1-44
	S5-13
	R1-10
F. A. Zak	R3-01
Central Files	B1-07
200 West Shift Office	T4-00
200 East Shift Office	S5-04
Environmental	
Data Mgmt Center (2)	H6-08
Unified Dose Assessment	
Center (UDAC)	A0-20
Document Processing Center	A3-94
<u>-</u>	